<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

District II

District IV

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170

State of New Mexico

Form C-101 Revised July 18, 2013

Energy Minerals and Natural Resources

Oil Conservation Division

HOBIGAMENDED REPORT

1220 South St. Francis Dr.

AUG 0 9 2013

1220 S. St. Franci Phone: (505) 476					Santa Fe,	, NM 8750	5				
APPLI	CATIO	N FOR	PERMIT TO	O DRILL,	RE-ENTE	R, DEEP	EN, PL	UGBACI	C, OR AD OGRID Num	DA ZONE	
Operator Name and Address VANGRUAD PERMIAN LLC POBOX 1570 281 NORTH NM HIGHWAY 248						258350					
	EUNICE, NM 88231						30-025-37829 API Number				
4. Prop	erty Code 2410				Property Name GRIZZELL B		<u></u>		6. V	Vell No. 8	
				^{7.} Sı	ırface Locatio	on					
UL - Lot H	Section 8	Township 22S	Range 37E	Lot Idn	Feet from 2310	N/S Line North		Feet From 497	E/W Line EAST	County LEA	
		,		8 Propose	ed Bottom Ho	· ·					
UL – Lot H	Section 8	Township 22S	Range 37E	Lot Idn	Feet from 2310	N/S Line NORTH	i i	Feet From 497	E/W Line EAST	County LEA	
					ool Informatio	on	_				
			PE		Name LY GRAYBUF	RG 🖌	•			Pool Code 50350	
				Addition	al Well Infor	mation					
	P O				13. Cable/Rotary R		^{14.} Lease Type PRIVATE		15. Gr	15. Ground Level Elevation 3420 KB	
16. M	lultiple		17. Proposed Depth 3780		18. Formation GRAYBURG			tractor	^{20.} Spud Date		
Depth to Gro	Depth to Ground water 40			Distance from nearest fresh water well			Distance to nearest surface water				
We will b		closed-loop	system in lieu of					rith a steel tank and	haul contents to the	e required disposal	
Туре	Hole	e Size	Casing Size	Casing Weight/ft		Setting Depth		Sacks of Cement		Estimated TOC	
	12	25	8.625	24		2950				·	
	1	17	5.5	17		5320	5320				
			Casin	g/Cement Pr	ogram: Addit	tional Com	ments				
			Casin	g/Cement 11	ogram. Addit	tional Com	incires				
			22.	Proposed Blo	owout Preven	tion Progra	ım				
			orking Pressure	ssure Test Press		t Pressure	re Manufa		anufacturer		
^{23.} I hereby c	ertify that th	ne information	n given above is tr	ue and complete	to the		OH 00	JOERALA			
	tify that I l		ed with 19.15.14.9	(A) NMAC	and/or App	proved By:		NSERVAI	TION DIVIS	ION	
Signature:	May	HER	rd							L. Character	
Printed name	Printed name: GAYN HEARD					Title: Petroicum Engineer					
Title:	Fitie: AGENT					Approved Date:					
	-mail Address: gheard@oilreportsinc.com					Oil Conser			=	Linguis -	
Date:	ate: Phone:				(Conditions of approval: Approval for drilling/workover					

SEP 09 2019

ONLY -- CANNOT produce Downhole Commingled until DHC is approoved in the OCD Santa Fe office.



WORKOVER PROCEDURE

Acidize, Test SA, then add Perforations, Stimulate & Test the Grayburg

Grizzell B #8
Eunice Area
Lea County, New Mexico
7/12/2013

HOBBS OCD

AFE#

AUG 0 9 2013

Well Data:

RECEIVED

RKB - GL: 3430' / 3429'

Surf. Casing: 8-5/8", 24# K-55, set at 871' Prod. Casing: 5-1/2", 17# K-55, set at 4496'

Tbg & Pkr: 2 7/8", 6.5# J-55 EUE, set at unknown

Perforations: San Andres 3,826' – 4,050' (See WBD)

PBTD: 4,451' FC WLM,

BHP: Not certain – well on pump

BHT: 120°F @ TD

Casing Specifications

Depth (ft)	Casing Wt & Grade	Burst	Col	Body Yield	JT Yield	Wall	ID	Drift Dia.	Top Cmt
0 – 1092'	8-5/8, 24#, K-55 ST&C	2,950	1,370	630	381	-	8.097	7.972	Surf.
0 – 4,284'	5-1/2", 17#, K-55	5,320	4,910	273	272	-	4.892	4.767	Surf.

Safety:

Vanguard's policy on safety as employees and contractors is for everyone to go home safely every day. To this end a safety meeting involving all persons on location will be held at the beginning of each day and prior to any significant activity during the course of this operation. It is the responsibility of the Wellsite Supervisor to lead these safety

Grizzell B #8
Acidize and test SA, Perf, Stim & Test Upper Grayburg

<u>meetings</u>, document attendance, note in the daily report, and retain the documentation for the permanent well record.

While there are multiple aspects running a safe operation, one key point that should be made at each safety meeting is the Stop Work Authority (SWA) policy. The SWA Policy grants all persons on a Vanguard site, facility, location, or property the **Right, Obligation, Authority, and Responsibility** to stop any work or action that are unsafe to personnel, equipment, or that if continued may damage the environment. This is a key component of our safety policy and must be conveyed to all personnel on location.

Scope of Operations:

AUG 0 9 2013

Acidize the San Andres and test. Then, isolate the current San Andres interval and 30 new perforations to the Grayburg Formation, fracture stimulate and test the Grayburg. Comingle if possible.

Contact Information:

Name	Title	Office	Cell	
Bryan Kindred	Workover Foreman		575-602-1788	
Mike Jones	Production Foreman	575-396-0812	575-390-4611	
Newt Painter	Production Superintendent	432-362-2209	432-438-3872	
Randall Hicks	Senior Operations Engineer	832-377-2207	713-252-1626	
Frank Lemkowitz	Operations Manager	832-377-2237	713-560-3122	

Procedure:

- 1. MIRU completion rig and test anchors.
- 2. Unseat pump and POOH w/ rods and pump.
- 3. ND WH and NU BOP. Kill well with 2% KCL water, if necessary. Release TAC and POOH w/ tubing.
- 4. PU, strap and TIH with 4-3/4" bit, 5-1/2" casing scrapper & 2-7/8" tubing. Clean out hole to PBTD (4451') until clean returns, POOH.
- 5. PU a 5-1/2" Arrowset I packer and RIH to \sim 3780'. Load tubing with 2 % KCl and set packer. Test csg to 3700 psi.
- 6. MIRU pump truck and test lines to 3500 psi.
- 7. Pump 4000 gals 15% NEFE acid with 125 ball sealers.
 - a. Pump 500 gal then drop 125 balls over next 3000 gals.
 - b. Pump last 500 gals and flush to 3874'.
 - c. Record ISIP, 5 min, 10 min and 30 min.
- 8. RU swabber and swab well in to test acid job. Recover load and report fluid/gas entry.
- 9. Load hole and release packer, POOH and lay out tubing.
- 10. MI wireline w/ packoff. RIH w/ CBP and GR/CCL & correlate to the Halliburton Spectral Density/Dual-spaced Neutron/GR log dated 6/08/2006.

Grizzell B #8

Acidize and test SA, Perf, Stim & Test Upper Grayburg

- 11. Set CBP @ ~3800'.
- 12. MU 3-1/8" slick casing guns set at 3 spf, 120° phasing (0.40" hole, 21" penetration).
- 13. Perforate as follows:
 - a. 3656' 3660' (4', 12 shots)
 - b. 3774' 3780' (6'. 18 shots) (30 total shots)
- 14. RD wireline.
- 15. RDMO completion rig.
- 16. Call out 4-500 bbl tanks & fill with 2% KCl water. Install frac valve in preparation for frac job.
- 17. RU frac Co. and test lines & pump as per frac schedule.
- 18. Monitor ISIP, 10 min, 15 min. Flowback until well dies.

HOBBS OCD

- 19. MIRU completion rig.
- 20. RIH w/ 5-1/2" TAC, SN and 2-7/8" tubing. Set SN at 3600'.

AUG 0 9 2013

RECEIVED

- 21. RIH w/ rods and pump.
- 22. RD & MO.
- 23. Turn well on to production.
- 24. Test well to get comingle permit.
- 25. See additional procedure to comingle zones, if needed.

Note: It is the responsibility of Wellsite Supervisor to enter all daily activity reports and costs into WellView on a timely basis.

Originator:	
	Randall Hicks
	Senior Operations Engineer
Approved:	
	Truck Law bowies
	Frank Lemkowitz Operations Manager



Grizzell B #8

Eunice SA SW Field - 30-025-37829

Lea County, New Mexico

INTERIM COMPLETION - 7/2013

Depth

unknown

Size

2 7/8"

6.5#

TOC @	surf
330 sxs	

8 5/8"csg @ 871

CASING PROGRAM								
<u>Depth</u>	<u>Size</u>	Weight	<u>Grade</u>	<u>I.D.</u>	<u>Collapse</u>	Burst		
871	8 5/8"	24#	K-55	8.097	1,370	2,950		
4496	5 1/2"	17#	K-55	4.892	4,910	5,320		

PRODUCTION TUBING Weight Grade Threads

J-55

HOBBS OCD

EUE

AUG 0 9 2013

RECEIVED

TOC @ surf 850 sxs



3,656' - 3,660' (3 spf, 12 holes) 3,774' - 3,780' (3 spf, 18 holes)

Composite BP @ 3800'

San Andres Perforations 182 holes: 3,826' - 3,864' (2 spf, 76 holes)

3,902' - 3,956' (1 spf, 54 holes) 3,992' - 4,050' (1 spf, 52 holes)

PBTD = 4,451' FC

5 1/2"csg @ 4496

Note: This schematic is not to scale. For display purposes only.