

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary-Designate

Brett F. Woods, Ph.D.  
Deputy Cabinet Secretary

Jami Bailey, Division Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Underground Injection Control Program*

*"Protecting Our Underground Sources of Drinking Water"*

19-Sep-13

CHAPARRAL ENERGY LLC  
701 CEDAR LAKE BLVD.  
OKLAHOMA CITY OK 73114-

**HOBBS OCD**  
**SEP 23 2013**  
**RECEIVED**

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE**  
**Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

**MECHANICAL INTEGRITY TEST DETAIL SECTION**

<b>WEST DOLLARHIDE QUEEN SAND UNIT No.033</b>			<b>30-025-12285-00-00</b>
Active Injection - (All Types)			F-31-24S-38E
Test Date:	9/17/2013	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 12/21/2013
Test Type:	Bradenhead Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT:	WELL FAILED BHT (RULE 19.15.26.11). WELL SHOULD BE SHUT IN AND DISCONNECTED IMMEDIATELY. CONTINUOUS FLOW OUT PRODUCTION CASING BH VALVE.		
<b>WEST DOLLARHIDE QUEEN SAND UNIT No.108</b>			<b>30-025-30196-00-00</b>
Active Injection - (All Types)			E-29-24S-38E
Test Date:	9/17/2013	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 12/23/2013
Test Type:	Bradenhead Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT:	WELL FAILED BHT (RULE 19.15.26.11). WELL SHOULD BE SHUT IN AND DISCONNECTED IMMEDIATELY. CONTINUOUS FLOW OUT PRODUCTION CASING BH VALVE.		

**SEP 23 2013**

**WEST DOLLARHIDE QUEEN SAND UNIT No.113****30-025-30231-00-00**

Active Injection - (All Types)

C-31-24S-38E

Test Date:	9/17/2013	Permitted Injection PSI:	Actual PSI:		
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	12/21/2013
Test Type:	Bradenhead Test	FAIL TYPE:	Other Internal Failure	FAIL CAUSE:	
Comments on MIT:	WELL FAILED BHT (RULE 19.15.26.11). WELL SHOULD BE SHUT IN AND DISCONNECTED IMMEDIATELY. CONTINUOUS FLOW OUT PRODUCTION CASING BH VALVE.				

**WEST DOLLARHIDE QUEEN SAND UNIT No.135****30-025-30295-00-00**

Expired TA Injection - (All Types)

F-32-24S-38E

Test Date:	9/17/2013	Permitted Injection PSI:	Actual PSI:		
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	12/23/2013
Test Type:	Bradenhead Test	FAIL TYPE:	Other Internal Failure	FAIL CAUSE:	
Comments on MIT:	WELL FAILED BHT (RULE 19.15.26.11). WELL SHOULD BE SHUT IN AND DISCONNECTED IMMEDIATELY. CONTINUOUS FLOW OUT PRODUCTION CASING BH VALVE.				

**WEST DOLLARHIDE QUEEN SAND UNIT No.148****30-025-30305-00-00**

Active Injection - (All Types)

M-32-24S-38E

Test Date:	9/17/2013	Permitted Injection PSI:	Actual PSI:		
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	12/21/2013
Test Type:	Bradenhead Test	FAIL TYPE:	Other Internal Failure	FAIL CAUSE:	
Comments on MIT:	WELL FAILED BHT (RULE 19.15.26.11). WELL SHOULD BE SHUT IN AND DISCONNECTED IMMEDIATELY. PRESSURE ON PRODUCTION CASING/TUBING ANNULUS, WOULD NOT BLEED OFF.				

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.


Sincerely,

  
**COMPLIANCE OFFICER**

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



HASLER	015H14 150977	US POSTAGE
	<b>\$0.46</b>	
	09/19/13	
	Mailed From 88240	

CHAPARRAL ENERGY LLC  
701 CEDAR LAKE BLVD.  
OKLAHOMA CITY, OK 73114