2 2014 FILE IN TRIPLICATE	State of N Energy, Minerals and Na	ew Mexico tural Resources Depart		Form C-103 Revised 5-27-2004
FILE IN TRIPLICATE	OIL CONSERVA	TION DIVISION		Revised 3-27-2004
DISTRICT	1220 South St. Francis Dr.		WELL API NO.	/
1625 Auron Mar Dr. , Hobbs, NM 88240	Santa Fe,	NM 87505	30-025-05505	
1301 W. Grand Ave, Artesia, NM 88210			5. Indicate Type of Lease STATE X	- FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410	CEAL WE DEPADER ON THE		21	
(DO NOT USE THIS FORM FOR PRO	CES AND REPORTS ON WEI		7. Lease Name or Unit Agreeme North Hobbs (G/SA) Unit	int ivame
DIFFERENT RESERVOIR. USE "API	LICATION FOR PERMIT" (Form C-1)	01) for such proposals.)	Section 25	G
I. Type of Well:			8. Well No. 321	/
Oil Well X 2. Name of Operator	Gas Well Other		9. OGRID No. 157984	
Occidental Permian Ltd.	······			
3. Address of Operator HCR Box 90 Denver City, TX 7	/9323		10. Pool name or Wildcat	Hobbs (G/SA)
4. Well Location	<u></u>			/
Unit Letter <u>G</u> : 1980	Feet From The North	1980	Feet From The East	Line 🗸
Section 25	Township 18-S	Range	37-Е ММРМ	Lea County
	11. Elevation (Show whether DF, RK 3658' GL	B, RT GR, etc.)		
12. Check NOTICE OF INTE PERFORM REMEDIAL WORK	Appropriate Box to Indicate Na NTION TO: PLUG AND ABANDON CHANGE PLANS		UBSEQUENT REPORT OF	
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oper proposed work) SEE RULE 1103. F I. RUPU & RU.	Multiple Completion	CASING TEST AND CE OTHER: <u>Return to</u> stails, and give pertinent of	MENT JOB production lates, including estimated date of st	arting any
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oper proposed work) SEE RULE 1103. F	Multiple Completion	CASING TEST AND CE OTHER: <u>Return to</u> tails, and give pertinent of relibore diagram of propo RD wire line.	MENT JOB production lates, including estimated date of so sed completion or recompletion. 4095' & 4132'. POOH w/bit & d	arting any rill collars. 1ES.
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oper proposed work) SEE RUPU & RU. 1. RUPU & RU. 2. ND BOP/NU wellhead. 3. RU wire line and run casing in 4. RIH w/RBP set @493°. Dun 5. NU wellhead/ND BOP 6. RDPU & RU to do wellhead of 7. RUPU & RU to do wellhead of 7. RUPU & RU to do wellhead of 7. RUPU & RU. 12/30/2010 8. ND wellhead/NU BOP. 9. RIH and wash sand off RPB. 10. RIH w/bit & drill collars. Tag 11. RIH w/CICR set @3886°. RU	Multiple Completion	CASING TEST AND CE OTHER: <u>Return to</u> tails, and give pertinent of rellbore diagram of propo RD wire line. RD wire line.	MENT JOB production lates, including estimated date of st sed completion or recompletion. 4095' & 4132'. POOH w/bit & d w/2% Cal & 2 Super CBL. RD l attached sheet for additional data	arting any rill collars. tES. ***
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oper proposed work) SEE RUPU & RU. 10. DBOP/NU wellhead. 3. RU wire line and run casing it 4. RIH w/RBP set @493'. Dun 5. NU wellhead/ND BOP 6. RDPU & RU to do wellhead of RDPU & RU to do wellhead of RDPU & RU to do wellhead of RUPU & RU to do wellhead of RUPU & RU hand wash sand off RPB. 10. RIH w/bit & drill collars. Tag 11. RIH w/CICR set @3886'. RU	Multiple Completion	CASING TEST AND CE OTHER: <u>Return to</u> tails, and give pertinent of rellbore diagram of propo RD wire line. RD wire line.	MENT JOB production Jates, including estimated date of so sed completion or recompletion. 4095' & 4132'. POOH w/bit & d w/2% Cal & .2 Super CBL. RD I attached sheet for additional data rtify that any pit or below-grade tank h	arting any rill collars. tES. ***
PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oper proposed worky SEE RUPU & RU. 2. ND BOP/NU wellhead. 3. RU wire line and run casing it 4. RIH w/RBP set @493'. Dun 5. NU wellhead/ND BOP 6. RDPU & RU to do wellhead of 7. RUPU & RU. 12/30/2010 8. ND wellhead/ND BOP. 9. RIH and wash sand off RPB. 10. RIH w/bit & drill collars. Tag 11. RIH w/CICR set @3886'. RU	Multiple Completion	CASING TEST AND CE OTHER: <u>Return to</u> tails, and give pertinent of relibore diagram of propo RD wire line. RD wire line. ent and CIBPs at 3900', Premium Plus Cement n ****see ledge and belief. I further ce or an (attached) altern plan	MENT JOB production Jates, including estimated date of so sed completion or recompletion. 4095' & 4132'. POOH w/bit & d w/2% Cal & .2 Super CBL. RD I attached sheet for additional data rtify that any pit or below-grade tank h	rill collars. HES. ***

NHU 25-321 API 30-025-05505

- 12. RIH w/packer set @3730'. Tested squeeze. Found leak 200' from surface.
- 13. RU HES & squeeze leak with 200 sacks of cement. RD HES.
- 14. RIH w/bit & drill collars. Drill on cement from 26' to 229'. Fell out of cement. Ran bit to 362'. Circulate clean. Tested squeeze. Tested OK. POOH w/bit & drill collars.
- 15. RIH w/bit and drill collars. Tag top of liner @3803'. Drill cement from 3855-4130'. Drill new formation from 4295-4322'. POOH w/bit & drill collars.
- 16. Run CNL/CCL/GR log from TD to 3355'.
- 17. RU wire line & perforate casing @4208-4215', 4224-4230', 4252-4264'. RD wire line.
- RIH w/treating packer set @4151'. RU HES & pump rock salt block acid job w/2000 gal of 15% NEFE HCL acid and 750# of rock salt block. RD HES. RU pump truck & pump scale squeeze w/100 bbl fresh water and 60 bbl 6490 chemical. Flush w/100 bbl 10# brine. RD pump truck. POOH w/packer.
- 19. RIH w/ESP equipment on 113 jts of 2-3/8" tubing. Intake set @3752'.
- 20. ND BOP/NU wellhead.
- 21. RDPU & RU. Clean location and return well to production.

C-103 filed per Sylvia Dickey's letter dated 07/17/2013

RUPU 12/08/2010 RDPU 02/19/2011