Submit 1 Copy To Appropriate District	Form C-103				
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 HOBBS CCCP, Minerals and Natural Resources District II – (575) 748-1283			Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240	BBS OCE		WELL API NO		
<u>District II</u> - (575) 748-1283	OIL CONSERVATION	IDIVISION	30-025-41045		
811 S. First St., Artesia, NM 88210	5. Indicate Type of Lease				
District III – (505) 334-6178	OIL CONSERVATION 6 2014 220 South St. Fran	ncis Dr.	STATE 7	FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	6. State Oil & Gas Lease No.				
87505	RECEIVED				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Monument G/SA Unit (302708)		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					
	Gas Well 🔲 Other		8. Well Number 392		
2. Name of Operator			9. OGRID Number	, 	
Apache Corporation			873		
3. Address of Operator			10. Pool name or Wil	dcat	
303 Veterans Airpark Lane, Suite 30	00 Midland, TX 79705		Eunice Monument; G-S	SA (23000)	
4. Well Location			L		
	feet from the South	line and 2420	feet from the	East line	
Section 30	Township 19S Ra	ange 37E	NMPM Co	ounty Lea	
	11. Elevation <i>(Show whether DR</i> 3619' GL	, RKB, RT, GR, etc.)			
12. Check A	ppropriate Box to Indicate N	lature of Notice, I	Report or Other Dat	a	
NOTICE OF IN	TENTION TO:	SUB:	SEQUENT REPO	RT OF:	
		REMEDIAL WORK			

	PLUG AND ABANDON			ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.	PANDA [
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB		
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM					
OTHER:			OTHER:	[
13. Describe proposed or comp	leted operations. (Clearly	state all p	pertinent details, and give pertinent da	tes, including estimated	date

of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache would like to Sonic hammer the lower Grayburg, perforate & acidize the upper Grayburg per the attached procedure.

Spud Date:	05/19/2013	Rig Release Date:	05/22/2013	
I hereby certi	fy that the information above is true a	nd complete to the best o	f my knowledge and belief.	
SIGNATURI		TITLE Regulatory	Analyst II	DATE_05/02/2014
Type or print For State Us APPROVED Conditions of	<u>e Ouly</u> Maluz Kin	b man address	atima.Vasquez@apachecorp.com	PHONE: $(432) 818-1015$ DATE $5/7/2014$
				MAY 07 2014

NMGSAU #392 API # 30-025-41045 Sec 30, T19S, R37E Elevation: 3630' KB, 3619' GL TD: 4,031' PBTD: 3,991' Casing Record: 8-5/8" 24# J-55@ 1,248' w/ 356 sxs 5-1/2" 17# J-55@ 4,031' w/ 679 sxs

Perfs: Grayburg: 3792-3806; 3825-35; 3842-47; 3877-81; 3889-95 w/ 2 jspf (78 holes)

Objective: Sonic hammer the lower Grayburg, perforate and acidize the upper Grayburg, RTP.

AFE: 11-14-1643

- 1. MIRU unit. Kill well as necessary. Unseat pump. POOH w/ rods and pump.
- 2. ND WH. NU BOP. Release TAC. POOH w/ tubing.
- 3. PU and RIH w/ bit, bit sub, and drill collars on 2-7/8" production tubing to PBTD @ ~4,031'.
- 4. PU and RIH w/ sonic hammer on 2-7/8" production tubing to bottom perf @ 3,895'.
- 5. MIRU acid services. Acidize down 2-7/8" J-55 tubing w/ 2,000 gals of 15% NEFE HCL w/ additives through the sonic hammer moving across perforations from 3,792'-3,895'. Drop ball and shear tool.
- 6. RU swab equipment and recover load and swab test perfs for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- 7. Kill well if necessary. POOH w/ sonic hammer and 2-7/8" tubing.
- MIRU WL. RIH w/ perforator and perforate the UPR Grayburg at 3615-24; 3654-64; 3712-17; 3732-46 w/ 2 jspf 120° phasing (76 holes). POOH w/ perf guns. Correlate to Weatherford Compensated Neutron Gamma Ray/CCL Log dated 5/30/2013. RDMO WL.
- 9. PU and RIH w/ RBP-PKR straddle assembly with ball catcher on WS. Set RBP and ball catcher at \pm 3,780. TOOH and set PKR at 3,775 and test RBP to 1000 psi. Release PKR and TOOH and set PKR above new perforations at \pm 3565'. Test backside to 500 psi.
- 10. MIRU acid services. Acidize the Grayburg (3,615-3,746) down the tubing with 3000 gallons 15% NEFE w/ additives using 150 ball sealers to divert evenly spaced throughout the job as a max rate but do not exceed 4,000 psi surface treating pressure. Displace to bottom perf with 30 bbls of flush. Release PKR and knock balls off. TOOH and set PKR at 3,565'.
- 11. RU swab equipment and recover load and swab test perfs for fluid entry and oil cut. Report results to Midland. RD swab equipment.
- *12.* Kill well if necessary. Release PKR and TIH to RBP and ball catcher. Latch and release RBP. POOH w/ RBP-PKR straddle assembly.
- 13. PU and RIH w/ production tbg and rods w/ new pump as per the Monument office specification
- 14. RDMOPU. Return well to production and place into test for 10 days.



