State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 HOBBS ICONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe. NM 87505	WELL API NO. 30-025-38125
DISTRICT I 1625 N. French Dr., Hobbs, NM 882401220 South St. Francis Dr. Santa Fe, NM 87505DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210MAY 202014	5. Indicate Type of Lease STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	North Hobbs (G/SA) Unit Section 19
1. Typetof Well: Oil Well X Gas Well Other	8. Well No. 638
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984 🖌
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323 4. Well Location	L
	t From The East Line
Section 19 Township 18-S Range 38-J	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3676' KB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or 0	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
OTHER: 2 OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	
proposed work one more than the second and the second and the proposed	emprenen er recemprenen.
1. RUPU & RU.	
2. ND wellhead/NU BOP.	
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. 	
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 sacks 	
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 sac into formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro 	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI.
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 sac into formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RD power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI.
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 sac into formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RD power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. 	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI.
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 satinto formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. 	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. 0'. POOH w/bit & drill collars. hed sheet for additional information***
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 sat into formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. 	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. 0'. POOH w/bit & drill collars. hed sheet for additional information*** that any pit or below-grade tank has been/will be
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 sac into formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. 	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. 0'. POOH w/bit & drill collars. hed sheet for additional information*** that any pit or below-grade tank has been/will be
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 satinto formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. ***see attace I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. D'. POOH w/bit & drill collars. hed sheet for additional information*** that any pit or below-grade tank has been/will be e OCD-approved
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 satisfies for formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. 0'. POOH w/bit & drill collars. hed sheet for additional information*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 05/16/2014
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 satinto formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. D'. POOH w/bit & drill collars. hed sheet for additional information*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 05/16/2014
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 sac into formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RD power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy/A. Jehnson Kendy A. Jehnson E-mail address: mendy_johnson@oxy.com	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. 0'. POOH w/bit & drill collars. hed sheet for additional information*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 05/16/2014
 ND wellhead/NU BOP. POOH and lay down ESP equipment. RIH w/bit. Tag @4030'. POOH w/bit. RU wire line & set CIBP @4165'. Set CICR @4065'. RD wire line. RU cement truck and squeeze perfs from 4110-4155' w/300 sacks of 50-50 POZ and 10 satinto formation. Sting out of retainer and reverse out 23.5 bbl of cement. Circulate w/fresh RIH w/bit & drill collars. Tag @4065'. RU power swivel. Drill out CICR and cement fro Held OK. Drill out CIBP @4165'. RD power swivel. Continue in hole and tag TD @444 RU wire line & perforate well @4302-20', 4323-39'. RD wire line. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy_johnson@oxy.com For State Use Onty APPROVED BY TITLE Ditted	water. RD cement truck. n 4065' to 4165'. Tested squeeze to 1000 PSI. D'. POOH w/bit & drill collars. hed sheet for additional information*** that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 05/16/2014

NHU 19-638 API 30-025-38125

9. RIH w/treating packer set @4000'. RU Warrior Energy and pumped 3500 gal of 15% NEFE acid in 2 stages. (2200 in 1st stage/1300 in 2nd stage). Flush w/40 bbl fresh water. RD Warrior Energy. RU pump truck and pump scale squeeze w/100 bbl fresh water and 100 gal of 6490 chemical. Flush w/200 bbl fresh water. RD pump truck. POOH w/packer.

.

- 10. RIH w/ESP equipment set on 124 jts of 2-7/8" tubing. Intake set @4021'.
- 11. ND BOP/NU wellhead.
- 12. RDPU & RU. Clean location and return well to production.

. RUPU 03/19/2014 RDPU 03/28/2014

Re-filed to show new perforations shot in well. 5/19/2014