Submit I Copy To Appropriate District State of New M		Form C-103
District I – (575) 393-6161 Energy, Minerals and Nat 1625 N. French Dr., Hobbs, NM 88240	ural Resources	Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION	N DIVISION	30-005-01098
<u>District III</u> – (505) 334-6178 1220 South St. Fra		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		303737
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) ECSNCH		WEST CAP QUEEN SAND UNIT
FRUFUSALS.		8. Well Number 11
1. Type of Well: Oil Well Gas Well Other INJECTION 2014 2. Name of Operator		9. OGRID Number
LEUACT RESERVES OF ERATING LI		240974
3. Address of Operator PO BOX 10848, MIDLAND, TX 79702	RECEIVED	10. Pool name or Wildcat CAPROCK; QUEEN
4. Well Location		
Unit Letter P : 660 feet from the SOUTH line and 660 feet from the EAST line		
Section <u>17</u> Township 14S Range 31E NMPM County CHAVES		
11. Elevation (Show whether DF	R, RKB, RT, GR, etc.,	
4140' GL	 	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
SEE ATTACHED P&A PROCEDURE ALONG WITH CURRENT & PROPOSED WELLBORE DIAGRAMS		
The Oil Conservation Division		
MUST BE NOTIFIED 24 Hours		
Prior to the beginning of operations		
		· · · · · · · · · · · · · · · · · · ·
Spud Date: Rig Release D	Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE LAUG MA	REGULATORY T	ECHDATE_08/06/2014
Type or print name <u>LAURA PINA</u> E-mail address: _	lpina@legacylp.cc	bm PHONE: _432-689-5200
For State Use Only		
APPROVED BY: Y LAWY DOWN TITLE Dist Supervisor Date 8/11/2014		
Conditions of Approval (if any):		
~		AUG 1 1 2014
en e	· .	$\mathcal{V}\mathcal{V}$

WCQSU #11

P&A PROCEDURE:

1.POOH & LD injection equipment.

2.Make a bit run on workstring to 2830' and POOH standing back. 3.RIH w/BP&PS on workstring to 2830' and spot 50 sx. PU, WOC a minimum of 4 hours and tag TOC at/above 2550'. Circulate minimum 9.5 ppg salt mud to 1925' and pressure test casing to 300 psi. POOH. 4.RIH w/packer on workstring, set and test. RU WL and perf(4) at 1925'. RD WL. Squeeze the perfs at 1925' w/minimum 40 sx. Leave well shut in w/squeeze

pressure a minimum of 3 hours before POOH.

5.RBIH w/BP&PS and tag TOC at/above 1825'. Circulate minimum 9.5 ppg salt mud to surface and POOH.

6.RU WL and perf (4) at 1150' and 260'. RD WL. RIH w/packer and squeeze perfs at 1150' w/ minimum 40 sx. POOH w/pkr. RBIH w/BP&PS and tag TOC at/above 1050'. 7.PU E-O-T to 310' and establish circulation on 5-1/2"-by-8-5/8" annulus. Fill 5-1/2" and 5-1/2"-by-8-5/8" to surface w/minimum 100 sx.

8.POOH LD WS, top off casing, and RD. Cut off wellheads, set P&A marker, clean and reclaim location.

All plugs are Class C w/2% CaCl2. Minimum 9.5 ppg salt mud between all plugs.



