
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV.	ATION DIVISIO	N	
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-38114	
DISTRICT II	,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 18	
1. Type of Well: Oil Well	Gas Well Other In	jector HOBBS OC	8. Well No. 518	,
Name of Operator Occidental Permian Ltd.	/	AUG 08 20	9. OGRID No. 157984	
3. Address of Operator		HOO 4 4 2 2 2	10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	K 79323			` ′
4. Well Location		RECEIVED		
Unit Letter M : 275 Feet From The South Line and 1030 Feet From The West Line				
Section 18	Township 18-S	Range	38-E NMPM	Lea County
	11. Elevation (Show whether DF, RF 3642' KB	KB, RT GR, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDOI				BANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB				
OTHER:				
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. RU wire line & set blanking plug @4150'. ND wellhead/NU BOP. POOH w/tubing & on/off tool. RU wire line & fish blanking plug. Unset and POOH w/injection packers. RIH w/bit & drill collars. Tag @4456'. NU power swivel and stripper head. Drill on cement from 4456-4466'. Circ clean. Drill on new formation from 4470-4484'. Circ clean. ND power swivel & stripper head. POOH w/bit & drill collars. RU wire line and run CNL from 4484' (TD) to 3850'. RD wire line. RU wire line and perforate casing @4328-33', 4345-61', 4363-74', 4378-85', 4396-4400', 4405-16', 4423-27', 4433-38', 4446-58'. RD 				
see attached sheet for additional data				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or				
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan				
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280				
For State Use Only				
$VV_{\alpha}V_{\alpha}V_{\alpha}V_{\alpha}V_{\alpha}V_{\alpha}V_{\alpha}V_{\alpha$				
CONDITIONS OF APPROVAL IF A Y:				

AUG 1 1 2014

Work Plan Report for Well:NHSAU 518-18



Survey Viewer



NHU 18-518 API #30-025-38114

- 10. RIH w/RBP set @4390' & packer set @4193'. RU Rising Star and pump 15000 gal of 15% NEFE acid into perfs between 4330-4390'. Release RPB and set packer @4390'. Pump 1800 gal of 15% NEFE into perfs. RD Rising Star.
- 11. POOH w/RBP and packer.
- 12. RIH w/dual injection packers set on 127 jts of 2-7/8" Hydrotested Duoline tubing. Arrowset 1-X packer set @4162' KTC Hydraulic packer set @4330'.
- 13. ND BOP/NU wellhead.
- 14. Test casing to 680 PSI for 30 minutes and chart for the NMOCD. Mark Whitaker w/NMOCD on site for test.
- 15. RDPU & RU. Clean location and return well to injection.

RUPU 04/07/2014 RDPU 04/17/2014

Had to rig back up on well to move packers that were set at wrong depths.

- 1. RUPU & RU.
- 2. ND wellhead/NU BOP.
- 3. Unseat and POOH w/packers.
- 4. Run back in hole with dual injection packers set on 130 jts of 2-7/8" Duoline tubing. Arrowset 1-X packer set @4153', KTC Hydraulic packer set @4286'.
- 5. ND BOP/NU wellhead.
- 6. Test casing to 610 PSI for 30 minutes and chart for the NMOCD.
- 7. RDPU & RU. Clean location and return well to injection.

RUPU 05/07/2014 RDPU 05/13/2014

Had to rig back up on well due to pressure loss.

- 1. RUPU & RU.
- 2. ND wellhead/NU BOP.
- 3. POOH w/tubing. Did not find bad seal or joint. Run back in hole w/tubing. Did not move packers.
- 4. RU wire line & run gauge ring down to 4472' with no problem. RD wire line.
- 5. ND BOP/NU wellhead.
- 6. Tested casing to 590 PSI for 30 minutes and charted for the NMOCD.
- 7. RDPU & RU. Clean location and return well to injection.

RUPU 05/21/2014 RDPU 05/22/2014



