Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103	
Office <u>District 1</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District 11</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-20787	
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE   FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	3,		o. State on & Gas Lease No.	
	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreement Name	e
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.)	ICATION FOR PERMIT" (FORM C-10	T) FOR SUCH	Loveless LQ State	
1. Type of Well: Oil Well	Gas Well   Other	HOBBS OCD  ANG 28 2014	8. Well Number 2	
2. Name of Operator		HOPE	9. OGRID Number	
Cross Border Resources, Inc.		8 5/1/2	286614	
3. Address of Operator		NUGE	10. Pool name or Wildcat	
2515 McKinney Ave, Suite 900, I	Dallas, TX 75201	T. SIED	Tomahawk San Andres	
4. Well Location		RECEIVED		
Unit Letter F:	1980 feet from the North	line and <u>198</u>	0feet from theWestline	
Section 36	Township 7S	Range 31E	NMPM Chaves County	
	11. Elevation (Show whether	DR, RKB, RT, GR, etc.		
12. Check	Appropriate Box to Indicat	e Nature of Notice,	Report or Other Data	
	• • •		•	
	NTENTION TO:		SEQUENT REPORT OF:	_
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			<del>_</del>	
TEMPORARILY ABANDON				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM	]	7	,	_
OTHER: Perforate P1, Acidize		OTHER:		<u> </u>
			d give pertinent dates, including estimated	date
proposed completion or re		VIAC. For Multiple Co	mpletions: Attach wellbore diagram of	
		o's RIH 3-3/4"w/ bit	and 4 drill collars. PU and RIH w/ newly	
			CIBP set at 4077'. Clean out hole to PBTD	of
4251'.	r 3-33 EOE production tuomig.	on out 40 cint and a	CIBI Set at 4077. Cican out note to 1 B 1 B	01
2. MIRU wireline unit. RIH w/ 3-1/8" casing guns and perforate the P-1 San Andres as follows: 3996'-4010' and 4030'-4038'				
(1 spf 90 degree phasing 22 holes total.) POOH with wireline. RD wireline unit.				
3. RIH w/ 4-1/2" treating packer and RBP. Set RBP at 4048' (Note: Only 20' between P1 and P2 perfs). Set packer at 3950'.				
Attempt to load hole to make sure the packer has a seat in the casing. Do not put more than 300 psig on the backside.				
Acidize P-1 perforations (3996'-4010' and 4030'-38') with 2500 gallons 20% NEFE HCL. Drop 45 ball sealers. Do not				
exceed 2500 psig or 2.5 BPM. Let acid sit for one hour. Be prepared for acid to break around down to the P2 perforations.				
	determine fluid rates and oil cut.	.0	C	101
			rforations with 6,000 gallons 20% NEFE H	
	r acid then drop 1000# rocks sait EFE HCl acid. Flush perforations		water. Repeat the process till the final stag	ge is
			Ill until well cleans up. Release packer and	
RBP and POOH.	water to react for two flours before	ic swadding. Swad we	if until well cleans up. Release packer and	
	equipment. Visit with Dallas of	fice on placement of SN	I. Plan on running a 76 rod string with 1.5'	,,
	SU. Return well to production.	noo on placement of or		
	** PLEASE SEE ATTACHE	ED WELL BORE DIAGR	AM **	
Spud Date:	Rig Releas	e Date:		
I hereby certify that the information	n above is true and complete to t	he best of my knowleds	ge and belief.	
• •	•			
SIGNATURE Clan To	Behall TITLE	Chairman	DATE 8/25/14	
Type or print name Alan Barksda			inresources.com PHONE: 214-871-0400	
For State Use Only		Petroleum Engineer	1 128/28/04	r
APPROVED BY:	TITLE '		DATE OUT OF T	<del></del>
Conditions of Approval (if any):			AUG 2 9 2014	