Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103 May 27, 2004
<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Reso	WELL API NO. 30-025-31399
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISI	ION
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	5. Indicate Type of Lease
District IV	Santa Fe, NM 87505	STATE FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.
	CES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK T	7. Lease Name or Unit Agreement Name State BTA
DIFFERENT RESERVOIR. USE "APPLIC/ PROPOSALS.)	ATION FOR PERMIT" (FORM C-101)	CD 8. Well Number 3
1. Type of Well: Oil Well x Ga		····· /
2. Name of Operator Paladin Energ	y Corp SEP 2 5 2	2014 9. OGRID Number
3. Address of Operator 10290 Monr	oe Dr., Suite 301	10. Pool name or Wildcat
Dallas, Texas 75229	RECEIVE	D Bagley Siluro-Devonian
4. Well Location		
Unit Letter <u>G</u> : Section 2	<u>1830</u> feet from the <u>North</u> line an Township 12S Range	d <u>1980</u> feet from the <u>East</u> line 33E NMPM Lea County
	11. Elevation (Show whether DR, RKB, RT	
	4237' DR	
12 Check At	ppropriate Box to Indicate Nature of	Notice Report or Other Data
		-PERMITTING
		-PERMITTING &A NR P&A R
		TTOP&A(PM) COMP
PULL OR ALTER CASING		SNG CHG Loc
OTHER:		A RBDMS CHART
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. EST. INJ RATE. SET PACKER @ 6700. NOTIFY OCD.		
 MIRU, Collapsed or parted casing at approx 6,920'. GIH with 2-7/8" tubing to 6700' (+,-). Pump 1st cement plug (200') from about 7,000' to 6,800' with 50 sacks of class H cement, POOH with tubing, WOC. Tag cement plug, <i>DR GREATER IF WELL CONDITION WILL ALLOW</i>. GBIH with tubing and set 2nd 100' cement plug from 5,600 to 5,500', POOH with tubing, WOC. 		
 3.) Cut and pull 5-1/2" casing at 4,150' (+,-) or deepest free point. GIH w/ 2-7/8" tubing and set 3rd 100' cement stub plug from 4,200' to 4,100' with 25 sacks cement. WOC. Tag plug at 4,100'. 4.) Pull up with workstring, EOT at 1,600', pump 50 sks class H cement. Spot 4th plug from 1,700' to 1,600'. 		
WOC. Tag plug.		378 ' 278' ent. Spot 5 th plug from 350' to 250'. WOC.
5.) Pull up with workstring,EO Tag plug. Spot 6 th surface p	T at 250', pump 50 sks class H ceme plug from 0 to 60'. Backfill and clear	ent. Spot 5" plug from 350' to 250'. WOC.
Place P&A marker and move of	flocation. PUMP M.L.F	BETWEEN ALL PLUGS.
I hereby certify that the information al grade tank has been/will be constructed or cl	pove is true and complete to the best of my l osed according to NMOCD guidelines , a general	knowledge and belief. I further certify that any pit or below- l permit 🛄 or an (attached) alternative OCD-approved plan 🗍.
SIGNATURE_Com	TITLE VP Expl	loration & ProductionDATE_9/23/2014
Type or print name	E-mail address:	Telephone No.
For State Use Only	No 40 Dist	Supervisor DATE 9/25/2014
APPROVED BY: Conditions of Approval (if any):	The Oil Conservation Divis	
y		
MUST BE NOTIFIED 24 Hours		
	Prior to the beginning of ope	SEP 2 5 2014

•



