
Submit 1 Copy To Appropriate District Office	State of Nev		Form C-103 Revised July 18, 2013	
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 Diegon H. (575) 748-1283		WELL API NO.		
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210	S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-28139 5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Santa Fe, N		STATE X FEE	
<u>District IV</u> = (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa i e, iv	VI 67303	6. State Oil & Gas Lease No.	
87505 SUNDRY NOT	ICES AND REPORTS ON WI	ELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLIP PROPOSALS.)	SALS TO DRILL OR TO DEEPEN (CATION FOR PERMIT" (FORM C-1	OR PLUG BACK TO A	Baum State	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	· /	8. Well Number 2	
Name of Operator State of New Mexico former	ly Canyon E&P Company	APR 2 3 2015	9. OGRID Number	
3. Address of Operator	y carry critical company		10. Pool name or Wildcat	
	obs, NM 88240	RECEIVED	Jalmat-T-Y-SR	
4. Well Location Unit Letter L: 1980 feet from the South line and 660 feet from the West line				
Section 8	Township 14S	Range 33E	NMPM County Lea	
n en	11. Elevation (Show whethe			
A Salva Control of Con				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	NTENTION TO:		ITTING <swdinjection></swdinjection>	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON X CHANGE PLANS	RE CONVE		
PULL OR ALTER CASING	MULTIPLE COMPL .	CA RETUR	N TO TA CHG LOC	
DOWNHOLE COMMINGLE		CSNG_	PA P&A NR P&A R	
CLOSED-LOOP SYSTEM OTHER:		OTis	PA 19 64 11 1	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
	ment. POOH w/ production ϵ	equipment.		
	rculate hole with mud laden	fluid. Pressure test ca	sing to 500 psi.	
	3. Spot 25 sx Class H cement on CIBP.			
4. POOH to 9050'. Spot 25 sx Class H cement.				
5 DOOH to 6500' Shot				
 POOH to 6500'. Spot Perforate at 4104'. Sq 	25 sx cement.	VOC and tag. (Interme	diate shoe)	
6. Perforate at 4104'. Sq				
6. Perforate at 4104'. Sq7. Perforate at 2650'. Sq8. Perforate at 1650'. Sq	25 sx cement. Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V	VOC and tag. (Base of VOC and tag. (Top at s	salt)	
6. Perforate at 4104'. Sq7. Perforate at 2650'. Sq8. Perforate at 1650'. Sq9. Perforate at 458'. Circ	25 sx cement. Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V Sulate cement to surface insi	VOC and tag. (Base of VOC and tag. (Top at s de/outside 5 1/2" casii	salt) salt) ng.	
 Perforate at 4104'. Sq Perforate at 2650'. Sq Perforate at 1650'. Sq Perforate at 458'. Circ Cut off wellhead 4' b 	25 sx cement. Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V	VOC and tag. (Base of VOC and tag. (Top at s de/outside 5 1/2" casii	salt) salt) ng.	
 Perforate at 4104'. Sq Perforate at 2650'. Sq Perforate at 1650'. Sq Perforate at 458'. Circ Cut off wellhead 4' b Cut off anchors. 	25 sx cement. Jueeze with 35 sx cement. V	VOC and tag. (Base of VOC and tag. (Top at s de/outside 5 1/2" casin ment to surface on all	salt) salt) ng.	
 Perforate at 4104'. Sq Perforate at 2650'. Sq Perforate at 1650'. Sq Perforate at 458'. Circ Cut off wellhead 4' b 	25 sx cement. Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V Jueeze with 35 sx cement. V Sulate cement to surface insi	VOC and tag. (Base of VOC and tag. (Top at s de/outside 5 1/2" casin ment to surface on all	salt) salt) ng.	
 Perforate at 4104'. Sq Perforate at 2650'. Sq Perforate at 1650'. Sq Perforate at 458'. Circ Cut off wellhead 4' b Cut off anchors. 	25 sx cement. Jueeze with 35 sx cement. V	VOC and tag. (Base of VOC and tag. (Top at s de/outside 5 1/2" casin ment to surface on all	salt) salt) ng.	
 Perforate at 4104'. Sq Perforate at 2650'. Sq Perforate at 1650'. Sq Perforate at 458'. Circ Cut off wellhead 4' b Cut off anchors. 	25 sx cement. Jueeze with 35 sx cement. Vilueeze with 35 sx cement.	VOC and tag. (Base of VOC and tag. (Top at side/outside 5 1/2" casing ment to surface on all see Date:	salt) salt) ng. string. Install P&A marker.	
6. Perforate at 4104'. Sq 7. Perforate at 2650'. Sq 8. Perforate at 1650'. Sq 9. Perforate at 458'. Circ 10. Cut off wellhead 4' b Cut off anchors.	25 sx cement. Jueeze with 35 sx cement. Vilueeze with 35 sx cement. Vilueeze with 35 sx cement. Vilueeze with 35 sx cement. Visualte cement to surface insigned elow ground level. Verify ce Rig Relea	VOC and tag. (Base of VOC and tag. (Top at side/outside 5 1/2" casing ment to surface on all see Date:	salt) salt) ng. string. Install P&A marker.	
6. Perforate at 4104'. Sq 7. Perforate at 2650'. Sq 8. Perforate at 1650'. Sq 9. Perforate at 458'. Circ 10. Cut off wellhead 4' b Cut off anchors.	25 sx cement. Jueeze with 35 sx cement. Vilueeze with 35 sx cement. Vilueeze with 35 sx cement. Vilueeze with 35 sx cement. Visualte cement to surface insigned elow ground level. Verify ce Rig Relea	VOC and tag. (Base of VOC and tag. (Top at side/outside 5 1/2" casing ment to surface on all see Date:	salt) salt) ng. string. Install P&A marker.	
6. Perforate at 4104'. Sq 7. Perforate at 2650'. Sq 8. Perforate at 1650'. Sq 9. Perforate at 458'. Circ 10. Cut off wellhead 4' b Cut off anchors. Spud Date: I hereby certify that the information SIGNATURE Mark Whitake	25 sx cement. Jueeze with 35 sx cement. V J	VOC and tag. (Base of VOC and tag. (Top at side/outside 5 1/2" casisment to surface on all see Date: the best of my knowleds Compliance Officer	salt) salt) ng. string. Install P&A marker. ge and belief.	
6. Perforate at 4104'. Sq 7. Perforate at 2650'. Sq 8. Perforate at 1650'. Sq 9. Perforate at 458'. Circ 10. Cut off wellhead 4' b Cut off anchors. Spud Date: Thereby certify that the information SIGNATURE Mark Whitake For State Use Only	25 sx cement. Jueeze with 35 sx cement. V J	VOC and tag. (Base of VOC and tag. (Top at side/outside 5 1/2" casin ment to surface on all see Date: Compliance Officer Iddress:	salt) salt) salt) string. Install P&A marker. ge and belief. DATE PHONE:	
6. Perforate at 4104'. Sq 7. Perforate at 2650'. Sq 8. Perforate at 1650'. Sq 9. Perforate at 458'. Circ 10. Cut off wellhead 4' b Cut off anchors. Spud Date: I hereby certify that the information SIGNATURE Mark Whitake	25 sx cement. Jueeze with 35 sx cement. V J	VOC and tag. (Base of VOC and tag. (Top at side/outside 5 1/2" casin ment to surface on all see Date: Compliance Officer Iddress:	salt) salt) ng. string. Install P&A marker. ge and beliefDATE	

CURRENT



13 3/8" @ 408' w/ 450 sx. Circ

8 5/8" @ 4054' w/ 2600 sx. Circ.

Perfs 9900-9922'

5 1/2" @ 10,105' w/900 sx. TOC by TS at 6220'

PBTD 10,065' TD 10,105'