Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD	Hobbe
-----	-------

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

NM	NM6	136	60	
NM	NM6	136	60	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals HOBBS OCD					NMNM61360		
Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. NMNM94480X		
1. Type of Well		8. Well Name and No. GAUCHO UNIT 20			DY YO		
Ø Oil Well	Contact: T	RINA C COL	ICH PEC	EIVED	9. API Well No.		
DEVON ENERGY PRODUCT	ION CO EPMail: trina.couch@				30-025-42778-0	5-5-5-5	
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102	Ph: 405-228	(include area code) 3-7203	,	10. Field and Pool, or Exploratory OJO CHISO			
4. Location of Well (Footage, Sec., T.	/				11. County or Parish, and State		
Sec 29 T22S R34E SESW 02 32.355420 N Lat, 103.492146					LEA COUNTY, NM		
12. CHECK APPR	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF 1	NOTICE, R	EPORT, OR OTHER	R DATA	
TYPE OF SUBMISSION			TYPE O	F ACTION			
Notice of Intent ■	☐ Acidize	☐ Deep	en	☐ Produc	ction (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Fract	ure Treat	☐ Reclan	nation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recom		Other	
☐ Final Abandonment Notice	☐ Change Plans		and Abandon		orarily Abandon		
	Convert to Injection	Plug		☐ Water Disposal ting date of any proposed work and appro			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for final Devon Energy Production Corunconsolidated sand at +/-2,8 casing to the proposed casing	k will be performed or provide to operations. If the operation rest andonment Notices shall be filed and inspection.) npany, L.P. respectfully re- 00' and lost returns +/-3.80	he Bond No. on alts in a multiple d only after all re	file with BLM/BIA completion or reco equirements, include	A. Required sompletion in a ling reclamation	ubsequent reports shall be new interval, a Form 316 on, have been completed, a	filed within 30 days 0-4 shall be filed once	
Devon Energy plans to return order to avoid LPC Timing stip	to the well location and propulations.	oceed with dr	illing after June	of 2016 in			
Attached is the P&A procedure	Э						
Thank you			SEE	ATTAC	CHED FOR		
	IDITIO	NS OF APPRO	VAI				
			CUI	VUITIO	V3 UF ALL INO	V. 1	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #3 For DEVON ENERGITED TO STATE OF THE PROPERTY OF T	BY PRODUCT	ION CO LP, sen	t to the Hob	bs		
Name(Printed/Typed) TRINA C	COUCH		Title REGUL	ATORY A	NALYST		
Signature (Electronic S	Submission)		Date 10/01/2	015		Ka	
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE	SEPROVED		
1.0			Tital		120	7 1	
_Approved By			Title	- 0	CT 2 2015	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office	15	S/ Chris Walle		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a c statements or representations as t	rime for any per o any matter wi	son knowingly and thin its jurisdiction	willfully to I			

P&A Procedure for Gaucho Unit 20Y

- 1. Notify BLM 4 hours prior to beginning P&A operation
- 2. TIH open ended to TD (2942')
- 3. Mix and spot 3600 sks of cement (2,942'-2,400')
- 4. TOH 10 stands and circulate bottoms up
- 5. WOC 4 hours
- 6. TIH and tag cement. Must tag cement at 2,400' or higher
- 7. TOH to 2,267' (shoe 2,217')
- 8. Mix and pump 404 sks of cement
- 9. TOH 5 stands and circulate bottoms up
- 10. WOC 4 hours
- 11. TIH and tag cement if must tag cement at 2,157'
- 12. TOH to 60'
- 13. Mix and pump 39 sks of cement to circulate surface. Be prepared to handle cement returns to surface. If cement falls, top off with sackrete
- 14. Record BLM notification
- Nipple down BOP, curt wellhead off and set a dry hole marker at ground level with the following information welded, stamped or otherwise permanently engraved into the marker's metal

The operator name Lease name and well number Location, (unit letter, section, township and range) Date of plugged

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours operator will place full tubing weight on plug when tagged.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs. The Neat cement shall be mixed according to the API water requirement. If operator requests a variance from the API water requirement, the plug(s) will be tagged and possibly pressure tested.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

Below Ground-level Abandoned Well Marker are required to avoid raptor perching: Upon the plugging and subsequent abandonment of the well, the well marker will be installed below ground level on a plate containing the pertinent information for the plugged well. Supply the GPS coordinates of the wellbore in the Subsequent Report of abandonment. For more installation details, contact the Carlsbad Field Office at 575-234-5972.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.