Submit 1 Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		Form C-103		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			Revised August 1, 2011 WELL API NO.		
District II - (575) 748-1283			WELL AFINO.	,	
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178			30-025-28256	V	
1000 Rio Brazos Rd., Aztec, NM 87410			5. Indicate Type of Lease STATE FEE XX		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sunta 1 0, 1417 07303		6. State Oil & Gas Lease No.		+
87505				100,00 - 200 - 1,000 - 100	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FORM C-101) FOR	Rocket			
PROPOSALS.) 1. Type of Well: Oil Well XX	Gas Well Other	8. Well Number 003 ✓		1	
2. Name of Operator		9. OGRID Number		1	
State of New Mexico formerly Car					
Address of Operator 1625 N. French Drive Hobbs, NM 88240			10. Pool name or Wildcat Jalmat-T-Y-SR		
4. Well Location			Jaimat-1-1-5K		4
ENGLISH CONTRACTOR AND ADDRESS OF THE PARTY.	2310feet from theSouth_	line and	2310 feet from the	Westline	
Section 10		tange 36E	NMPM Lea	County	
	11. Elevation (Show whether DR, I				
					4
RETURN TO CSNG ENVIRO INT TO PA P&A NR OTHEH: 13. Describe proposed or comp	CHG LOC CHG LOC Check operations. (Clearly state all peork). SEE RULE 19.15.7.14 NMAC.	For Multiple Cor	T JOB P AN	cluding estimated date ore diagram of	e
			001 1 8 2013		
			RECEIVED)	
I hereby certify that the information	above is true and complete to the bes	t of my knowledg	e and belief.		_
SIGNATURE	TITLE		DATE_		_
Type or print name	E-mail address:		PHONE		
For State Use Only	0				
APPROVED BY: Conditions of Approval (if any):	PUT TOWN THE DIS	t Supe	WISOU DATE !	0/13/2015	_

Plugging Report Rocket #3

9/30/2015 Move rig to location and spot. Could not rig up due to bee hive in pump jack.

10/1/2015 Rigged up. Unseated pump and laid down 140 ¾" rods. Dug out wellhead and replaced broke off connections on surface head. Installed BOP. SION

10/2/2015 POOH with 112 jts of 2 3/8" tubing. Made gauge ring run to 3400'. RIH and set 5 ½" CIBP at 3387'. Attempted to circulate hole with brine and mud. Slight blow to the pit but no circulation. Called OCD. Spotted 25 sx cement on CIBP. Shut down. Will tag and attempt to circulated again Monday.

10/5/2015 RIH with tubing to tag. No cement on top of CIBP @ 3387'. Established circulation with 20 bbls. Closed casing valve to the pit and tested casing to 400#. Held good. Re-spotted 25 sx Class C cement on top of CIBP at 3387'. POOH to 2920' and spotted 25 sx cement. Laid down pipe and POOH. Perforated 5 ½" casing at 1487'. RIH and squeezed perfs with 30 sx class c cement. SION. Will tag in the morning.

10/6/2015 RIH and tagged cement at 1314'. Laid down remaining pipe. Perforated 5 ½" casing at 300'. Established circulation and pumped cement down 5 ½" casing to perfs at 300' and up annulus to surface. Took 85 sx. Rigged down. Dug out cellar and cut off. Cement had fallen. Filled up both strings of casing to surface with 25 sx cement. Installed marker and cut off anchors. Filled in holes and back-drug location. Moved rig and equipment.