	Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
	Office District I – (575) 393-6161 HOBBS Energy, Minerals and Natural Resources	Revised July 18, 2013
	1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
,	District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 NOV 1 6 2015 CONSERVATION DIVISION District III - (505) 334-6178	30-025-00370
	Distriction (303) 334 0170	5. Indicate Type of Lease
	1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE  6. State Oil & Gas Lease No.
	District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM RECEIVED 87505	6. State Oil & Gas Lease No.
	SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
	PROPOSALS.)	Lea R State NCT A
	1. Type of Well: Oil Well Gas Well Other	8. Well Number 001
1	2. Name of Operator	9. OGRID Number
	Devon Energy Production Company, LP	6137
	3. Address of Operator	10. Pool name or Wildcat
	333 W. Sheridan Avenue, Oklahoma City, OK 73102	Anderson Ranch;Cisco-Canyon,North
	4. Well Location	
	Unit LetterA:_990' feet from theNorth line and660	feet from theEastline
	Section 02 Township 16S Range 32E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM Lea County, NM
	4316.5' KB; 4300'GL; 16.5' KB to GL	
	12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
		•
		ITTING <swdinjection></swdinjection>
	TEMPORARII V ARANDONI TI CHANCE DI ANC	
	DILL OR ALTER CASING AMULTIPLE COMPLETE	
	DOWNHOLE COMMINGLE	
	CLOSED-LOOP SYSTEM	PAMP&A NR P&A R
	OTHER:	1.1
	OTHER:  OTHER:  OTHER:  OTHER:	d give pertinent dates, including estimated date
-	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co</li> </ol>	
	13. Describe proposed or completed operations. (Clearly state all pertinent details, an	
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.</li> </ol>	mpletions: Attach wellbore diagram of
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> </ol>	mpletions: Attach wellbore diagram of 0' – 9,090'. (T.Wolfcamp @ 9,202)
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A.)</li> </ol>	mpletions: Attach wellbore diagram of 0' - 9,090'. (T.Wolfcamp @ 9,202) lbo @ 7,610')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A.)</li> </ol>	mpletions: Attach wellbore diagram of 0' - 9,090'. (T.Wolfcamp @ 9,202) abo @ 7,610') Glorieta @ 5,680')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A. Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T.C.)</li> </ol>	mpletions: Attach wellbore diagram of 0' – 9,090'. (T.Wolfcamp @ 9,202) abo @ 7,610') Glorieta @ 5,680') OC. (9-5/8" shoe @ 4,174')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T. C Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T</li> </ol>	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  bo @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T. C Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> </ol>	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  bo @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T. C Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> <li>Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.</li> </ol>	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  bo @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T. C Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> </ol>	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  bo @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T. O Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> <li>Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.</li> <li>Cut wellhead off. Set dry hole marker.</li> </ol>	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  bo @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A.)</li> <li>Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T.C.)</li> <li>Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T.</li> <li>Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> <li>Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.</li> <li>Cut wellhead off. Set dry hole marker.</li> </ol> The 6	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')  (13-3/8" shoe @ 611')  Oil Conservation Division
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A.)</li> <li>Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T.C.)</li> <li>Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T.</li> <li>Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> <li>Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.</li> <li>Cut wellhead off. Set dry hole marker.</li> </ol> MUST MUST	mpletions: Attach wellbore diagram of  0' – 9,090'. (T.Wolfcamp @ 9,202)  bo @ 7,610') Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430') (13-3/8" shoe @ 611')  Oil Conservation Division  Γ BE NOTIFIED 24 Hours
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A.)</li> <li>Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T.C.)</li> <li>Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T.</li> <li>Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> <li>Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.</li> <li>Cut wellhead off. Set dry hole marker.</li> </ol> MUST MUST	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')  (13-3/8" shoe @ 611')  Oil Conservation Division
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A.)</li> <li>Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T.C.)</li> <li>Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T.</li> <li>Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> <li>Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.</li> <li>Cut wellhead off. Set dry hole marker.</li> </ol> MUST Prior to	mpletions: Attach wellbore diagram of  0' – 9,090'. (T.Wolfcamp @ 9,202)  bo @ 7,610') Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430') (13-3/8" shoe @ 611')  Oil Conservation Division  Γ BE NOTIFIED 24 Hours
	13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21   2. Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A   3. Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T. C   4. Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T   5. Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T   6. Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T   7. Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.   8. Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.   9. Cut wellhead off. Set dry hole marker.  • 9# mud will be circulated between each plug.  The O   MUST	mpletions: Attach wellbore diagram of  0' – 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')  (13-3/8" shoe @ 611')  Oil Conservation Division  T BE NOTIFIED 24 Hours  The beginning of operations
	<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21</li> <li>Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A.)</li> <li>Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T.C.)</li> <li>Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T.</li> <li>Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T.</li> <li>Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.</li> <li>Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.</li> <li>Cut wellhead off. Set dry hole marker.</li> </ol> MUST Prior to	mpletions: Attach wellbore diagram of  0' – 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')  (13-3/8" shoe @ 611')  Oil Conservation Division  T BE NOTIFIED 24 Hours  The beginning of operations
	13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') C1 C @ 9,21   2. Perf sqz holes @ 7,575'. Pump 50 sx (140') C1 H in/out @ 7,575' - 7,435'. (T.A   3. Perf sqz holes @ 5,680'. Pump 50 sx (175') C1 C in/out @ 5,680' - 5,505'. (T. C   4. Perf sqz holes @ 4,224'. Pump 50 sx (165') C1 C in/out @ 4,224' - 4,059'. Tag T   5. Perf sqz holes @ 2,540'. Pump 50 sx (165') C1 C in/out @ 2,540' - 2,375'. Tag T   6. Perf sqz holes @ 1,430'. Pump 50 sx (165') C1 C in/out @ 661' - 496'. Tag TOC.   8. Perf sqz holes @ 661'. Pump 50 sx in/out from 165' to surface.   9. Cut wellhead off. Set dry hole marker.  • 9# mud will be circulated between each plug.  The MUST    Prior to	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610') Glorieta @ 5,680') OC. (9-5/8" shoe @ 4,174') OC. (B.Salt @ 2,540') OC. (T.Salt @ 1,430') (13-3/8" shoe @ 611')  Oil Conservation Division T BE NOTIFIED 24 Hours The beginning of operations
1	13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21   2. Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A   3. Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T. C   4. Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T   5. Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T   6. Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T   7. Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.   8. Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.   9. Cut wellhead off. Set dry hole marker.  • 9# mud will be circulated between each plug.  The O   MUST	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610') Glorieta @ 5,680') OC. (9-5/8" shoe @ 4,174') OC. (B.Salt @ 2,540') OC. (T.Salt @ 1,430') (13-3/8" shoe @ 611')  Oil Conservation Division T BE NOTIFIED 24 Hours The beginning of operations
]	13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21   2. Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' – 7,435'. (T.A   3. Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' – 5,505'. (T.   4. Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' – 4,059'. Tag T   5. Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' – 2,375'. Tag T   6. Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' – 1,265'. Tag T   7. Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' – 496'. Tag TOC.   8. Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.   9. Cut wellhead off. Set dry hole marker.  • 9# mud will be circulated between each plug.  The MUST    MUST    Prior to    Spud Date: Rig Release Date:    The Graduate    TITLE    Production Technological    Production Technological    SIGNATURE    Annual Market    TITLE    Production Technological    The Graduate    TITLE    Production Technological    The Graduate    TITLE    Production Technological    The Graduate    TITLE    Production Technological    TITLE    Production Technological    The Graduate    TITLE    Production Technological    The Graduate    TITLE    Production Technological    The Graduate    TITLE    Production Technological    Total Technological    The Graduate    Total Technological    The Graduate    Total Technological    The Graduate    The Gra	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202) abo @ 7,610') Glorieta @ 5,680') OC. (9-5/8" shoe @ 4,174') OC. (B.Salt @ 2,540') OC. (T.Salt @ 1,430') (13-3/8" shoe @ 611')  Oil Conservation Division T BE NOTIFIED 24 Hours The beginning of operations  The beginning of operations
	13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21   2. Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' – 7,435'. (T.A   3. Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' – 5,505'. (T. C   4. Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' – 4,059'. Tag T   5. Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' – 2,375'. Tag T   6. Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' – 1,265'. Tag T   7. Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' – 496'. Tag TOC.   8. Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.   9. Cut wellhead off. Set dry hole marker.  • 9# mud will be circulated between each plug.  The MUST    Prior to    Spud Date:  Rig Release Date:  The Gray    SIGNATURE	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202) abo @ 7,610') Glorieta @ 5,680') OC. (9-5/8" shoe @ 4,174') OC. (B.Salt @ 2,540') OC. (T.Salt @ 1,430') (13-3/8" shoe @ 611')  Oil Conservation Division T BE NOTIFIED 24 Hours The beginning of operations  The beginning of operations
1	13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21   2. Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' - 7,435'. (T.A   3. Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (T.   4. Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag T   5. Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag T   6. Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag T   7. Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag TOC.   8. Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.   9. Cut wellhead off. Set dry hole marker.  • 9# mud will be circulated between each plug.  The MUST    **MUST**  **Prior to**  **ITTLE**  **Production Technologitation**  **TITLE**  **Production Technologitation**  **Total Complete to the best of my knowledge   **SIGNATURE**  **Jump**  **TITLE**  **Production Technologitation**  **Total Complete to the best of my knowledge   **Prior to**  **TITLE**  **Production Technologitation**  **TITLE**  **Production Technologitation**  **Total Complete to the best of my knowledge   **Total Complete to the	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')  (13-3/8" shoe @ 611')  Oil Conservation Division  T BE NOTIFIED 24 Hours  The beginning of operations  The beginning of operations  The beginning of operations
	13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.  1. MIRU. Tag PBD @ 9,595'. Circulate w/9# mud. Spot 25 sx (120') Cl C @ 9,21   2. Perf sqz holes @ 7,575'. Pump 50 sx (140') Cl H in/out @ 7,575' – 7,435'. (T.A   3. Perf sqz holes @ 5,680'. Pump 50 sx (175') Cl C in/out @ 5,680' – 5,505'. (T. C   4. Perf sqz holes @ 4,224'. Pump 50 sx (165') Cl C in/out @ 4,224' – 4,059'. Tag T   5. Perf sqz holes @ 2,540'. Pump 50 sx (165') Cl C in/out @ 2,540' – 2,375'. Tag T   6. Perf sqz holes @ 1,430'. Pump 50 sx (165') Cl C in/out @ 1,430' – 1,265'. Tag T   7. Perf sqz holes @ 661'. Pump 50 sx (165') Cl C in/out @ 661' – 496'. Tag TOC.   8. Perf sqz holes @ 165'. Pump 50 sx in/out from 165' to surface.   9. Cut wellhead off. Set dry hole marker.  • 9# mud will be circulated between each plug.  The MUST    Prior to    Spud Date:  Rig Release Date:  The Gray    SIGNATURE	mpletions: Attach wellbore diagram of  0' - 9,090'. (T.Wolfcamp @ 9,202)  100 @ 7,610')  Glorieta @ 5,680')  OC. (9-5/8" shoe @ 4,174')  OC. (B.Salt @ 2,540')  OC. (T.Salt @ 1,430')  (13-3/8" shoe @ 611')  Oil Conservation Division  T BE NOTIFIED 24 Hours  The beginning of operations  The beginning of operations  The beginning of operations

All Name   EAD STAIGT A #4	PRODUCTION COMPANY LP
Vell Name: LEA R ST NCT A #1 ocation: 990' FNL & 660' FEL; SEC 2-T165-R32E	Field: ANDERSON RANCH NORTH  County: LEA State: NM
levation: 4316.5 KB; 4300' GL; 16.5' KB to GL	County: LEA State: NM Spud Date: 11/3/57 Compl Date: 5/15/58
Pl#: 30-025-00370   Prepared by: Ronnie Slack	Date: 6/17/15 Rev:
PROPOSED PLUG & ABANDONMENT	Proposed: 1. Perf sqz holes @ 165'. 2. Pump 50 sx Cl C in/out to surface.
17-1/2" hole 13-3/8", 48#, H40, @ 611' Cmt'd w/725 sx to surface	9# mud  3. Cut wellhead off. Set dry hole marker  Proposed: 1. Perf sqz holes @ 661'. 2. Pump 50 sx (165') Cl C in/out @ 661' - 496'. Tag.
HOBBS OCD	9# mud  Proposed: 1. Perf sqz holes @ 1,430'.
NOV 1 6 2015	9# mud 2. Pump 50 sx (165') Cl C in/out @ 1,430' - 1,265'. Tag. (T.Salt 1430')
RECEIVED	Proposed: 1. Perf sqz holes @ 2,540'. 2. Pump 50 sx (165') Cl C in/out @ 2,540' - 2,375'. Tag.  (B.Salt 2540')
12-1/4" hole 9-5/8", 36#, S80, @ 4,174' Cmt'd w/2770 sx to surface	Proposed: 1. Perf sqz holes @ 4,224'. 2. Pump 50 sx (165') Cl C in/out @ 4,224' - 4,059'. Tag.
3	Proposed: 1. Perf sqz holes @ 5,680'. 2. Pump 50 sx (175') Cl C in/out @ 5,680' - 5,505'. (Glorieta @ 5,680')
TOC @ 7,600' (temp survey)	Proposed: 1. Perf sqz holes @ 7,575'. 2. Pump 50 sx (140') Cl H in/out @ 7,575' -7,435'. (Abo @ 7,610') 9# mud
	Proposed: Spot 25 sx (120') Cl H @ 9,210' - 9,090'. (Wolfcamp @ 9,202')
	35' Cmt. 9,595' PBD. (2/19/13) CIBP @ 9,630' (2/19/13) 35' Cmt. 9,715' PBD. (2/15/13)
WOLFCAMP (orig dual cmpl - 5/58) 9,828' - 9,862' (sqzd w/150 sx-1/29/82)	CIBP @ 9,750' (2/15/13)
CISCO CANYON (9/10/84) 10,501' - 10,508'	35' Cmt. 10,435' PBD. (2/14/13) CIBP @ 10,470' (2/14/13)
DV Tool @ 11,419'	Tight spot noted in csg @ 11,335', w/6-1/8 bit in hole.  Milled through to 11,678'. 3/1/82  Set DR Packer Plug (9/7/84)
9 2/4" Hala	Model D Packer @ 13,275' (3/25/82)  Fished out Model D Packer at 13,318. TIH w/6-1/8" bit,
8-3/4" Hole 7", 23# & 26#, N80 & S95, @ 13,391' Cmt'd w/1250 sx	cleaned out to 13,418' (3/24/82)  Rec back to Devonian - 22 bo, 1068 bw on Kobe pmp
6-1/8" Devonian Open Hole (orig dual cmpl - 5/58) 13,391' - 13,420'	(4/27/82)

DEVON ENERGY F	PRODUCTION COMPANY LP
Vell Name: LEA R ST NCT A #1	Field: ANDERSON RANCH NORTH
ocation: 990' FNL & 660' FEL; SEC 2-T16S-R32E	County: LEA State: NM
(levation: 4316.5 KB; 4300' GL; 16.5' KB to GL	Spud Date: 11/3/57   Compl Date: 5/15/58
PI#: 30-025-00370   Prepared by: Ronnie Slack	Date: 4/30/15 Rev:
CURRENT WELLBORE  17-1/2" hole 13-3/8", 48#, H40, @ 611' Cmt'd w/725 sx to surface  HOBBS OCD  NOV 1 6 2015  12-1/4" hole 9-5/8", 36#, \$80, @ 4,174' Cmt'd w/2770 sx to surface	Wellbore TA'd on 2/19/13    ZONE
TOC @ 7,600* (temp survey)	301 Jts, 2-7/8", N80 production tbg SN @ 9,401' (2/9/13) 35' Cmt. 9,595' PBD. (2/19/13) CIBP @ 9,630' (2/19/13)
WOLFCAMP (orig dual cmpl - 5/58) 9,828' - 9,862' (sqzd w/150 sx-1/29/82)	35' Cmt. 9,715' PBD. (2/15/13) CIBP @ 9,750' (2/15/13)
CISCO CANYON (9/10/84) 10,501' - 10,508'	35' Cmt. 10,435' PBD. (2/14/13) CIBP @ 10,470' (2/14/13)
DV Tool @ 11,419'	Tight spot noted in csg @ 11,335', w/6-1/8 bit in hole. Milled through to 11,678'. 3/1/82
	Set DR Packer Plug (9/7/84) Model D Packer @ 13,275' (3/25/82)  Fished out Model D Packer at 13,318. TIH w/6-1/8" bit, cleaned out to 13,418' (3/24/82)
8-3/4" Hole  7", 23# & 26#, N80 & S95, @ 13,391'  Cmt'd w/1250 sx  6-1/8" Devonian Open Hole 13,391' - 13,420'  (orig dual cmpl - 5/58)	Rec back to Devonian - 22 bo, 1068 bw on Kobe pmp (4/27/82)