Submit 1 Copy To Appropriate District Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised July 18, 2013 WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	OIL CONSERVATI 1220 South St. I Santa Fe, NM	Francis Dr.	30-025-36226         5. Indicate Type of Lease         STATE       FEE         6. State Oil & Gas Lease No.	
		R PLUG BACK TO A 1) FOR SUCH	<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>HOWSE</li> <li>8. Well Number 1</li> </ul>	
2. Name of Operator CHEVRON U.S.A., INC.	/	MOV 1 9 2015	9. OGRID Number 147179	
3. Address of Operator 15 SMITH ROAD, MIDLAND, 7	TEXAS 79705	NUT 10	10. Pool name or Wildcat SWD; San Andres	
4. Well Location       Image: Construct of the section o				
12. Check	Appropriate Box to Indicate	e Nature of Notice,	Report or Other Data	
F       E-PERMITTING <swdinjection>         T       CONVERSIONRBDMS]         F       RETURN TOTA]         CSNGENVIRO_CHG LOC         INT TO PAP&amp;A NR_P&amp;A R]</swdinjection>				
	ork). SEE RULE 19.15.7.14 NM		d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of	

Please find attached a summary report for work conducted 10/22-29/2015 to plug and abandon the subject well.

Spud Date:	Rig Release Date:	
I hereby certify that the information above is true	e and complete to the best of my knowledge and b	pelief.
SIGNATURE Bol Hall	TITLE WORKOVER ENGINEER	DATE 11/18/2015
Type or print name BoB HALL	E-mail address:	RON. COM PHONE: 432-687-7243
For State Use Only A	1 TITLE Dist. Supervision	
	DEC 0 2	201 <b>5</b>

10/22-24/2015 MIRU plugging equipment. Bleed well down. Kill well. Remove downhole equipment.


10/24/2015 RU Wireline Unit. Set CIBP @ 4,263'. RD Wireline Unit. Pressure test casing to 500 psi for 30 minutes – good test.

10/26/2015 TIH with tubing workstring. Tag CIBP @ 4,263'. Pull up to 4,259'. Circulate well with 110 BBL 9.4 PPG Salt Gel. Spot balanced plug of 25 sks Class C cement (14.8 PPG, 1.32 ft3/sk yield) @ 4,259'. Pull tubing and SWI to WOC. TIH with tubing to tag TOC @ 3,978'. POOH with tubing. SWI.

10/27/2015 RU Wireline Unit. Perforate @ 2,800'. RD Wireline Unit. RIH to set packer @2,413'. Pressured up to 2,000 psi and could not establish injection rate into perforations. Contacted Mark Whitaker and received permission to spot cement plug. Release packer. POOH and laydown packer. RIH with tubing to 2,853'. Spot balanced plug of 25 sks Class C cement (14.8 PPG, 1.32 ft3/sk yield) @ 2,853'. POOH with tubing. SWI.

10/28/2015 RU Wireline Unit. RIH to tag TOC @ 2,538'. Perforate @ 1,710'. RIH to set packer @ 1,282'. Establish injection rate into perforations of 2.5 BPM @ 1,500 psi. Pump 65 sks Class C cement (14.8 PPG, 1.32 ft3/sk). Displace with 12 BBL. SWI to WOC. Release packer & TIH to tag TOC @ 1,456'. POOH with tubing and packer. Perforate@ 400'. RD Wireline Unit. Established injection rate into perforations of 3 BPM @ 600 psi with no returns after pumping 140 BBL fresh water. Contacted Mark Whitaker and received permission to pump 40 sacks cement and displace to 300', then to perforate casing @ 60'. Pump 40 sks Class C cement (14.8 PPG, 1.32 ft3/sk). Displace with 6 BBL. SWI with 300 psi on casing.

10/29/2015 RU Wireline Unit. RIH to tag TOC @ 234'. Perforate @ 60'. Unable to establish injection or circulation through perforations. Contacted Mark Whitaker and received permission to bullhead squeeze 25 sacks of cement from surface. RD Pulling Unit. ND BOP. NU wellhead flange. Bullhead squeeze from surface 10 sks Class C cement (14.8 PPG, 1.32 ft3/sk) @ 1.5 BPM when well locked up at 1,000 psi. Bled down to 500 psi. SWI. RDMO plugging equipment.



Updated: 11/18/2015

By: Bob Hall