Submit I Copy To Appropriate District Office	State of	New Me	exico			C-103
District I – (575) 393-6161	Energy, Minerals	and Natu	ral Resources	THE LAND	Revised July	18, 2013
1525 N. French Dr., Hobbs, NM 88240				WELL API	1 NO. <b>30-025-027</b> I	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERV	OIL CONSERVATION DIVISION		5 Indicate	Type of Lease	,
District III - (505) 334-6178	1220 South St. Francis Dr.			STA		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fo	e, NM 87	7505		1 & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM					811	
87505	ICES AND REPORTS O	NI WELLS	HOBBS (		ame or Unit Agreement	Jame
(DO NOT LISE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEE	DEN OR DI	IG BACK TO A			vaille /
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FOR	M C-101) FO	OR SUCHEB 2 9 20	16 State	D	1
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well  Other			8. Well Nu	imber # 002	
2. Name of Operator	Resources Con	20-10	RECEIV	OGRID	Number	
	1 Kesources Con	poraori		10 D 1	162928	
3. Address of Operator 3510 N. 'A' St. Bld	lgs A+B Midland	ITX T	79705		ame or Wildcat	
4. Well Location	160.	C 1	,		. 11. +	
Unit Letter:	1980 feet from the				eet from the West	_line
Section 2	Township 14		ange 35 E	NMPM	County Lea	,
	11. Elevation (Show with 39°	hether DR,	RKB, RT, GR, etc.)	)		
10 (1)		1' . N	CNT	D	24 D	
12. Check A	Appropriate Box to In	idicate N	ature of Notice,	Report or C	Other Data	
NOTICE OF IN	ITENTION TO:		SUB	SEQUEN	_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	I X	REMEDIAL WOR	K	INT TO PA	]
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI		P&A NR	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT	T JOB	P&A R	_
DOWNHOLE COMMINGLE						_
CLOSED-LOOP SYSTEM			OTHER:			1
OTHER:  13. Describe proposed or comp	leted operations (Clearly	v state all t		d give pertine	ent dates including estima	ated date
of starting any proposed wo						
proposed completion or rec					0	
	./ / 21/1	1				
See a	Hacked P3 A	Pro	oduse			
200	100000000000000000000000000000000000000	10	avacce			
1211			m hero	n		
NOTE L'HA	NGB>		Mountago			
* NOTE CHA	TENT					
, ,		NOTIEV	OCD 24 HOURS	PRIOR TO E	BEGINNING	
		PLUGG	ING OPERATIONS	S		
	p: 1	D 1 D				
Spud Date:	Rig I	Release Da	ite:			
I hereby certify that the information	above is true and comple	te to the b	est of my knowledge	e and belief.		
A moreog certify that the information	toove is true und comple	to to the o	ost of my mio wieug	o una conten		
SIGNATURE Bunda TK	attyes TIT	LE Rees	clatary Analy	nt	DATE 2/24/1	6
Type or print name Brenda F. K	E-m	ail address	s: prathjen @	energen.	OMHONE: 432/688	3247
For State Use Only	D.1.	TI		2 . 1	1 1	
APPROVED BY! Wall	Witaha TITI	Etetro	leum Engr. S	pegalis	- DATE 03/01/2	2016
Conditions of Approval (if any):			V			

MAR 0 3 2016

#### **ENERGEN RESOURCES CORPORATION**

State -D- 2, API # 30-025-02711

AFE # PB16500033, \$75,000 1980' FSL & 330' FWL Sec. 1, T-16-S, R-35-E Lea County, NM

The State -D- 2 was spud 01/29/56, and was completed 03/24/56 as a Wolfcamp producer. It was temporarily abandoned 12/02/05. The well will not pass the required casing pressure test, and is recommended for plug and abandonment.

For scope changes during work, stop and discuss with engineering before proceeding

API:

30-025-02711

KR. 11' PBTD: 10250' w/ CIBP

Spud Date:

3989

TD: 10645'

1/29/1956

GLE:

Plug and Abandon Procedure

#### SAFETY CONSIDERATIONS

Observe all Energen Guidelines for PPE and H2S Safety

Observe perforation and contractor safety guidelines

Wireline and explosives on location while perforating

Workstring should be in good condition and tested to 5000 psi.

BOP should be in good working condition and tested

Rig anchors will need to be tested prior to MIRU

Keep a TIW valve open and on the rig floor at all times

Notify the NM OCD 24 hours prior to starting P&A operations

Requires FAA notice due to being close to airport.

Meet with engineer, superintendents, and consultant prior to beginning the job,

to assure that everyone is agreement with the procedure.

Bid as a turnkey project.

1	MIRI	I Well	Service	Unit

- 2 NDWH
- 3 NU adapter flange and BOP for 8-5/8" csg and 2-7/8" tubing. Test to 500 psi above working pressure.
- 4 Unload and rack 10,300' 2-7/8" workstring. Maintain kill truck w/10 ppg brine on location.
- 5 RIH with workstring, Circulate hole to 10 ppg mud. Tag CIBP @ 10.250'.
- 6 Dump bail 5 sx cmt or 20 sx through tubing on top CIBP. CLASS' H'

7 Perforate and squeeze at 7400' w/ 30 sxs cement plug and displace to 7300'. (Tubb)

Pressure test csq.

9 Perforate and squeeze at 4713' w/ 40 sxs cement plug and displace to 4613'. (shoe) 7.547 Spot 25 sx at 2000'
10 Perforate and squeeze at 4519' w/ 40 sxs cement plug and displace to 4419' (liner ton)
11 PROTECTION

10 Perforate and squeeze at 4519' w/ 40 sxs cement plug and displace to 4419'. (liner top)

11 Perforate and squeeze at 345' w/ 40 exe gement plug and displace to 245'. (surface casing shoe) TO SURFACE

12 WOC & tag.

13 Pull uphole, spot 30 sxs Class "C" cement at 100' to surface. (Visual top plug)

14 ND BOP. Top off well with cement. RD and clean location.

14 ND BOP. Top off well with cement. RD and clean location.

15 Cut off all casing strings at base of cellar or 3' below restored ground level. Verify cmt to surface all strings.

16 Cover wellbore with metal plate welded in place or with cement cap.

17 Erect capped abandonment marker inscribed with well information.

18 Cut off dead man anchors and fill in cellar. Backfill pit. RDMO.

19 Clean and restore location to natural condition and fulfill any and all regulatory requirements.

# ENERGEN RESOURCES CORP

State -D- 2

**Current WBD** LEA COUNTY, NM Conductor: None Surface Casing: 13-3/8", 48# @295' in 17" hole Cemented to surface 295' with 350 sx Intermediate Casing: 8-5/8" 24# & 32# @4653' in 11" hole w/2300 sx, circ'd 4653' Liner top squeezed w/ 200sx 7413' **Production Casing:** 5-1/2", 17# liner @ 4469'-10,633' w/ 600 sx, TOC 7413' by WWS TS

GL Elevation: 3989'

KB Elevation: 4000' -- 11' above GL Location: 1980' FSL & 330' FWL

Sec 1-T16S-R35E

Spud: 03/28/56

API: 30-025-02711

Anhydrite 1820'
Yares 3150
Queen 3950
San Andres 4648
Glorieta 6266
Tubb 7400
Abo 8100
Wolfcamp 10466

### Wolfcamp perfs:

03/24/56: 10571'-10605' 06/60: 10544'-10561'

7/30/81: CIBP 10450' w/ 50' sand 7/30/81: 10293'-10314' 12/02/05: CIBP @ 10,250'√


PBTD: 10,633' BP lost at 10,580' TD: 10,645'

## ENERGEN RESOURCES CORP

State -D- 2

GL Elevation: 3989'

KB Elevation: 4000' -- 11' above GL



7413'

mud

5 sx cmt on top CIBP 12/02/05: CIBP @ 10,250'

#### Wolfcamp perfs:

03/24/56: 10571'-10605' 06/60: 10544'-10561' 7/30/81: CIBP 10450' w/ 50' sand 7/30/81: 10293'-10314' 12/02/05: CIBP @ 10,250'

PBTD: 10,633' BP lost at 10,580' TD: 10,645'

**Production Casing:** 

5-1/2", 17# liner @