Form 3160-5 (August 2007)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5.	Lease Serial No.	
	NIMMIM120722	

SUNDRY N	OTICES A	AND REPO	DRTS ON	WELLS
Do not use this	form for p	roposals to	drill or to	re-enter an
abandoned well.	Use form	3160-3 (AF	PD) for suc	h proposals.

abandoned we	6. If Indian, Allotte	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	7. If Unit or CA/A NMNM13407	greement, Name and/or No.			
1. Type of Well Gas Well Other				Well Name and No.     HAMON A FEDERAL COM 4H	
Name of Operator LEGACY RESERVES OPERA	Contact: ATING LPE-Mail: csparkman	CRAIG SPARKMAN @legacylp.com	9. API Well No. 30-025-4161	7-00-S1	
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702		3b. Phone No. (include area code Ph: 432-689-5200 Ext. 633	10. Field and Pool, TEAS	, or Exploratory	
4. Location of Well (Footage, Sec., 7 Sec 6 T20S R34E SWSE 420 32.354534 N Lat, 103.354824	FSL 1920FEL	APR 21	LEA COUNT	11. County or Parish, and State  LEA COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION		
<ul><li>□ Notice of Intent</li><li>☑ Subsequent Report</li><li>□ Final Abandonment Notice</li></ul>	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	□ Production (Start/Resume) □ Reclamation □ Recomplete □ Temporarily Abandon □ Water Disposal	<ul><li>□ Water Shut-Off</li><li>□ Well Integrity</li><li>☑ Other</li></ul>	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

HORIZONTAL LATERAL COMPLETION. SEE ATTACHED PROCEDURE.

14. I hereby certify th	at the foregoing is true and correct.  Electronic Submission #301770 verifie  For LEGACY RESERVES OPE  Committed to AFMSS for processing by LI	d by the RATING NDA JII	e BLM Well Information System à LP, sent to the Hobbs MENEZ on 09/02/2015 (15LJ1880SE)			
Name(Printed/Type	ed) CRAIG SPARKMAN	Title	OPERATIONS ENGINEER			
Signature	(Electronic Submission)	Date	O5/14/2015 ACCEPTED FOR RECORD			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
certify that the applicant	f any, are attached. Approval of this notice does not warrant or holds legal or equitable title to those rights in the subject lease applicant to conduct operations thereon.	Title	APRI 2016  Date  Date  CARLSBAD FILLO OFFICE			
	001 and Title 43 U.S.C. Section 1212, make it a crime for any pous or fraudulent statements or representations as to any matter w		owingly and willfully to make to any trepartment or agency of the United jurisdiction.			

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

# **HAMON FED COM A #4H**

# Subsequent Report for Form 3160-5

## **Horizontal Lateral Completion**

## 11/25/14:

Install frac valve. RU pump truck. Establish injection rate of 7.3 BPM @ 5100# into toe sleeve. RD pump truck.

## 12/8/14 to 12/14/14:

MIRU frac crew. Pump down CCL/GR logs. Pull logs from 16,138' MD to 9,800' MD. Frac'd horizontal lateral as follows:

Stage 1:

Perf: 15,841'-16,136' MD. Acidized w/3k gals 10% acid. Frac'd w/8821 bbls 20# XL gel, 303,971# 20/40 White, & 98,104# 20/40 OilPlus.

Stage 2:

Set flow-thru plug @ 15,796' MD. Plug did not shear off of setting tool. Could not pull out of rope socket. Attempt to shear plug from setting tool by shooting first perforating gun at 15,784' MD, no success. RU to pump down one hour timed WL cutting tool. While equalizing pressure to the lubricator the WL was sheared at the top of the lubricator due to insufficient grease. Bled pressure and removed WL cutting tool from lubricator. RU slickline truck & RIH w/wireline catch tool. Tag'd wireline @ 560'. Latched onto parted wireline and pulled to surface. RU & pumped down one hour timed WL cutting tool. RU cut off WL back onto WL truck & POH spooling WL. RD WL equipment. RU CTU. RIH w/2.25" grapple and overshot. Tag'd fish @ 15,624' MD. Worked overshot down to 15,784'. Pumped 200 bbls 17# kill mud. POH w/CT. Recovered remaining wireline and WL cutting tool. RIH w/2.25" grapple and overshot. Tag'd WL CCL tool @ 15,766' MD. Latched on and attempted to shear plug from setting tool, no success. Drop ball and shear off CT BHA. WL tools left in well: 5-1/2" flow-thru plug (1.25') @ 15,796' MD, setting sleeve (4.32" OD - 1.20'), Baker 20 setting tool w/firing head (3.82" OD - 6'), plug shoot (3.12" OD – 3.45'), sub (3.12" OD – 0.25'), gun (3.12" OD – 3'), sub (3.12" OD – 0.25'), gun (3.12" OD – 3'), sub (3.12" OD – 0.25'), gun (3.12" OD – 3'), sub (3.12" OD – 0.25'), gun (3.12" OD – 3'), top sub (3.12" OD - 0.25'), CCL (3.12" OD - 2.6'), and cable head (1.7" OD - 1.50'). Total length of WL tools is 29.25'. CT fishing tools left in well: Overshot cutlip guide (3.88" OD – 0.23'), overshot extension (3.88" OD - 3'), series 150 overshot (3.88" OD), rotary sub (3.88" OD), ultra short fishing motor (2.88" OD), and hydraulic disconnect (2.88" OD). Total length of CT fishing tools is 13.83'. Top of fish is 15,753' MD.

## 12/15/14 to 12/18/14:

Resume fracturing horizontal lateral as follows:

Stage 2:

Set flow-thru plug @ 15,748' MD. Perf: 15,456'-15,734' MD. Acidized w/3k gals 10% acid. Frac'd w/6296 bbls 20# XL gel, 306,168# 20/40 White, & 100,523# 20/40 OilPlus. Stage 3:

Set flow-thru plug @ 15,411' MD. Perf: 15,071'-15,366' MD. Acidized w/3k gals 10% acid. Frac'd w/6559 bbls 20# XL gel, 304,049# 20/40 White, & 101,238# 20/40 OilPlus.

#### Stage 4:

Set flow-thru plug @ 15,026' MD. Perf: 14,686'-14,981' MD. Acidized w/3K gals 10% acid. Frac'd w/6444 bbls 20# XL gel, 304,004# 20/40 White, & 100,562# 20/40 OilPlus.

## Stage 5:

Set flow-thru plug @ 14,641' MD. Perf: 14,301'-14,596' MD. Acidized w/3k gals 10% acid. Frac'd w/6574 bbls 20# XL gel, 305,538# 20/40 White, & 107,901# 20/40 OilPlus.

## Stage 6:

Set flow-thru plug @ 14,256' MD. Perf: 13,916'-14,211' MD. Acidized w/3k gals 10% acid. Frac'd w/6343 bbls 20# XL gel, 299,955# 20/40 White, & 101,274# 20/40 OilPlus.

### Stage 7:

Set flow-thru plug @ 13,871' MD. Perf: 13,628'-13,826' MD. Acidized w/3k gals 10% acid. Frac'd w/6190 bbls 20# XL gel, 297,688# 20/40 White, & 99,177# 20/40 OilPlus.

#### Stage 8:

Set flow-thru plug @ 13,486' MD. Perf: 13,146'-13,441' MD. Acidized w/3k gals 10% acid. Frac'd w/6299 bbls 20# XL gel, 304,123# 20/40 White, & 97,300# 20/40 OilPlus.

#### Stage 9:

Set flow-thru plug @ 13,101' MD. Perf: 12,761'-13,056' MD. Acidized w/3k gals 10% acid. Frac'd w/6245 bbls 20# XL gel, 301,544# 20/40 White, & 99,043# 20/40 OilPlus.

#### Stage 10:

Set flow-thru plug @ 12,716' MD. Perf: 12,376'-12,671' MD. Acidized w/3k gals 10% acid. Frac'd w/6041 bbls 20# XL gel, 298,692# 20/40 White, & 55,544# 20/40 OilPlus.

#### Stage 11:

Set flow-thru plug @ 12,331' MD. Perf: 11,991'-12,286' MD. Acidized w/3k gals 10% acid. Frac'd w/6953 bbls 20# XL gel, 308,789# 20/40 White, & 103,823# 20/40 OilPlus.

### Stage 12:

Set flow-thru plug @ 11,964' MD. Perf: 11,586'-11,868' MD. Acidized w/3k gals 10% acid. Frac'd w/6330 bbls 20# XL gel, 313,134# 20/40 White, & 112,754# 20/40 OilPlus. RDMO frac crew & equipment.