Submit 1 Copy To Appropriate District Office	State of New		Form C- Revised July 18,		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and	Natural Resources	WELL API NO. 30-025-36480		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVAT		5. Indicate Type of Lease	- j	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St.		STATE FEE X		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NN	VI 8/303	6. State Oil & Gas Lease No. 311978	/	
87505 SUNDRY NOT	ICES AND REPORTS ON WE	ELLS	7. Lease Name or Unit Agreement Nam	ne	
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI	SALS TO DRILL OR TO DEEPEN O	R PLUG BACK TO A	Cambio 31	/	
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well X Other	HOBBS OCE	8. Well Number 001	/	
2. Name of Operator PPC Operating Company LLC	✓	MAY A F 2010	9. OGRID Number 288774	/	
3. Address of Operator		WIAT U 3 ZUIS	10. Pool name or Wildcat		
1500 Industrial Blvd., Ste. 304;	Abilene, TX 79602	DECENTER	Townsend;Permo Upper Penn		
4. Well Location	1000 0 0 1 N	KECEIAED	054		
	1230 feet from the No			ine	
Section 31	Township 15S  11. Elevation (Show whether	Range 35E	NMPM County Lea		
	4015 GR	DR, RAD, RI, OR, etc.,			
12. Check	Appropriate Box to Indica	te Nature of Notice,	Report or Other Data		
NOTICE OF IN	1	I SUB	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	INT TO PA	REMEDIAL WOR			
TEMPORARILY ABANDON	P&A NR X	COMMENCE DRI	The state of the s	×	
PULL OR ALTER CASING	P&A R	CASING/CEMEN	T JOB		
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM  OTHER:		OTHER:			
	oleted operations. (Clearly state		d give pertinent dates, including estimated	date	
of starting any proposed w	ork). SEE RULE 19.15.7.14 N		mpletions: Attach wellbore diagram of		
proposed completion or rec		Tarand TOC @ 0 1161			
1. RIH with open-ended tubing & spotted	150 sx cement @ 9,818 : WOC &	ragged TOC @ 9,116".			
2. Spotted 25 sx cement @ 7,250' 3. Spotted 75 sx @ 5.775': WOC & Taggs	ad TOC @ 5 581'. Snoke w/ Mayey	Brown: snotted 50 sy cem	ent & tagged TOC @ 5,581'; bottom 10 jts we	re full of	
cement; shut down overnight	id Toe @ 3,301, Spoke w/ Maxey	brown, spotted 30 sx cerns	and a tagged 100 @ 3,301 , bottom 10 jts we	e full of s	
4. Spotted another 50 sx cement at 5,57	5' & tagged TOC @ 4,923'				
		ed to EOPS; squeezed 13 bb	ols cement into squeeze holes leaving 3 bbls c	ement in	
5 1/2" casing; tagged TOC @ 4,778'.; s	poke w/ Maxey Brown; respotted	25 sx cement from 4,522' t	0 4,778'.		
6. Perfed @ 2,950' & pumped 30 sx cem	ent; squeezed 5 bbls cement into 8	3 5/8" casing, leaving 2 bbl	cement in 5 1/2" casing; tagged TOC @ 2,656	'; spoke v	
Maxey Brown & he advised depth was go	od.				
7. Perfed @ 1,800' & pumped 30 sx cem			ed depth was okay.		
8. Perfed @ 550' & pumped 150 sx ceme	nt; circulated 15 sx out the 8 5/8"	casing.			
Sand Date: 05 /45 /2007	Dia Dalas	os Deter 05 /00 /000			
Spud Date: 05/15/2007	Rig Releas	se Date: 05/23/200	1		
I hereby certify that the information	above is true and complete to	the best of my knowledg	e and belief.		
^ 4		,			
SIGNATURE ana orra	berry TITLE	Office Administrator	DATE_ 05/04/2016		
Type or print name Jana Spraberry	E-mail ad	dress: jspraberry@plan	tationpetro.com PHONE: 325-267-6046		
For State Use Only	C .	71 701		rain in	
APPROVED BY: Wall	ALL TITLE ?	P.E.S.	DATE 05/09/20	016	
Conditions of Approval (if any):	TITLE_		DATE		

WELL:

Cambio 31 #1

PPC Operating Co., LLC

**DAILY OPERATIONS** 

FIELD:

Facilities AFE Number Facilities AFE Amount

100146 \$160,000

PTD:

COUNTY/STATE:

Lea/NM

TOTAL AFE:

\$160,000

LOCATION:

**ELEVATION (RKB):** 

API #:

30-025-36480

SERIAL NO: SPUD DATE:

**OBJECTIVE:** JOB NAME:

Oct 10 2013

10-9-13 Enviromental Clean-up &

Repair

CONTRACTOR/RIG#:

RIG SUPERVISOR:

Richard Ouintana

FW:

0.0

0.0

PRESENT OPERATIONS:

MISI 4-Frac tanks

Arrived on location. Hold safety meeting,;MI Gandy trucking set in 4-500 bbl frac tanks;RU flow line from 5.5" csg valve to frac tanks. Open csq valve set choke on a 30/64" well flowing 80-85 bbls PH w/400 psi. Turned well over to

flow back hand,

ACTIVITY PLANNED:

MIRU Pulling unit POOH w/rods & Pump

DAILY JOB COST:

\$2,425

TOTAL JOB COST:

\$2,425

TOTAL WELL COST:

\$24,845

Oct 11 2013 RIG SUPERVISOR: Richard Quintana

FW:

PRESENT OPERATIONS: Dig out cellar & POOH w/Rods & Pump

Road rig w/crew to location. From Midland Texas. Well was flowing w/380 psi up the 5.5" csg. well flowed back 1,480 bbls. Of salty water in 18 hrs.;Dig out cellar down to 8-5/8" csg valve. Plumb riser up to surface installed 2" valve at surface. Open 8-5/8" csg valve it also showed 380 psi.;MIRU Red Diamond well service. SITP-40 psi. bleed tbg pressure down. Unhang well LD PR. RU Rod Stripper. Unseat pump.;POOH w/7/8" x 4' x 4' x 4' x 8' subs. 139-7/8" rods. 254-3/4" rods. 8-1.5" Kbars. 1-7/8" x 4' sub w/SRG. 7/8" x 1' LS. 26 K shear tool. 2.5" x 1.5" x 24' MHDP, Secure well SDFN,

**ACTIVITY PLANNED:** 

Kill the flow & POOH w/tbg.

DATLY TOR COST.

\$5,550

TOTAL JOB COST:

\$7,975

TOTAL WELL COST:

\$30,395

Oct 12 2013

RIG SUPERVISOR:

Richard Quintana

FW:

0.0

PRESENT OPERATIONS:

Pump 12# mud kill water flow NU BOP. POOH w/tbg

Arrived on location. Hold safety meeting.;SITP-0 psi. 5.5" CP-380 psi. Flowing at 80-90 bpm SI 8-5/8" CP-460 psi. MIRU Globe reverse unit. Bleed 8-5/8" csg down to 0-psi. in 5-10 sec. The pressure on 5.5" csg didn't change,;Hooked onto 5.5" csg. pump 30 bbls of 10# brine water pressure drop down to 320 psi. Shut down unable to kill the flow. MI unload 160 bbls. of 12# mud into frac tank. Pumped 70 bbls of 12# mud the 5.5" csg. Casing went on a vacuum, NDWH NU 3K BOP.; Work tbg and attempt to release TAC w/no success. Worked tbg while waiting on wireline truck,;MIRU Rotary wireline services. RIH w/CCL and free point tool. Found top of TAC@9,867' by wireline depth. Tbg showed to be 100% stuck @9,863'. 35% stuck@9,853'. and 100% free @9,690'. POOH w/free point tool. MURIH w/chemical cutter. Got on depth cut tbg @9,818'. 1-1/2 jt above TAC. Well started flowing up the 2 7/8" tbg. Pulled wireline up to surface open 2" valve on pack off it was flowing at 3/4-1 bpm. all water, RURUP to 2" valve pumped 20 bbls of 12# mud put tbg on vacuum. RDWL;Tallied OOH w/60 jts of 2 7/8" 6.5# N80 EUE 8rd tbg. Secure well SDFWE,

ACTIVITY PLANNED:

Continue POOH w/tbg & TIH w/Plug & Pkr to isolate hole on csg,

DAILY JOB COST:

\$33,160

TOTAL JOB COST:

\$41,135

TOTAL WELL COST:

\$63,555

WELL:	Cambio 31 #1					
Oct 15 2013	RIG SUPERVISOR:	Richard Quintana	- "	FW:	0.0	
	PRESENT OPERATIONS:	RIH w/plug&packer Lo				
	Arrived on location. Hold safety meeting. SITP-a slight blow. SI 5.5" CP-0 psi. SI 8 5/8" CP-60 psi. Bleed 8 5/8" csg down to 0-psi in 5 sec. rec about a gallon full of dark water,;Continue talling OOH w/236 more jts of 2 7/8" 6.5# N80 tbg. Got out w/a total of 296 jts and half of the 297 th jt. 8 5/8" csg started flowing at 3-4 bpm @320-psi flowed back about 1,000 bbls. of dark dirty water shut 8 5/8" csg valvre in,;MURIH w/2 3/8" X 5.5" RBP. ON&OFF tool. 2 3/8" X 5.5" pkr. 2 3/8" X 2 7/8" XO. 2.5" SN and 196 jts of 2 7/8" 6.5# N80 tbg. Tagged tight spot@5,624'. fell through. Set RBP@6,480'. Pulled 2 jts. set pkr@6,424' w/194 jts in. Load tbg w/4 bbls of 10# brine water. Pressure test tools to 2K. Lost 300# in 3.5 min. Unset pkr RIH w/1 jt Re-set pkr@6,466'. w/195 jts in. Load tbg w/2 bbls. Pressure test tools to 2K. Lost 300# in 3.5 min;Open bypass on pkr. Drop SV pump SV down w/30 bbls of 10# brine water. Seat SV in 2.5" SN. Pressure test 2 7/8" tbg to 2K. Lost 350# in 3 min. Reverse unit operator found elaking valve on his pump. Replace valve test tbg to 2k. No leak off.;MURIH w/fishing tool on sandline latched onto SV Open bypass on SV. To equalize fluid. POOH w/SV;Reset pkr@6,466' w/195 jts in. Test tools to 2K. OK. Unset pkr POOH w/19 jts. Set pkr@5,829'. w/176 jts in. Load tbg. PT csg to 2K from 5,829'-6,466'. Test OK. unset pkr POOH w/8 more jts to get above tight spot Set pkr@5569'. w/168 jts in. Load tbg w/3 bbls. Got injection rate of 3.5 bpm @500 psi. Pumped 15 bbls. Hooked onto 5.5" csg load csg w/40 bbls of 10# brine water but couldn't pressure up on csg. It was taking fluid. Secure well SDFN, Hauled 9 loads of water to disposal					
	ACTIVITY PLANNED:	Continue looking for h	ole & Run csg inspection log			
	DAILY JOB COST:	\$12,088	TOTAL JOB COST:	\$53,223		
	TOTAL WELL COST:	\$75,643				
Oct 16 2013	RIG SUPERVISOR:	Richard Quintana		FW:	0.0	
	PRESENT OPERATIONS:	Continue looking for h	ole in csg. Run csg inspection	log.		
	pkr@5241' w/158 jts in the hounable to load csg. Unset pkr. pump 10 bbls of 10# brine wi 1,000 psi test good. Release p. 5.5" csg. Pump 40 bbls of 12# valve and left it flowing into fi 6.5# N80 tbg. LD 2 3/8" X 5.5 6480';MIRU Capitan wireline tw/40 ARM Multi Sensor Calipe 4,650' Possible Parted Collar (N8) the ack bill strips. Shut the	POOH w/2 jts set pkr@5,3 ater. SD ISIP-0 psi. Unset p pressure. Unset pkr. POOH if mud down the csg to kill if act tanks. 5.5" csg went on is" pkr. Good csg from surfaruck. MURIH w/GR/CCL down the clectro Magnetic Thicknet @5582' and a Possible Hole	71'. L&T csg to 500 psi. Got is kr POOH w/1 jt Reset;Packer w/60 jts of 2 7/8" 6.5# N80 to the flow SD well did not go or a slight vacuum. Continue PCcce-5338' Bad csg from 5338'-wn to 6482' Log up to 4800' stool down to 6,482' Log an @5410'. POOH w/tool. RDWI	njection rate 2 bp @5,338'. w/161 jt bg. Well started to a vacuum. Open OOH w/101 more 5896' Good csg fr w/GR/CCL. POOH d run casing Insp _;RIH w/60 jts of	om @650 psi ss in L&T csg to o flow out of a 8 5/8" csg jts of 2 7/8" om 5896- w/GR. MURIH ection up to 2 7/8" 6.5#	
	N80 tbg. as kill string. Shut th		rted flowing out the 5.5" csg	. Secure well. SDF	-N,	
	ACTIVITY PLANNED:	WOO	TOTAL 100 000T	+50.550		
	DAILY JOB COST:	\$16,430	TOTAL JOB COST:	\$69,653		
Oct 17 2012	TOTAL WELL COST:	\$92,073		F)M:	0.0	
Oct 17 2013	RIG SUPERVISOR: PRESENT OPERATIONS:	Richard Quintana TIH w/ON&OFF tool		FW:	0.0	
	Arrived on location. Hold min safety meeting. SITP-65 psi. SI 5.5" CP-100 psi. SI 8 5/8" CP-480 psi.;WOO;Bled down tbg pressure it started flowing pump 10 bbls of 12# mud to kill the flow. Open 8 5/8" csg valve on a 30/64" choke 5.5" csg went on a slight vacuum,;POOH w/60 jts of 2 7/8" 6.5# N80 tbg. MURIH w/Retrieving head and 196 jts of 2 7/8" 6.5# N80 tbg. Tagged bad spot in casing @5,624' by tbg tally. Latched onto RBP@6480'.;Unset RBP well started flowing out of tbg and 5.5" csg and 8 5/8" csg. Pumped 30 bbls of mud down 5.5" csg. POOH w/32 jts w/5.5" csg running over well started flowing harder out of 5.5" csg and tbg. Pumped mud unable to put well on a vacuum Ordered 150 bbls of 13# mud it will be on location in the morning. Secure well SDFN,					
	ACTIVITY PLANNED:	Mud up & Continue PO				
	DAILY JOB COST:	\$9,538	TOTAL JOB COST:	\$79,191		
	TOTAL WELL COST:	\$101,611	10111230200011	4,3/232		
Oct 18 2013	RIG SUPERVISOR:	Richard Quintana	Total Control	FW:	0.0	
Oct 18 2013	RIG SUPERVISOR: PRESENT OPERATIONS:	Richard Quintana Mud up Finish POOH	v/tbg&RBP	FW:	0.0	
Oct 18 2013		Mud up Finish POOH of the meeting. SITP-150 psi SITP-150	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down to I flowing shut csg valve; Wait bbls of 13# mud down the 8 8/8" X 5.5" RBP.; Tallied PU RI 3/8" IF X 3-3/4" X 1-1/2" Jar	475 psi. Unload : the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the till w/4-11/16" Ov s. 6-3-1/2" DCs. 2	150 bbls of 13# ped 75 bbls s of 13# mud flow on the 8 ershot w/2- 2 3/8" X 3-3/4"	
Oct 18 2013	PRESENT OPERATIONS:  Arrived on location. Hold safe mud into frac tank; Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.; CC 5/8" csg.; POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/X 1-1/2" Excelerator. 3-5/8" X	Mud up Finish POOH of the meeting. SITP-150 psi SITP-150	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I flowing shut csg valve;Wait bbls of 13# mud down the 8 bls of 5.5" RBP.;Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le	475 psi. Unload : the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the till w/4-11/16" Ov s. 6-3-1/2" DCs. 2	150 bbls of 13# ped 75 bbls s of 13# mud flow on the 8 ershot w/2- 2 3/8" X 3-3/4"	
Oct 18 2013	PRESENT OPERATIONS:  Arrived on location. Hold safe mud into frac tank; Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.; Cc 5/8" csg.; POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/X 1-1/2" Excelerator. 3-5/8" X Secure well SDFN,	Mud up Finish POOH of the meeting. STTP-150 psi SI pown. Pumped 30 bbls of 13 of mud. 8 5/8" csg was still ontinue pumping 115 more 2 7/8" 6.5# N80 tbg. LD 2 34" X 1-1/2" Bumper Sub. 2-1-1/2" Top Sub. and 140 j	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I flowing shut csg valve;Wait bbls of 13# mud down the 8 bls of 5.5" RBP.;Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le	475 psi. Unload : the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the till w/4-11/16" Ov s. 6-3-1/2" DCs. 2	150 bbls of 13# ped 75 bbls s of 13# mud flow on the 8 ershot w/2- 2 3/8" X 3-3/4"	
Oct 18 2013	PRESENT OPERATIONS:  Arrived on location. Hold safe mud into frac tank;Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.;Cc 5/8" csg.;POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/X 1-1/2" Excelerator. 3-5/8" X Secure well SDFN, ACTIVITY PLANNED:	Mud up Finish POOH of the property meeting. STTP-150 psi SI pown. Pumped 30 bbls of 13 of mud. 8 5/8" csg was still on the pumping 115 more 2 7/8" 6.5# N80 tbg. LD 2 3 4" X 1-1/2" Bumper Sub. 2-1-1/2" Top Sub. and 140 j	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I flowing shut csg valve; Wait bbls of 13# mud down the 8 \$/8" X 5.5" RBP.; Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le	475 psi. Unload: the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the IH w/4-11/16" Ov s. 6-3-1/2" DCs. 2 ave the end of FT	150 bbls of 13# pped 75 bbls s of 13# mud flow on the 8 ershot w/2-2 3/8" X 3-3/4" (@4,871'.	
	PRESENT OPERATIONS:  Arrived on location. Hold safe mud into frac tank;Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.;Cc 5/8" csg.;POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/ X 1-1/2" Excelerator. 3-5/8" X Secure well SDFN,  ACTIVITY PLANNED:  DAILY JOB COST:  TOTAL WELL COST:  RIG SUPERVISOR:	Mud up Finish POOH of the property meeting. SITP-150 psi SI pown. Pumped 30 bbls of 13 of mud. 8 5/8" csg was still ontinue pumping 115 more 2 7/8" 6.5# N80 tbg. LD 2 3 4" X 1-1/2" Bumper Sub. 2 1-1/2" Top Sub. and 140 j  RIH w/fishing tool&DC \$35,198 \$136,809  Richard Quintana	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I I flowing shut csg valve;Wait bbls of 13# mud down the 8 8/8" X 5.5" RBP.;Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le	475 psi. Unload: the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the IH w/4-11/16" Ov s. 6-3-1/2" DCs. 2 ave the end of FT	150 bbls of 13# ped 75 bbls s of 13# mud flow on the 8 ershot w/2- 2 3/8" X 3-3/4"	
	PRESENT OPERATIONS: Arrived on location. Hold safe mud into frac tank;Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.;Cc 5/8" csg.;POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/X 1-1/2" Excelerator. 3-5/8" X 5ecure well SDFN, ACTIVITY PLANNED: DAILY JOB COST: TOTAL WELL COST: RIG SUPERVISOR: PRESENT OPERATIONS:	Mud up Finish POOH of the property meeting. SITP-150 psi SI Down. Pumped 30 bbls of 13 of mud. 8 5/8" csg was still of mud. 8 5/8" csg was still onlinue pumping 115 more 2 7/8" 6.5# N80 tbg. LD 2 3 4" X 1-1/2" Bumper Sub. 2-1-1/2" Top Sub. and 140 j  RIH w/fishing tool&DC \$35,198 \$136,809  Richard Quintana  RIH w/overshot 3.5"	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I flowing shut csg valve;Wait bbls of 13# mud down the 8 8/8" X 5.5" RBP.;Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le cs and tbg  TOTAL JOB COST:	475 psi. Unload : the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the IH w/4-11/16" Ov s. 6-3-1/2" DCs. 2 ave the end of FT \$114,389	150 bbls of 13# pped 75 bbls s of 13# mud flow on the 8 ershot w/2-2 3/8" X 3-3/4" @4,871'.	
Oct 18 2013  Oct 19 2013	PRESENT OPERATIONS:  Arrived on location. Hold safe mud into frac tank;Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.;Cc 5/8" csg.;POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/X 1-1/2" Excelerator. 3-5/8" X Secure well SDFN,  ACTIVITY PLANNED:  DAILY JOB COST:  TOTAL WELL COST:  RIG SUPERVISOR:  PRESENT OPERATIONS:  Arrived on location, hold safet continue RIH w/ 2-7/8" tbg ta 9818' run in real slow kept tag @ 9867' pulled on 2-7/8" tbg move down or up, released fis stand back 6-3-1/2" DC's LD j	Mud up Finish POOH of the process of	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I flowing shut csg valve; Wait bbls of 13# mud down the 8 8/8" X 5.5" RBP.; Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le Cs and tbg  TOTAL JOB COST:  DC's  blow SI 5.5" CP 0 psi SI 8-5/4 190 jts plus BHA from 6504' latched on to fish @ 9818' wumped down on tbg w/ bum w/ 291 jts of 2-7/8" 6.5# N80	475 psi. Unload : the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the IH w/4-11/16" Ov s. 6-3-1/2" DCs. 2 ave the end of FT  \$114,389  FW: G" CP a slight blow down to the top / 10' in on jt 291; per sub unable to	150 bbls of 13# ped 75 bbls s of 13# mud flow on the 8 ershot w/2- 2 3/8" X 3-3/4" @4,871'.  0.0  v open BOP of the fish @ jarred on TAC get TAC to	
	PRESENT OPERATIONS:  Arrived on location. Hold safe mud into frac tank;Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.;Cc 5/8" csg.;POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/X 1-1/2" Excelerator. 3-5/8" X Secure well SDFN,  ACTIVITY PLANNED:  DAILY JOB COST:  TOTAL WELL COST:  RIG SUPERVISOR:  PRESENT OPERATIONS:  Arrived on location, hold safet continue RIH w/ 2-7/8" tbg ta 9818" run in real slow kept tag @ 9867" pulled on 2-7/8" tbg move down or up, released fit stand back 6-3-1/2" DC's LD j ACTIVITY PLANNED:	Mud up Finish POOH of the process of	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I flowing shut csg valve; Wait bbls of 13# mud down the 8 8/8" X 5.5" RBP.; Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le Cs and tbg  TOTAL JOB COST:  DC's blow SI 5.5" CP 0 psi SI 8-5/4 190 jts plus BHA from 6504' latched on to fish @ 9818' woumped down on tbg w/ bum w/ 291 jts of 2-7/8" 6.5# N80 ot secured well SDOWE	475 psi. Unload : the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the : the W4-11/16" OV s. 6-3-1/2" DCs. 2 ave the end of FT \$114,389  FW:  3" CP a slight blow down to the top / 10' in on jt 291; per sub unable to 0 tbg LD top sub a	150 bbls of 13# ped 75 bbls s of 13# mud flow on the 8 ershot w/2- 2 3/8" X 3-3/4" @4,871'.  0.0  v open BOP of the fish @ jarred on TAC get TAC to	
	PRESENT OPERATIONS:  Arrived on location. Hold safe mud into frac tank;Bled tbg d down the 8 5/8" csg. Run out Unload mud into frac tank.;Cc 5/8" csg.;POOH w/164 jts of 7/8" grapple. 2-3/8" IF X 3-3/X 1-1/2" Excelerator. 3-5/8" X Secure well SDFN,  ACTIVITY PLANNED:  DAILY JOB COST:  TOTAL WELL COST:  RIG SUPERVISOR:  PRESENT OPERATIONS:  Arrived on location, hold safet continue RIH w/ 2-7/8" tbg ta 9818' run in real slow kept tag @ 9867' pulled on 2-7/8" tbg move down or up, released fis stand back 6-3-1/2" DC's LD j	Mud up Finish POOH of the process of	5.5" CP 400 psi SI 8 5/8" CP # mud. Pump 90 bbls down I flowing shut csg valve; Wait bbls of 13# mud down the 8 8/8" X 5.5" RBP.; Tallied PU R: 3/8" IF X 3-3/4" X 1-1/2" Jar ts of 2 7/8" 6.5# N80 tbg. Le Cs and tbg  TOTAL JOB COST:  DC's  blow SI 5.5" CP 0 psi SI 8-5/4 190 jts plus BHA from 6504' latched on to fish @ 9818' wumped down on tbg w/ bum w/ 291 jts of 2-7/8" 6.5# N80	475 psi. Unload : the 5.5" csg. pum on 150 more bbls 5/8" csg. Kill the IH w/4-11/16" Ov s. 6-3-1/2" DCs. 2 ave the end of FT  \$114,389  FW: G" CP a slight blow down to the top / 10' in on jt 291; per sub unable to	150 bbls of 13# ped 75 bbls s of 13# mud flow on the 8 ershot w/2- 2 3/8" X 3-3/4" @4,871'.  0.0  v open BOP of the fish @ jarred on TAC get TAC to	

WELL: Cambio 31 #1 Oct 22 2013 RIG SUPERVISOR: Richard Quintana FW: 0.0 LD DC's. RIH w/tbg & Rods LD 93-7/8" rods PRESENT OPERATIONS: Arrived on location, Hold safety meeting, SI 5.5" & 8 5/8 CP-0 psi,:WOO:RIH w/6-3.5" DC's, POOH and LD the DC's.;MURIH w/2.5" SN. Then 294 jts of 2 7/8" 6.5# N80 EUE 8rd tbg. Leave EOT@9,736';RU equipment to run rods. MURIH w/2.5" Nogo 254-3/4" rods. 139-7/8" rods. Out of the derrick. Set 3 old its of 2 7/8" tbg across to LD rods,;POOH LD 93-7/8" rods. PU stuffing box and polish rod. Secure well SDFN. ACTIVITY PLANNED: Finish LD rods DAILY JOB COST: \$7,900 TOTAL JOB COST: \$135,553 TOTAL WELL COST: \$157,973 Oct 23 2013 RIG SUPERVISOR: Richard Quintana FW: 0.0 PRESENT OPERATIONS: LD the rest of the rods Arrived on location. Hold safety meeting. SITP-a slight blow. SI 5.5" & 8 5/8" CP-0 psi.;LD polish rod. NU rod stripper. POOH LD 46-more 7/8" rods. Then 254-3/4" rods. 8-1.5" Kbars.;MI Double R forklift. Move all rods to the edge of location. Set in pipe racks clean up around location. SDFN ACTIVITY PLANNED: Start to P&A well DAILY JOB COST: \$4,738 TOTAL JOB COST: \$140,291 TOTAL WELL COST: \$162,711 Oct 24 2013 RIG SUPERVISOR: Richard Ouintana FW: 0.0 RU Cement Specialists spot a 50 sx plug @9818' PRESENT OPERATIONS: Arrived on location. Hold safety meeting. SITP-0 psi. SI 5.5" & 8-5/8" CP-0 psi. MIRU Cement Specialists; Roll mud around in frac tank.;RIH w/2 jts put the EOSN@9818' w/a total of 296 jts of 2 7/8" 6.5# N80 tbg. Test lines to 2K OK-Pumped 65 bbls of 12# mud brk circulation. SD Mixed cmt pump 1 bbl of FW spacer pump a 50 sx plug of class H cmt @2.5 bpm @600 psi. And displace w/53 bbls of 13# mud. Spot plug@9818', POOH w/100 jts to 6489' tbg was pulling wet.; Hooked up to 5.5" csg. Load w/26 bbls of mud. Unable to reverse out. Hooked on to tbg. Pressure up on tbg to 1500 psi tbg was plugged up.; Continue POOH w/172 more jts of 2 7/8" 6.5# N80 plugged tbg. LD the Last 24 jts they were plugged w/cmt.; Well started flowing up the 5.5" csg. Hooked up to csg pump 65 bbls of mud to kill the flow.:MURIH w/OE 2-7/8" perf sub 2.5" SN. and 276 jts of 2-7/8" 6.5# N80 tbg. Tag top of cmt@9116' w/10' in on jt #276 by tbg tally, we should have tagged at around 9300' with the amount of cement that we pumped the only thing I can think of what happened is that when we were pumping the cement we might have charged up the perforations and that's why it pushed the cement up so high and plugged up the tbg.; POOH LD 2 jts and stand back 114 jts. LTEOPS @5303' w/160 jts in Got above the bad csg. Secure well SDFN, ACTIVITY PLANNED: Continue plugging well. DAILY JOB COST: \$10,788 TOTAL JOB COST: \$151,079 \$173,499 TOTAL WELL COST: Oct 25 2013 RIG SUPERVISOR: Richard Quintana FW: 0.0 PRESENT OPERATIONS: Spot cmt plugs Arrived on location. Hold safety meeting, SITP-a slight blow SI 5.5" & 8-5/8" CP-0 psi.;Roll the mud. RIH w/59 its of 2 7/8" 6.5# N80 tbg. Set EOPS@7250' w/a total of 219 jts in & 83 jts out. RU cmt trucks pump 20 bbls of mud to break circulation. Mix cmt. Pump 3 bbls of FW spacer switch to cmt. Pump 25 sx of class H. 15.6# 1.18 yield cmt @800 psi @2.5 bpm. 2 bbls of FW. Then displaced w/38.4 bbls of mud spot plug @7250' SD.; POOH LD 45 jts of 2 7/8" 6.5# N80 tbg. Leave EOPS@5775' w/174 jts in & 128 jts out.; Pump 20 bbls of mud to break circulation. Mix cmt pump 2 bbls of FW spacer switch to cmt. Pump 75 sx of class H cmt. @400 psi. @2.5 bpm. Then pump 1 bbl of FW & displaced w/27.9 bbls of mud. Spot plug @5775' SD. Tbg & 8-5/8" csg went on a vacuum. POOH LD 54 jts & stand back 30 more jts. Leave the EOPS@2974' w/90 jts in & 212 jts out. WOC from 10:30 am -14:30 pm;WOC to tag;Open well fluid was running over the BOP. RIH w/79 jts out of the derrick. Tag cmt @5581' w/16' in on jt#169 LD jt#169 put the EOPS@5575' w/168 jts plus a 10' sub. Should have tagged @5173' Lost 408' of cmt.Talk to Maxi Brown w/OCD He said to pump 50 more sx of cmt; Hooked up to tbg. Pump 15 bbls of mud tbg pressured up to 1500 psi. Bled pressure off. TOOH w/10' sub & 168 jts of 2 7/8" 6.5# N80 tbg. LD the bottom 10 jts. They were full of soft cmt. Cement got inside tog while RIH to tag. Never felt nothing until we tagged up at 5581'. Secure well SDFN, ACTIVITY PLANNED: Continue P&A well DAILY JOB COST: \$21,313 TOTAL JOB COST: \$172,392 TOTAL WELL COST: \$194,812 Oct 26 2013 RIG SUPERVISOR: Richard Ouintana 0.0 PRESENT OPERATIONS: Pump plug mud to kill water flow. Unable to kill flow

Arrived on location. Hold safety m bled down pressure well started f RU Cement pump truck to 5.5" cs 1000 psi. 5min-980 psi. Bled csg to get 13# Kill mud. They couldn' ACTIVITY PLANNED:	lowing w/190 psi. Unloadii gg valve. Pump 120 bbls of down into frac tank well st t get mud ready till late in	ng 7-8 bbls of water pm. Flo f plug mud @1 bpm @1100 carted fowing w/190 psi. Shu	wed back 120 bt psi to kill the flow it csg valve in.;C	bls. Shut csg. w SD ISIP-	Shut csg. D ISIP-			
DAILY JOB COST:	\$3,925	TOTAL JOB COST:	\$176,317					
TOTAL WELL COST:	\$198,737							
RIG SUPERVISOR:	Richard Quintana		FW:	0.0				
PRESENT OPERATIONS:	Pump 50 sx cmt plug & s	spot@5575'						
Arrived on location. Hold safety m 13# kill mud. RU Cement pump t psi;,MURIH w/2-7/8" X 4" PS. 2.5' @5,575' RU Cement to tbg pump Pump 1 bbl of FW spacer switch of was on a vacuum. RD Cement lin- out.;Reverse out 25 bbls of mud.	ruck to 5.5" csg. Pumped: " SN. then 168 jts of 2-7/8 20 bbls of 13# mud break over pump 50 sx of cmt @ e off of tbg.;POOH w/54 st	110 bbls of mud down the co " 6.5# N80 tbg. plus a 2-7/8 corculation. Mix 50 sx of cla 2.5 bpm @400 psi. Displace	sg. Pressure drop 8" X 10' sub. Lea ss H 15.6# 1.18 d w/28.4 bbls of	ye the EOPS yield cmt. mud. SD tbg				
ACTIVITY PLANNED:	RIH & Tag cmt plug							

TOTAL JOB COST:

\$197,147

\$20,830

\$219,567

Oct 27 2013

DAILY JOB COST: TOTAL WELL COST:

WELL:	Cambio 31 #1						
Oct 29 2013	RIG SUPERVISOR:	Richard Quintana		FW:	0.0		
	PRESENT OPERATIONS:	Perf squeeze holes @4	810' & Pump 80 sx of cmt				
	Arrived on location. Hold safet w/90 jts of 2 7/8" 6.5# N80 th said that it was good to conting the continuous to the continuous to the continuous that it was good to continuous the continuous to the continuous that it was good minimum to the continuous that it was good that the continuous that it was good to the continuous that it was good to the continuous that it was good to the continuous that	ng. Tag cmt @4,923" by tbg nue w/the plugging. POOH volume w/the plugging. POOH volume w/the plugging. POOH volume w/the plugging. POOH volume w/the plugging w/the plugging w/the w/the plugging w/the w/th	tally w/10' in on jt #150. Ta v/7 jts. Leave the EOPS@4,7 v/1-11/16" CCL/1-11/16" per depth perforate 6 squeeze ha 8" valve. Pump on tbg broked d was circulating out the 8-5 sx of cmt. Displaced cmt to nto Squeeze perfs w/15.6 ma '8" 6.5# N80 tbg. Leave the mud. Secure well SDFN,	iked to Maxi Brov (52' by tbg tally, S f gun set w/6 sho bles @4810'. POO e squeeze perfs @ (/8" csg. Mix 80 so the EOPS w/11.4 ore bbls of mud @	n w/OCD. He hut BOP test ts. Tag top of H RD WL.;RU 900 psi. Got of class H bbls of mud. 22 bpm @1,00		
	TOTAL WELL COST:	\$229,317					
Oct 30 2013	RIG SUPERVISOR:	Richard Quintana		FW:	0.0		
	PRESENT OPERATIONS:	Plugging well					
	4,778'-4522'.;RD Cement pump truck. POOH LD 60 jts of 2 7/8" 6.5# N80 tbg. Leave the EOPS@2784' by tbg tally. R Cement pump truck to tbg. Break circulation w/10 bbls of mud shut 5.5" CV Leave 8 5/8" CV open pressure test 5.5" csg to 800 psi. Test good for 10 min. Release pressure,;RU Capitan wireline RIH w/1-11/16" CCL/1-11/16" perf gun set w/6 shots. Fell out of PS@2785' by WL depth. Got on depth perforate @2,950'. POOH w/WL.;RU Cement pump truck to tbg. Load 5.5" csg w/15 bbls. of plug mud shut 5.5" CV Leave 8-5/8" CV open got injection rate of 2 bpm @800 psi'. pump 20 bbls. SD Mud was flowing back out of the tbg @.5 bpm. Pump 80 bbls of plug mud and displace heavy mud out of the 8-5/8" csg. Mix cmt. Pump 2 bbls of FW spacer @2 bpm @300 psi. Pump 30 sx of 14.8# 1.32 yield class C cmt. w/2% cacl. @2 bpm @300 psi. Displaced w/1 bbl of FW and 17 bbls of plug mud @2 bpm @200 ps Squeeze 5 bbls of cmt into 8-5/8" csg;Leave 2 bbls of cmt in 5.5" csg. POOH w/84 jts of 2 7/8" 6.5# N80 tbg. Securi						
	well SDFN,						
	ACTIVITY PLANNED:	Continue plugging wel					
	DAILY JOB COST:	\$9,559	TOTAL JOB COST:	\$216,456			
	TOTAL WELL COST:	\$238,876	15				
Oct 31 2013	RIG SUPERVISOR:	Richard Quintana		FW:	0.0		
	PRESENT OPERATIONS:  Arrived on location. Hold safe	Finish plugging well	Desertion		-		
	TOC@2,656'. Talk to Maxi Brown w/OCD. He said that was good. POOH LD 33 jts. Leave EOPS@1,707 by tbg tally. w/51 jts in the hole. RU Cement pump truck. Shut 5.5" CV Leave 8-5/8" CV open test 5.5" csg to 500 psi. OK. Release pressure.;MIRU Capitan wireline. RIH w/1-11/16" CCL/1-11/16" gun w/6 shots. Fell out the end of tbg @1,707' by WI Depth. Got on depth perforate @1,800'. POOH w/WL.;Ru Cement pump truck. Load csg break circulation. out the 8-58" CV got Injection rate 2 bpm @500 psi pump 10 bbls of mud SD. Mix cmt pump 2 bbls FW spacer. Pump 30 sx of class C 14.8# 1.32 yield cmt w/2% Cacl @2 bpm @300 psi. Pump 1 bbl of FW. Displaced cmt w/9.2 bbls of mud @1.5 bpm @100 psi. SD;POOH w/51 jts of tbg. WOC.;RIH w/2 7/8" X 4' PS. 2.5" SN. and 49 jts of 2 7'8" 6.5# N80 tbg. Tat TOC@1,629" by tbg tally. Talk to Maxi Brown w/OCD OK- POOH LD 37 jts of tbg. Leave EOPS@398' by tbg tally. Tes 5.5" csg to 500 psi test good Release pressure.;RU wireline RIH w/1-11/16" CCL/1-11/16" Gun w/6 shots. Fell out of the EOT@408' by WL depth. Got on depth perforate @550'. POOH and Release WL. Load csg w/3 bbls break circulation. Got injection rate 2 bpm @e300 psi. SD. POOH LD the last 12 jts,;RD work floor. Put cap flange on well. RU cmt pump truck to cap flange. Mix cmt pump 5 bbls of FW spacer @1.5 bpm @700 psi. Pump 150 sx of class C cmt w/2% cacl. @1 bpm @400 psi. Circulate 15 sx out the 8-5/8" csg. Wash up. Secure Well SDFN,						
	ACTIVITY PLANNED:	Check TOC Rig down					
	DAILY JOB COST:	\$26,003	TOTAL JOB COST:	\$242,459			
W - 2 G	TOTAL WELL COST:	\$264,879					
Nov 1 2013	RIG SUPERVISOR:	Richard Quintana	A STATE OF THE STA	FW:	0.0		
	PRESENT OPERATIONS:	Check cmt level RD Pu	lling Unit				
	Arrived on location. Hold safety meeting. SI 5.5" & 8-5/8" CP-0 psi., Removed cap flange looked inside 5.5" csg. Top of cmt was about 4-5' from surface. Put cap flange back on well. Rig down. Red Diamond Well Service Rig #26 Pick up all trash. Road rig to EP/CII#16.						
	all trash. Road rig to ERCU#1	6					

Finish cleaning out frac tanks

TOTAL JOB COST:

\$288,080

\$45,621

\$310,500

ACTIVITY PLANNED:

DAILY JOB COST:

TOTAL WELL COST: