Submit 1 Copy To Appropriate District State of New Mexico	Form C-103 Revised August 1, 2011
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. Francis Dr.	WELL API NO.
District II - (575) 748-1283	30-025-34247
District III – (505) 334-6178	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 UEU 9 2016 Sonto Ec. NM 87505	STATE X FEE 6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	0. State Off & Gas Lease NO.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	LEA AQ STATE
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well X Gas Well 🗌 Other	8. Well Number
2. Name of Operator	9. OGRID Number
CIMAREX ENERGY CO. OF COLORADO	162683
3. Address of Operator 600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	10. Pool name or Wildcat PEARL SAN ANDRES, WEST
4. Well Location	
Unit Letter M : 990 feet from the SOUTH line and 990	feet from the WEST line /
	SE NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, e	
3,732' - GR	
12. Check Appropriate Box to Indicate Nature of Notic	e Report or Other Data
	IBSEQUENT REPORT OF:
	DRK ALTERING CASING DRILLING OPNS. P AND A X
DOWNHOLE COMMINGLE	
	_ PLUGGED AND ABANDONED 11/23/16.
 Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0 	and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60
 Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0 proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D
 Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0 proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0 proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. 60 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM); 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO SURF. X INSTALL DRY HOLE MARKER. 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM); 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO SURF. X INSTALL DRY HOLE MARKER. 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL 90 of wellbore only. Liability under ing restoration and completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. CPLATE TO SURF. X INSTALL DRY HOLE MARKER. 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL 90 of wellbore only. Liability under ing restoration and completion for Subsequent Report of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM); 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO SURF. X INSTALL DRY HOLE MARKER. 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D) N ALL ANNULUS; WELD ON STEEL 9 of wellbore only. Liability under ing restoration and completion for Subsequent Report of may be found on the OCD
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM); 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO SURF. X INSTALL DRY HOLE MARKER. Approved for Plugging bond is retained pend of the C-103, Specific Well Plugging, which the second se	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D) N ALL ANNULUS; WELD ON STEEL 9 of wellbore only. Liability under ing restoration and completion for Subsequent Report of may be found on the OCD
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM); 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO SURF. X INSTALL DRY HOLE MARKER. Approved for Plugging bond is retained pend of the C-103, Specific Well Plugging, which the second se	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL 90 of wellbore only. Liability under ing restoration and completion for Subsequent Report of nay be found on the OCD
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OPLATE TO SURF. X INSTALL DRY HOLE MARKER. Spud Date: MIRU: 11/19/16 Rig F 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL 90 of wellbore only. Liability under ing restoration and completion for Subsequent Report of nay be found on the OCD
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OPLATE TO SURF. X INSTALL DRY HOLE MARKER. Spud Date: MIRU: 11/19/16 Rig F 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL 90 of wellbore only. Liability under ing restoration and completion for Subsequent Report of nay be found on the OCD
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0 proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. OPLATE TO SURF. X INSTALL DRY HOLE MARKER. Spud Date: MIRU: 11/19/16 Rig F Approved for Plugging, which is web page under forms I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL g of wellbore only. Liability under ing restoration and completion for Subsequent Report of may be found on the OCD dge and belief. DATE: 11/28/16
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO SURF. X INSTALL DRY HOLE MARKER. Spud Date: MIRU: 11/19/16 Rig F Approved for Plugging, which web page under forms I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE DAVID A. EYLER Type or print name: DAVID A. EYLER 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL g of wellbore only. Liability under ing restoration and completion for Subsequent Report of may be found on the OCD dge and belief. DATE: 11/28/16
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple 0 proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM); 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. CPLATE TO SURF. X INSTALL DRY HOLE MARKER. Spud Date: MIRU: 11/19/16 Rig F Approved for Plugging, which is web page under forms Thereby certify that the information above is true and complete to the best of my knowled SIGNATURE TTTLE: AGENT Type or print name: DAVID A. EYLER E-mail address: deyler@milag 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D .) N ALL ANNULUS; WELD ON STEEL g of wellbore only. Liability under ing restoration and completion for Subsequent Report of may be found on the OCD dge and belief. DATE: 11/28/16 ro-res.com PHONE: 432.687.3033
 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple (proposed completion or recompletion. 11/21/16: SET 5-1/2" CIBP @ 5,700'; CIRC. WELL W/ PXA FLUID; PRES. TEST CS SXS. CMT. @ 5,700'-5,225'; PUMP 40 SXS. CMT. @ 3,500'; WOC. 11/22/16: TAG CMT. PLUG @ 3,167' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 1,8 BY OCD); MIX X CIRC. TO SURF. 60 SXS. CMT. @ 495'-3' (PERF BLM) 11/23/16: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. C PLATE TO SURF. X INSTALL DRY HOLE MARKER. Spud Date: MIRU: 11/19/16 Rig F Approved for Plugging, which web page under forms I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE DAVID A. EYLER Type or print name: DAVID A. EYLER 	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of GG. X CIBP TO 750# - HELD OK; PUMP 60 60'; WOC X TAG CMT. PLUG @ 1,605'(OK'D DN ALL ANNULUS; WELD ON STEEL g of wellbore only. Liability under ing restoration and completion for Subsequent Report of may be found on the OCD dge and belief. DATE: 11/28/16