	State of New Me	Form C-103					
Office <u>District I</u> – (575) 393-6161  1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283  811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178  1000 Rio Brazos Rd., Aztec, NM 84310  Santa Fe, NM 87505			WELL API NO.	evised August 1, 2011			
District II - (575) 748-1283	30-025-30960						
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87310 District IV – (505) 476-3460	5. Indicate Type of Leas STATE	se FEE 🔲					
<u>District IV</u> – (505) 476-3460	7505	6. State Oil & Gas Leas					
1220 S. St. Francis Dr., Santa Fe, NM 87505							
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSA	7. Lease Name or Unit	Agreement Name					
DIFFERENT RESERVOIR. USE "APPLICA	WEST LOVINGTON	N UNIT					
PROPOSALS.)  1. Type of Well: Oil Well   C	8. Well Number: 68						
2. Name of Operator		9. OGRID Number					
Chevron Midcontinent, L.P.  3. Address of Operator			241333 10. Pool name or Wildo	eat			
6301 DEAUVILLE BLVD, MID	LAND, TX 79706 RM.N3002		LOVINGTON UPP				
4. Well Location							
Unit Letter FV: 133							
Section 38 1	Township 17S  11. Elevation (Show whether DR,	Range 36E	NMPM	County Lea			
	3914' GR						
12 Charles		CNI	0.1 D				
12. Check Ap	opropriate Box to Indicate N	ature of Notice,	Report or Other Data				
NOTICE OF INT	SEQUENT						
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORLD TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI			INIT T	TO PA PMX			
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMEN			LING OF NO.L				
DOWNHOLE COMMINGLE				R			
OTHER:	П	OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat							
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.							
1. Call and notify NMOCD 24 hrs. before operations begin.							
1 Call and notify NMOC	D 24 hrs, before operation	ns hegin					
		ns begin.					
2. MIRU. NDWH. NU I	BOPE.		of cmt on top. Press	sure test casing			
<ol> <li>MIRU. NDWH. NU I</li> <li>Set CIBP@4,700',circ</li> </ol>	BOPE. ulate well w/9.5 ppg mud	and spot 25sx o		sure test casing.			
<ol> <li>MIRU. NDWH. NU I</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> </ol>	BOPE. ulate well w/9.5 ppg mud ' cement from 3,138'-2,93	and spot 25sx o	. (B.Salt)	sure test casing.			
<ol> <li>MIRU. NDWH. NU II</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> </ol>	BOPE. ulate well w/9.5 ppg mud ' cement from 3,138'-2,93 ' cement from 2,100'-1,90	and spot 25sx o 88', WOC&Tag 00', WOC&Tag	. (B.Salt) . (T.Salt)				
<ol> <li>MIRU. NDWH. NU II</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> </ol>	BOPE. ulate well w/9.5 ppg mud 'cement from 3,138'-2,93 'cement from 2,100'-1,90 x of Class "C" cement from	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surface	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surfac	ce)			
<ol> <li>MIRU. NDWH. NU II</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C'</li> <li>Spot 25sx of Class "C'</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfa</li> </ol>	BOPE. ulate well w/9.5 ppg mud ' cement from 3,138'-2,93 ' cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surface	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surfac	ce)			
<ol> <li>MIRU. NDWH. NU II</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and cle</li> </ol>	BOPE. ulate well w/9.5 ppg mud ' cement from 3,138'-2,93 ' cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off veran location.	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surface wellhead and ar	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surface) achors 3' below grad	ce) de. Weld on			
<ol> <li>MIRU. NDWH. NU II</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and cle</li> </ol>	BOPE. ulate well w/9.5 ppg mud ' cement from 3,138'-2,93 ' cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surface wellhead and ar seed for fluids.	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surface) nchors 3' below grade	ce) de. Weld on			
<ol> <li>MIRU. NDWH. NU II</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and clear Closed loop above gro</li> </ol>	BOPE. ulate well w/9.5 ppg mud ' cement from 3,138'-2,93 ' cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off veran location. und tank system will be us	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surface wellhead and ar seed for fluids.	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surface) nchors 3' below grade	ce) de. Weld on			
<ol> <li>MIRU. NDWH. NU II</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and cle</li> </ol>	BOPE. ulate well w/9.5 ppg mud ' cement from 3,138'-2,93 ' cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off veran location. und tank system will be us	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surface wellhead and ar seed for fluids.	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surfac	ce) de. Weld on			
<ol> <li>MIRU. NDWH. NU II.</li> <li>Set CIBP@4,700',circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and classification of Closed loop above ground in the company of the</li></ol>	ulate well w/9.5 ppg mud 'cement from 3,138'-2,93 'cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off ver ean location. und tank system will be us	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surfact wellhead and are sed for fluids.  NOTIFY OCD A BEGINNING P	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surface) chors 3' below grace 24 HOURS PRIOR T	ce) de. Weld on O NONS			
<ol> <li>MIRU. NDWH. NU II.</li> <li>Set CIBP@4,700', circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and clear Closed loop above ground in the company of the company of</li></ol>	ulate well w/9.5 ppg mud cement from 3,138'-2,93 cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off ver can location. und tank system will be us  ove is true and complete to the t	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surfact wellhead and an are sed for fluids.  NOTIFY OCD TO BEGINNING Paget Manager	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surface) achors 3' below grade 24 HOURS PRIOR T LUGGING OPERAT	ce) de. Weld on O OONS			
<ol> <li>MIRU. NDWH. NU II.</li> <li>Set CIBP@4,700', circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and clear Closed loop above ground in the company of the company of</li></ol>	ulate well w/9.5 ppg mud cement from 3,138'-2,93 cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off ver can location. und tank system will be us  ove is true and complete to the t	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surfact wellhead and an are sed for fluids.  NOTIFY OCD TO BEGINNING Paget Manager	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surface) chors 3' below grace 24 HOURS PRIOR T	ce) de. Weld on O OONS			
<ol> <li>MIRU. NDWH. NU II.</li> <li>Set CIBP@4,700', circ</li> <li>Spot 25sx of Class "C"</li> <li>Spot 25sx of Class "C"</li> <li>Perf and squeeze 110s</li> <li>Verify cement to surfadryhole marker and clear Closed loop above ground in the company of the company of</li></ol>	ulate well w/9.5 ppg mud cement from 3,138'-2,93' cement from 2,100'-1,90 x of Class "C" cement from ce on all casings. Cut off we can location.  und tank system will be use the cove is true and complete to the temporary E-mail address:	and spot 25sx of 88', WOC&Tag 00', WOC&Tag m 412' to surfact wellhead and are sed for fluids.  NOTIFY OCD A BEGINNING Pagent Manager  LRoark@Chevro.	. (B.Salt) . (T.Salt) ce. (Shoe/FW/surface) achors 3' below grade 24 HOURS PRIOR T LUGGING OPERAT	ce) de. Weld on Onons 03/28/17 32)-687-7279			

## WELLBORE DIAGRAM WLU 68

Created: 01/10/14 By: Updated: By: Lease: West Lovington Upper Sa Surf. Loc.: 1335' FNL 1280' F Bot. Loc.: County: Lea St.: Status: Producing Well	n Andres WL NM	Well #: API Unit Ltr.: TSHP/Rng: Pool Code: Directions: Chevno:	68 St. Lse:  30-025-30960  F Section: 7  17S 36E  OGRID:  Lovington, NM
Surface Casing Size: 8 5/8" Wt., Grd.: 24# Depth: 362' Sxs Cmt: 275 Circulate: Yes TOC: Surface Hole Size: 12-1/4"			KB: DF: 3,915  Ini. Spud: 12/11/90  Ini. Comp.: 02/22/91  3/92: Perf 4,756-5,156'. Acidize w/ 1,000g 15% HCL & w/ 6,325g 20% NEFE. IP 32 BOPD, 314 BWPD.
Production Casing         Size:       5 1/2"         Wt., Grd.:       15.5#         Depth:       5200'         Sxs Cmt:       600         Circulate:       No         TOC:       1,000'         Hole Size:       7 7/8"         Perf Details:         2 SPF, 180 Degree Phasing, 22.7 gm         4756-61, 62-68, 91-96         4,816-26         4922-25, 30-34, 41-43, 72-76, 98-5001         5013-19, 26-32, 36-39, 58-61, 65-75, 86-90         5100-07, 15-19, 25-29, 37-42, 52-56	PBTD: TD: 5	5,201'	Tubing Details:  153 Jts 2-7/8" J-55 6.5#  TAC @ 4,692'  14 Jts 2-7/8" J-55 6.5#  1 2-7/8" Blast Joint  SN @ 5,159'  1 2-7/8" Mud Anchor  Rod String Details:  1 1" PR  1 1-1/4" FG Rod Sub  1 1-1/4" FG Rod Sub  1 1-1/4" FG Rods  110 7/8" N-90 Rods  1 7/8" D Rod Sub  2 7/8" Shear Coupling  1 7/8" D Rod Sub  1-1/4" Rod Insert Pump

## WELLBORE DIAGRAM West Lovington Unit # 68

## PROPOSED

Created: Updated: Lease: Field: Surf. Loc.: Bot. Loc.: County: Status:	WEST LOVINGTO	By: By: VINGTON I IN UPPER SA L & 1280' F	N ANDRES		Well #: API Unit Ltr.: TSHP/Rng: Pool Code: Directions: Chevno:	
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8 5/8" 24# 362' 275 yes surface 12-1/4"					
				MLF	fro	erf and Sqz. 110sx of Class "C" Cement om 412'-surface, Verify cement at urface. (Shoe/FW/Surface.)  pot 25sx of Class "C" Cement from 100'-1,900',WOC&TAG. (T.Salt)
				MLF		pot 25sx of Class "C" Cement from 138'-2,938', WOC&TAG. (B.Salt)
Production of Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	Casing 5 1/2" 15.5# 5200' 600 NO 1000' 7 7/8"			TD 5206'	P	et CIBP@4,700' and spot 25sx of lass "C" Cement on top.  erfs: 4756'-5156'