

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-005-60824 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit |
| 8. Well Number 60 |
| 9. OGRID Number |
| 10. Pool name or Wildcat Twin Lake; San Andres (Assoc) |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other **HOBBS OCD**

2. Name of Operator
State of New Mexico for Blue Sky NM, Inc. **MAY 23 2017**

3. Address of Operator
1625 N. French Drive Hobbs, NM 88240 **RECEIVED**

4. Well Location
Unit Letter **B** : **300** feet from the **North** line and **2310** feet from the **East** line
Section **6** Township **9S** Range **29E** NMPM County **Chaves**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED PROCEDURE AND SCHEMATIC

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Whitaker TITLE P.E.S. DATE 05/23/2017

Type or print name Mark Whitaker E-mail address: PHONE: 575-393-6161

For State Use Only

APPROVED BY: Maury Brown TITLE AO/II DATE 5/23/2017

Conditions of Approval (if any):

Blue Sky NM, Inc.
Twin Lakes San Andres Unit No. 60
30-005-60824
UL – B, Sec. 6, T9S, R29E
330' FNL & 2310' FEL


8 5/8" 20 # csg at 135' w/ 75 sx cmt (circ)
4 1/2" 9.5 # csg at 2950' w/ 175 sx cmt
TD – 2950' Perfs 2734' – 2824'

1. MIRU plugging equipment. POOH w/ production equipment.
2. Run gauge ring. Set CIBP at 2634'. Circulate hole w/ mud laden fluid and pressure test casing to 500 psi.
3. Spot 50 sx cement on CIBP.
4. Perforate at 750'. Squeeze w/ 35 sx. WOC & tag.
5. Perforate at 185'. Pump sufficient cement to circulate to surface inside/outside 4 1/2" casing.
6. Cut off wellhead 4 feet below ground level.
7. Verify cement to surface on all strings.
8. Install upright P&A marker and cut off anchors.

NOTES: Mud laden fluid consists of 9.5 ppg with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to preceding with P&A.

Blue Sky NM, Inc.
TWIN LAKES SAN ANDRES UNIT #60

PROPOSED
30-005-60824



8 5/8" 20# @ 135' (circ cmt)

CUT OFF WELLHEAD, VERIFY CEMENT TO SURFACE,
& INSTALL DRY HOLE MARKER

PERF @ 185'. CIRCULATE CEMENT TO SURFACE

PERFORATE AT 750'. SQZ W/ 35 SX. WOC & TAG.

TOC unknown

PRESSURE TEST CASING
CIRCULATE MUD LADEN FLUID

SET CIBP AT 2634'. CAP WITH 50 SX

Perfs 2734'-2824'
4 1/2 " 9.5# @ 2950'