# Form 3160-5 (August 2007) HOBBS OCCO NITED STATES MENT OF THE INTERIOR OF LAND MANAGEMENT

Change Plans

Convert to Injection



FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. NMNM03210

Temporarily Abandon

Water Disposal

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. 8910084860		
1. Type of Well  ✓ Oil Well Gas Well Other				8. Well Name and No. WEST CAP QUEEN SAND UNIT 004		
2. Name of Operator REMNANT OIL OPERATING, LLC				9. API Well No. 30-005-01092		
3a. Address		3b. Phone No. (include area co	de) 10.	Field and Pool or E	Exploratory Area	
P.O. BOX 5375 MIDLAND, TX 79704	432-242-4965	CA	CAPROCK-QUEEN			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)				11. Country or Parish, State		
1982 FNL 660 FEL; UL H FSEC 17 T14S R31E	CH	CHAVES , NM				
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	E OF NOTICE, F	REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	✓ Production	n (Start/Resume)	Water Shut-Off	
Notice of Intelli	Alter Casing	Fracture Treat	Reclamati	ion	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomple	ete	Other	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

Plug Back

## 04/06/2017

Final Abandonment Notice

Move in rig up pulling unit. Remove horse head from pumping unit and attempted to release pump. Pump stuck, pumped 65bbls fresh water down casing and attempted to circulate (tubing plugged) Could not circulate or get pump to pump by stroking it with pulling unit. Nippled down wellhead, nipple up blow out preventer. Picked up, ran in hole with two(2) joints 2 3/8" J-55 tubing and tagged 42.5' below end of tubing. Last report put end of tubing at 2657' putting tag at 2699'. Backed off seven(7) 3/4" rods and pulled 9 joints 2 3/8" J-55 Tubing. Secured well. Shut down for night.

	/					
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)						
CARIE STOKER	Title REGULATORY AFFAIRS COORDINAT	or /				
Signature Carrie Stoll on	Date 07/11/2017 ACCEPTE	D FOR RECORD				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by	Title	Date 2017				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or contact that the applicant holds legal or equitable title to those rights in the subject lease which wo entitle the applicant to conduct operations thereon.		E LAND MANAGEMENT BAD FIELD OFFICE				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any pe	rson knowingly and willfully to make to any departmer	nt or agency of the United States any false,				
fictitious or fraudulent statements or representations as to any matter within its jurisdiction						
(Instructions on page 2)		KA				

#### WEST CAP QUEEN SAND UNIT #004

## 04/07/2017

Picked up on rods and unseated pump. Pull out of hole with a total of 99-3/4" steel rods, 6-1 1/2" sinker bars and pump. Pull out of hole with 82 joints 2 3/8" J-55 tubing, seating nipple, 1-4' x 2 3/8" perforated sub and bull plug. Run back in hole with 4 3/4" bit, bit sub, x-over and 80 joints tubing. Tag at 2595'and try to work bit through spot while circulating well at 1bpm. Tag is hard, bit bouncing and not showing anything in returns. Pull out of hole to inspect tools. Bit shows wear on outside of cone housing consistent with being turned on metal. Ran five stands back in hole for kill string. Secured well. Shut down for weekend.

# 04/10/2017

Pull out of hole with kill string. Run tubing string back in hole from top down as follows:

82- Joints 2 3/8" J-55 Tubing 1- Seating Nipple 1- 2 3/8" x 4' Perforated Sub 1- Bull Plug 2 3/8"

Ran rod string in hole from top down as follows:

99- 3/4" Steel "D" Rods 6- 1 1/2" Sinker Bars 1- Pump 2" x 1 1/2" x 16' RWBC

Hung well on and long stroked pump with the pulling unit. Good pump action with no leak off. Pressure holding at 500#. Rig down move out pulling unit.