Submit 1 Copy To Appropriate District Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	WELL API NO. DIVISION ncis Dr. Revised August 1, 2011 WELL API NO. 30-015-05586 5. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO RRILL OF TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator State of New Mexico formerly Tom R. Come 3. Address of Operator 1725 N. French Drive Hobbs, NM 88240 4. Well Location	7. Lease Name or Unit Agreement Name North Shugart Queen Unit 8. Well Number 008 9. OGRID Number 188152 10. Pool name or Wildcat Shugart; Yates-7RV-Q-GB
Unit Letter I : 2310 feet from the South line and 330 feet from the East line Section 20 Township 18S Range 31E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
NOTICE OF INT SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A XX	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURETITLE	DATE
Type or print name E-mail address For State Use Only APPROVED BY: TITLE P.E. Conditions of Approval (if any):	PHONE:

Plugging Report North Shugart Queen Unit #8 API: 30-015-05586

4/11/2018 Cleared location and moved in. Rigged up. No rods. Installed the BOP. Tubing was stuck. Loaded casing with 2 bbls of fresh water and tubing with less than I bbl. Stretch test showed tubing to be stuck at 1060'. RIH with wireline and sat down inside tubing at 11'. Attempted to screw onto the fish with 3/4" and 5/8" rods boxes and pins. No success. Worked tubing and got to go down 2" and up 5". Pulled 60 points over and fluid started to run over the BOP. The flow was very small and then some gas bubbles appeared. Worked tubing again and flow stopped. Left 60 points pulled on tubing. Clased in the well and SION.

4/12/2018 Worked tubing free, but could only gain down hole. Worked down hole 1 full joint and got stuck again. Performed 2 more stretch tests and showed tubing stuck @ 1115' and 1157'. RIH with outside back off tools and sat down at 1134'. Back off collar closest to 1000'. Got the back off in one shot. Laid down 2 joints and RIH with rods and tagged fish at 40'. Fish is not coming out of the hole with the tubing. Assume there is a full rod string in the hole. RIH with the 2 joints that were laid down and spotted 35 sx cement on top of back off. POOH 10 stands and SION.

4/16/2018 Caught fish at 40' with overshot. Backed off 8 rods. Made second attempt and caught 2 additional rods. Fish now at 290'. POOH with 16 joints of tubing. 31 total joints were recovered from the outside back off from 976'. ETOC at 639'. Set packer at 252' and tested plug below the packer to 800#. Held good. Isolated holes in 5 ½' casing between 63' and 126'. Perforated casing at 285' and set packer at 126'. Established rate and pumped cement down the tubing, under the packer to the perfs at 285' and to surface behind the 5 ½' casing. Took 75 sx to get cement to surface. Rigged down. Brought in another load of fresh water to water the road. SION.

4/17/2018 Moved rig and equipment off location with the assistance of a 4WD loader. Dug out and cut off. Filled up 5 ½"X 8 5/8" annulus to surface from 35' with 5 sx cement. 5 1/2" casing took less than a sack to fill up. Installed marker and cut off anchors. Cleaned the pit.