District 1 - (575) 1625 N. French D		State of New Mexico Energy, Minerals and Natural Resources				Form C-103 Revised July 18, 2013			
	r., Hobbs, NM 88249				5541445	WELL AP			
District II - (575) 811 S. First St. A	748-1283	ses ard	ONSERVAT	ION DIV	SION	C. Indiant		<u>30-025-2</u>	4391
$\begin{array}{c} \underline{\text{District I}} = (575) \ 393-6161 \\ \underline{\text{District II}} = (575) \ 393-6161 \\ \underline{\text{District II}} = (575) \ 748-1283 \\ \underline{\text{S11 S. First St., Artesia, NM 88210}} \\ \underline{\text{District III}} = (505) \ 334-6178 \\ \underline{\text{1000 Rio Brazos Rd., Aztec, NM 87 MAR}} \ 2 \ 8 \ 2019 \\ \underline{\text{District IV}} = (505) \ 476-3460 \\ \end{array}$						5. Indicate	ATE X		
District IV - (505	(d., Aztec, NM 8741971) ) 476-3460	1 2 0 2019	Santa Fe, NM	M 87505		6. State O			
1220 S. St. Franci 87505	s Dr., Santa Fe, NM	CEIVED				00335	5		
01303		ICES AND REI	PORTS ON WE	ELLS				Unit Agree	ement Name
	HIS FORM FOR PROPO SERVOIR. USE "APPLI					1			S SAN ANDRES
1. Type of Well: Oil Well 🔲 Gas Well 🔀 Other							8. Well Number 708		
2. Name of O						9. OGRID			
CROSS TIMBERS ENERGY, LLC 3. Address of Operator							298299 10. Pool name or Wildcat		
3. Address of Operator 400 W 7TH STREET, FORT WORTH, TX 76102							GRAYBURG-SAN ANDRES		
4. Well Locat	400 W	/IH SIREEI	,FORT WO	<u>KIH, IX</u>	/6102	GIA	IDUN	J-SAIN A	INDRES
	Letter O :	_100 feet	t from the S		line and	2590	feet from	the	E line
Sectio			wnship 17-S		33E	NMPM			LEA
a state of the sta			(Show whether						
		<u> </u>		·					
					0.1.1	<b>D</b>	<u>.</u>	<b>.</b> .	
	12. Check	Appropriate I	Box to Indica	te Nature	of Notice,	Report or	Other I	Jata	
	NOTICE OF IN	NTENTION <sup>-</sup>	TO:	1	SUB	SEQUEN		ORT O	F:
PERFORM REMEDIAL WORK 🖾 PLUG AND ABANDON 📋 REMEDIAL WOR									GCASING 🗌
TEMPORARIL				1	MENCE DR			P AND A	
			COMPL	CAS	ING/CEMEN	t job		0	
DOWNHOLE ( CLOSED-LOO									
OTHER:		•		ОТН	ER:				
	be proposed or comp ing any proposed w ed completion or re-	ork). SEE RUL							
		completion.							
	•								
propos 3/21/19: MI	RU	Dolosood from on (of	ftaal on aadon O d	4 188, BOOR	ul inightion stal	ing paraming T	Damla and tu	hina	
propos 3/21/19: MI	•	Released from on/of	f tool on packer @ 4	4,188'. POOH	w/ injection stri	ing, scanning. F	Replaced tu	bing.	
propos 3/21/19: MI 3/22/19: Se	RU		-		-		-	bing.	
propos 3/21/19: MI 3/22/19: Se 3/25/19: RI 3/26/19: PO	RU t plug in profile nipple. 1	ion string, could not plug w/ magnet – no	t latch back on to or catch. RIH w/ imp	n/off tool. Pro	file plug appears	s to have come l	oose.	-	lug to be to the side o
propos 3/21/19: MJ 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor	ion string, could not plug w/ magnet – no rt catch on/off tool. 1	t latch back on to or catch. RIH w/ imp Unable.	n/off tool. Pro pression block,	file plug appears	s to have come l	oose.	-	vlug to be to the side o
propos 3/21/19: MI 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out j g packer @ 4,188' with II	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA.	n/off tool. Pro pression block, profile plug. IH w/ on/off to Release from	file plug appears clean imprint o ol connection.	s to have come l f top of profile r Latch onto pack	oose. nipple – he xer, release	lieve profile p & POOH. Re	edress packer and
propos 3/21/19: MI 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out p	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA.	n/off tool. Pro pression block, profile plug. IH w/ on/off to Release from	file plug appears clean imprint o ol connection.	s to have come l f top of profile r Latch onto pack	oose. nipple – he xer, release	lieve profile p & POOH. Re	edress packer and
propos 3/21/19: MJ 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run J	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out g packer @ 4,188' with II MIT per NMOCD guidel	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA. Return well to injec	n/off tool. Pro pression block, profile plug. IH w/ on/off to Release from tion.	file plug appears clean imprint o ol connection.	s to have come l f top of profile r Latch onto pack	oose. nipple – he xer, release	lieve profile p & POOH. Re	edress packer and
Propos 3/21/19: MJ 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run J	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out j g packer @ 4,188' with II	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA.	n/off tool. Pro pression block, profile plug. IH w/ on/off to Release from tion.	file plug appears clean imprint o ol connection. on/off, circulate	s to have come l f top of profile r Latch onto pack	oose. nipple – be ker, release cker fluid.	lieve profile p & POOH. Re	edress packer and
propos 3/21/19: MI 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out g packer @ 4,188' with II MIT per NMOCD guidel	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA. Return well to injec	n/off tool. Pro pression block, profile plug. IH w/ on/off to Release from tion.	file plug appears clean imprint o ol connection. on/off, circulate	s to have come l f top of profile r Latch onto pack backside w/ pac	oose. nipple – be ker, release cker fluid.	lieve profile p & POOH. Re	edress packer and
propos 3/21/19: MJ 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run J	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out g packer @ 4,188' with II MIT per NMOCD guidel	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA. Return well to injec <b>Rig Relea</b> s	n/off tool. Pro pression block, profile plug. III w/ on/off to Release from ttion. se Date:	file plug appears clean imprint o ol connection. on/off, circulate 0	s to have come l f top of profile r Latch onto pack backside w/ pac 93/11/2009	oose. nipple – be cer, release cker fluid.	lieve profile p & POOH. Re	edress packer and
propos 3/21/19: MJ 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run J	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out j g packer @ 4,188' with II MIT per NMOCD guidel 12/30/20	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA. Return well to injec <b>Rig Relea</b> s	n/off tool. Pro pression block, profile plug. III w/ on/off to Release from ttion. se Date:	file plug appears clean imprint o ol connection. on/off, circulate 0	s to have come l f top of profile r Latch onto pack backside w/ pac 93/11/2009	oose. nipple – be cer, release cker fluid.	lieve profile p & POOH. Re	edress packer and
propos 3/21/19: MJ 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run b pud Date:	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out j g packer @ 4,188' with II MIT per NMOCD guidel 12/30/20 that the information	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA. Return well to injec Rig Releas nd complete to t	n/off tool. Pro pression block, profile plug. III w/ on/off to Release from the Date:	file plug appears clean imprint o ol connection. on/off, circulate 0 ny knowledg	s to have come l f top of profile r Latch onto pack backside w/ pack 3/11/2009 ge and belief.	oose. nipple – be ker, release cker fluid.	lieve profile p & POOH. R Notify NMO	edress packer and OCD of intent to run
propos 3/21/19: MJ 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run b pud Date:	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out j g packer @ 4,188' with II MIT per NMOCD guidel 12/30/20	ion string, could not plug w/ magnet – no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response.	t latch back on to or catch. RIH w/ imp Unable. on/off to mill out p tool. POOH and RI Pressure test TCA. Return well to injec Rig Releas nd complete to t	n/off tool. Pro pression block, profile plug. III w/ on/off to Release from the Date:	file plug appears clean imprint o ol connection. on/off, circulate 0 ny knowledg	s to have come l f top of profile r Latch onto pack backside w/ pack 3/11/2009 ge and belief.	oose. nipple – be ker, release cker fluid.	lieve profile p & POOH. Re	edress packer and OCD of intent to run
propos 3/21/19: MI 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run I pud Date:	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out j g packer @ 4,188' with II MIT per NMOCD guided 12/30/20 that the information	ion string, could not plug w/ magnet - no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response. 008	t latch back on to or o catch. RIH w/ imp Unable. Ton/off to mill out p tool. POOH and RI Pressure test TCA. Return well to inject Rig Release Ind complete to the Complete to the Complete to the	n/off tool. Pro pression block, profile plug. III w/ on/off to Release from ction. se Date:	file plug appears clean imprint o ol connection. on/off, circulate 0 ny knowledg	s to have come l f top of profile r Latch onto pack backside w/ pack 03/11/2009 ge and belief.	oose. nipple – be ker, release cker fluid.	lieve profile p & POOH. Ro Notify NMO	edress packer and OCD of intent to run
propos 3/21/19: MI 3/22/19: Se 3/25/19: RI 3/26/19: PC the PN. Att 3/27/19: PC Plan forwar RBIH settin MIT. Run I pud Date: hereby certify IGNATURE ype or print na	RU t plug in profile nipple. 1 H with 2-3/8" IPC inject DOH. Attempt to catch p tempt to latch on w/ shor J & RIH w/ washpipe and d: Continue to mill out j g packer @ 4,188' with II MIT per NMOCD guidel 12/30/20 that the information me Samanntha A Dniv	ion string, could not plug w/ magnet - no rt catch on/off tool. I d cutrite & mill over plug around on/off t PC injection string. lines and response. 008	t latch back on to or o catch. RIH w/ imp Unable. Ton/off to mill out p tool. POOH and RI Pressure test TCA. Return well to inject Rig Release Ind complete to the Complete to the Complete to the	n/off tool. Pro pression block, profile plug. III w/ on/off to Release from se Date:	file plug appears clean imprint o ol connection. on/off, circulate 0 ny knowledg 7 Technicia	s to have come l f top of profile r Latch onto pack backside w/ pack 03/11/2009 ge and belief.	oose. nipple – be ker, release cker fluid.	lieve profile p & POOH. Ro Notify NMO	edress packer and OCD of intent to run