Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I – (575) 393-6161	State of New Mexico Dergy, Minerals and Natural Re OIL CONSERVATION DIV. 1220 South St. Francis D anta Fe, NM 87505 ESTAND REPORTS ON WELLS TO DRILL OR TO DEEPEN OR PLUG BACK TION FOR PERMIT" (FORM C-101) FOR SUC	sources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	00.	WELL	API NO. 30-025-23699	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIV	ISION 5 India	cate Type of Lease	
District III - (505) 334-6178	1220 South St. Francis D	r.	STATE X FEE	
District IV - (505) 476-3460	S anta Fe, NM 87505	6. State	Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	EM		312479	
SUNDRY NOTIC	ES OND REPORTS ON WELLS	7. Leas	e Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOS	FOUND REPORTS ON WELLS TO DRILL OR TO DEEPEN OR PLUG BACTION FOR PERMIT" (FORM C-101) FOR SUC	КТОА		
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	TION FOR PERMIT" (FORM C-101) FOR SUC	H NO	ORTH VACUUM ABO UNIT	
	Gas Well 🗓 Other INI	8. Well	Number 161	
2. Name of Operator		9. OGF	RID Number	
	IMBERS ENERGY, LLC		298299	
3. Address of Operator			10. Pool name or Wildcat	
	TH STREET, FORT WORTH, TX	76102 VA	CUUM; ABOU NORTH	
4. Well Location	1000 A A A			
Unit Letter H:		line and <u>660</u>	feet from the Eline	
Section 12	Township 17-S Range	34-E NMPM	County LEA	
	11. Elevation (Show whether DR, RKB, 4020 GR	KI, GK, etc.)		
	1020 GR			
12 Check Ar	opropriate Box to Indicate Nature	of Notice Report	or Other Data	
-	•	•		
NOTICE OF INT			ENT REPORT OF:	
	 [EDIAL WORK	■ X ALTERING CASING □	
		MENCE DRILLING O		
	MULTIPLE COMPL	NG/CEMENT JOB		
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM		ED.		
OTHER:	OTH		tinent dates including estimated dat	
OTHER: 13. Describe proposed or comple	ted operations. (Clearly state all pertine	nt details, and give per		
OTHER: 13. Describe proposed or comple	ted operations. (Clearly state all pertines). SEE RULE 19.15.7.14 NMAC. For	nt details, and give per		
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record	ted operations. (Clearly state all pertines). SEE RULE 19.15.7.14 NMAC. For npletion.	nt details, and give per Multiple Completions		
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record	ted operations. (Clearly state all pertines). SEE RULE 19.15.7.14 NMAC. For	nt details, and give per Multiple Completions		
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For appletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3	nt details, and give per Multiple Completions /8"	: Attach wellbore diagram of	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55	ted operations. (Clearly state all pertine k). SEE RULE 19.15.7.14 NMAC. For appletion. To Tog. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 1	nt details, and give per Multiple Completions /8"	: Attach wellbore diagram of	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55 4/16/19 - Latch on to pkr @ 7	ted operations. (Clearly state all pertine k). SEE RULE 19.15.7.14 NMAC. For appletion. To Tog. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 1	nt details, and give per Multiple Completions /8"	: Attach wellbore diagram of	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2	ted operations. (Clearly state all pertine k). SEE RULE 19.15.7.14 NMAC. For appletion. To Tog. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 1	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu	: Attach wellbore diagram of ill the control of the	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For appletion. To Tbg. PU & TIH w o/o tool & 229 jts 2 37.186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg Trest @ 8505'. Pressure test backside to 40.	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu) psi for 30 mins. Held	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. To Tog. PU & TIH w o/o tool & 229 jts 2 37.186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg To set @ 8505'. Pressure test backside to 40.18. Notified OCD of intent to run MIT. Ga	nt details, and give per Multiple Completions /8" RU tbg tester. PU rebu psi for 30 mins. Held ary from OCD witnes.	ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 ce. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psi	nt details, and give per Multiple Completions /8" RU tbg tester. PU rebu psi for 30 mins. Held ary from OCD witnes.	ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertine (c). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/186'. POOH w 229 jts 2 3/8" & LD pkr. 12 3/8" J55 tbg 1 set @ 8505'. Pressure test backside to 40 c. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhee	nt details, and give per Multiple Completions //8" RU tbg tester. PU rebu psi for 30 mins. Held rry from OCD witnes. for 32 min. Failing Mineral remediation to follow	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back. Spud Date: 05/07/197	ted operations. (Clearly state all pertines). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 37.186'. POOH w 229 jts 2 37.186'. Pressure test backside to 46.18. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhed to bleed down line. NOI for Bradenhed Rig Release Date: Rig Release Date:	Multiple Completions Multiple Completion Multiple Completions Multiple Complet	Attach wellbore diagram of ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow.	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J5: 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back	ted operations. (Clearly state all pertines). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 37.186'. POOH w 229 jts 2 37.186'. Pressure test backside to 46.18. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhed to bleed down line. NOI for Bradenhed Rig Release Date: Rig Release Date:	Multiple Completions Multiple Completion Multiple Completions Multiple Complet	ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow. of Approval: notify of Approval: Test & Chart aning MIT Test & Chart ef. DATE 04/24/2019	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valved Hook csg and surface csg back Spud Date: O5/07/1972	ted operations. (Clearly state all pertine k). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 3/886. POOH w 229 jts 2 3/88 & LD pkr. 10.2 3/88 J55 tbg 12 set @ 8505'. Pressure test backside to 46 st. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psi k to bleed down line. NOI for Bradenhed Rig Release Date: Rig Release Date:	Multiple Completions Multiple Completions Multiple Completions RU tbg tester. PU rebu psi for 30 mins. Held ry from OCD witnes. for 32 min. Failing MI ad remediation to foll which is a second of the completion of the compl	ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow. of Approval: notify of Approval: notify Test & Chart	
OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record 4/15/19 - POOH W 2 3/8, J55 4/16/19 - Latch on to pkr @ 7 @ 5000 psi & TIH w 229 jts 2 4/18/19 - PUArrowset 1X pk 4/22/219 - ND BOP. NU tree coming from surface csg valve Hook csg and surface csg back. Spud Date: 05/07/197: I hereby certify that the information at SIGNATURE Type or print name Samanntha Avantable.	ted operations. (Clearly state all pertines). SEE RULE 19.15.7.14 NMAC. For impletion. 5 Tbg. PU & TIH w o/o tool & 229 jts 2 37.186'. POOH w 229 jts 2 37.186'. Pressure test backside to 46.18. Notified OCD of intent to run MIT. Gave. Chart showed 545 psi, ending 535 psick to bleed down line. NOI for Bradenhed to bleed down line. NOI for Bradenhed Rig Release Date: Rig Release Date:	Multiple Completions Multiple Completions Multiple Completions RU tbg tester. PU rebu psi for 30 mins. Held ry from OCD witnes. for 32 min. Failing MI ad remediation to foll which is a second of the completion of the compl	ilt pkr & test back under slips ok. Circ 200 bls pkr fluid. Ran MIT noticed fluid T due to rule 19.15.26.11. ow. of Approval: notify of Approval: Test & Chart aning MIT Test & Chart ef. DATE 04/24/2019	