
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103	
Office State of New Mexico Energy, Minerals and Natural Resource	EIVED UCI 14 2010 May 27, 2004	
Last we strand tong Hotobs, 't was we	WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-05230	
	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE	
District IV Santa Fe, NIVI 87505	6. State Oil & Gas Lease No.	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIEFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	300380	
SLINDRY NOTICES AND REPORTS ON WELLS HOPP	7. Lease Name or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT 8 2019 RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State "T"	
RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	n in the second se	
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 5	
RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Weir Nulliber 5	
	9. OGRID Number 228051	
Americo Energy Resources, LLC		
3. Address of Operator	10. Pool name or Wildcat	
7575 San Felipe, Suite 200, Houston, TX 77063	Denton (Wolfcamp)	
4. Well Location		
Unit Letter_K:2215feet from theSout line and2046_	feet from theWestline	
Section 2 Township T16S Range 37-E	NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application 🗌 or Closure 🗌		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistar	re from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construct	ion Material	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data	
	•	
NOTICE OF INTENTION TO: SU	JBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🛛 PLUG AND ABANDON 🔲 REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI		
	NG OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC	DB	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back higher OTHER: Plug back higher	DB Ind complete higher	
PULL OR ALTER CASING Image: Multiple complete c	DB Ind complete higher Ind give pertinent dates, including estimated	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back OTHER: Plug back at a light back back back back back back back back	DB Ind complete higher Ind give pertinent dates, including estimated	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back at a light proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion.	DB Ind complete higher Ind give pertinent dates, including estimated	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string)	DB Ind complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear \$-1/2" casing liner to the top of fish at 8	0B Ind complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string)	DB	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: plug back higher OTHER: Plug back at a light of the proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Report of the stand back tubing string).	DB	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: plug back higher OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and	DB	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step!	DB	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge	DB	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: plug back higher OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'.Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700'	DB	
 PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700' .Pooh and lay down g 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket	
 PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700' .Pooh and lay down g 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket	
 PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down g 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole and ran CBL/CCL/VDL/GR log from 7000' to 6000 (Block squeeze if necessar) 	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket /) 6046'-6058') with 4 ½" hollow carrier gun	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: plug back higher OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(602'-602'-602')	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket /) 6046'-6058') with 4 ½" hollow carrier gun	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JO OTHER: plug back higher OTHER: plug back higher OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6022'-6026')+(6022'-6026')+(6022'-6026')+(6022'-6022')+(6022'-6026')+(6022'-6022')+(6022'-6026')+(6022'-6022')	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket /) 6046'-6058') with 4 ½" hollow carrier gun	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: plug back higher OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700' .Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-ded with 4 jet shot per foot 160 degree phasing . pooh and rig down perforating equiprint 11- Check well for flow	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket /) 6046'-6058') with 4 ½" hollow carrier gun	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT IC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700' .Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-Check well for flow 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string, and lay down packer	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket /) 6046'-6058') with 4 ½" hollow carrier gun	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT IC OTHER: plug back higher OTHER: Plug back and the proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down geto frip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-Trip in hole with tubing string and isolation packer, swab well in if necessary!	0B Image: Complete higher Image: Complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket /) 6046'-6058') with 4 ½" hollow carrier gun nent	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-ded with 4 jet shot per foot 160 degree phasing . pooh and rig down perforating equipr 11- Check well for flow 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string, and lay down packer 14- Trip in hole	0B	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT IC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole and ran CBL/CCL/VDL/GR log from 7000' to 6000 (Block squeeze if necessary) 10-Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6) 10-ded with 4 jet shot per foot 160 degree phasing . pooh and rig down perforating equiprima 1- Check well for flow 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string, and lay down packer 14- Trip in hole with production string and put well on beam/rod pumping 14- Trip in hole with production string and put well	0B	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT IC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down g 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole and ran CBL/CCL/VDL/GR log from 7000' to 6000 (Block squeeze if necessary) 10-Trip in hole with tubing string and isolation packer, swab well in if necessary! 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string and put well on beam/rod pumping 1 hereby certify that the information above is true and co	0B	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT IC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down g 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole and ran CBL/CCL/VDL/GR log from 7000' to 6000 (Block squeeze if necessary) 10-Trip in hole with tubing string and isolation packer, swab well in if necessary! 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string and put well on beam/rod pumping 1 hereby certify that the information above is true and co	DB Ind complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket /) 6046'-6058') with 4 ½" hollow carrier gun nent	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT IC OTHER: plug back higher OTHER: Plug back a OTHER: Plug back a 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down g 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole and ran CBL/CCL/VDL/GR log from 7000' to 6000 (Block squeeze if necessary) 10-Trip in hole with tubing string and isolation packer, swab well in if necessary! 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string and put well on beam/rod pumping 1 hereby certify that the information above is true and co	0B ond complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) poort findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent lige and belief. 1 further certify that any pit or below- an (attached) alternative OCD-approved plan []10/10/2019	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher 13. Describe proposed or, completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6 loaded with 4 jet shot per foot 160 degree phasing . pooh and rig down perforating equipr 11- Check well for flow 12- Trip in hole with tubing string and isolation packer. 14- Trip in hole with production string and put well on beam/rod pumping I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines], a general permit] or SIGNATURE TITLE_Area Asset Manager	0B ond complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) poort findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent lige and belief. I further certify that any pit or below- an (attached) alternative OCD-approved plan []10/10/2019	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6 loaded with 4 jet shot per foot 160 degree phasing . pooh and rig down perforating equipr 11- Check well for flow 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string and put well on beam/rod pumping 1 hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or SIGNATURE <td [],="" a="" according="" colsed="" general="" guidelines="" nmocd="" permit<="" td="" to=""><td>DB Ind complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent Ige and belief. 1 further certify that any pit or below- an (attached) alternative OCD-approved plan []</td></td>	<td>DB Ind complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent Ige and belief. 1 further certify that any pit or below- an (attached) alternative OCD-approved plan []</td>	DB Ind complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) port findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent Ige and belief. 1 further certify that any pit or below- an (attached) alternative OCD-approved plan []
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JC OTHER: plug back higher 13. Describe proposed or completed operations. (Clearly state all pertinent details, a date of starting any proposed work). SEE RULE 1103. For Multiple Completions: completion or recompletion. 1-Rig up on the well, and pooh with production equipment (rods and tubing string) 2- Trip in hole with rock bit on tubing string, clear 5-1/2" casing liner to the top of fish at 8 Fish left in the well in 1998 (Sinker bars and 400' of sand line, Baker Mod 415 at 8955 and 3- Attempt to tag and push junk down if Possible. Pooh and stand back tubing string. (Reg 4- If unable to push junk down the hole go to next step! 5-Run Gauge ring and junk basket, clear 5-1/2" casing liner to 8700'. Pooh and lay down ge 6- Trip in hole with CIBP, Correlate and set CIBP at 8700' 7- Bail dump 20' cement on top of CIBP at 8700-8680' (wait on cement) 8- Rig up Perforating company. Nipple up and test casing lubricator 600# 9- Trip in hole with casing gun Perforate 7-5/8" casing at: (6002'-6012')+ (6022'-6026')+(6 loaded with 4 jet shot per foot 160 degree phasing . pooh and rig down perforating equipr 11- Check well for flow 12- Trip in hole with tubing string and isolation packer, swab well in if necessary! 13- If no flow, Pooh with tubing string and put well on beam/rod pumping 1 hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or SIGNATURE <td [],="" a="" according="" colsed="" general="" guidelines="" nmocd="" permit<="" td="" to=""><td>0B ond complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) poort findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent lige and belief. 1 further certify that any pit or below- an (attached) alternative OCD-approved plan []10/10/2019</td></td>	<td>0B ond complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) poort findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent lige and belief. 1 further certify that any pit or below- an (attached) alternative OCD-approved plan []10/10/2019</td>	0B ond complete higher Ind give pertinent dates, including estimated Attach wellbore diagram of proposed 741' Kobe pump and 2-7/8" tubing left in the hole) poort findings for OCD record) gauge ring & Junk basket () 6046'-6058') with 4 ½" hollow carrier gun nent lige and belief. 1 further certify that any pit or below- an (attached) alternative OCD-approved plan []10/10/2019

؍



Oil saturation.3/6/1953) Core Lab. Report.

7-5/8" casing set at 7186' w/1200 sxs.

Last run lost Sinker bars & 400' of sand line. Baker Mod 415 at 8968', Kobe Pump Cavity & 2 7/8" Tubing cut off fish. Top of fish at 8924'