UNITED STATES

FORM APPROVED OMB NO. 1004-0137

BUREAU OF LAND MANAGEMENT	UCDI	lodds	Expires: January 31, 20
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter abandoned well. Use form 3160-3 (APD) for such propos	5. Lease Serial No. NMLC063586		
abandoned well. Use form 3160-3 (APD) for such propos	36. If Indian, Allottee or Tribe Nam		
SUBMIT IN TRIPLICATE - Other instructions on page 2	2 KOR (7 2019	7. If Unit or CA/Agreement, Name
	**		NMNM94514X

SUBMIT IN TRIPLICATE - Other instructions on page 2		 If Unit or CA/Agreement, Name and/or No. NMNM94514X
1. Type of Well Gas Well Other	* <u>*</u>	8. Well Name and No. LUSK WEST DELAWARE UNIT 902
Name of Operator Contact: SHACKELFORD OIL COMPANY E-Mail: brady@chc	BRADY SHACKELFORD octawservices.com	9. API Well No. 30-025-30329-00-S1
3a. Address MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-682-9784	10. Field and Pool or Exploratory Area LUSK
4. Location of Well (Footage, Sec., T., R., M., or Survey Description,)	11. County or Parish, State
Sec 29 T19S R32E NWNE 990FNL 1900FEL		LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off □ Well Integrity □ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection (Sect. CTBC 4703, Sfot. 50 Sx. from 4703-PROCEDURES FOR PLUGGING LWDU #902

Spot. Alexander of the proposed work and approximate duration thereof.

The proposed or Completed Plugging Completed and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection of the involved operation of

1. SET CIBP AT 2470' PUMP 25 SXS OF CLASS C CEMENT 2. TAG CEMENT AND PRESSURE TEST CASING TO 500 PSI

3. PERFORATE 980-50' BELOW T/SALT AND ATTEMPT TO SQUEEZE CEMENT TO 500'-WOC AND TAG 1025 - 858

4. PERFORATE AT 60' AND CIRCULATE TO SURFACE

5. DIG OUT AND CUT OFF WELLHEAD BELOW GROUND LEVEL. WELD DRY MARKER TO CASING

6. RECLAIM LOCATION AND SEED

SEE ATTACHED FOR CONDITIONS OF APPROVAL

_			CO	I TO CHIOLEIGH	11 1100 1110	
Below	ground level dry hole	. W	varker	required		
14. I hereby certify that the foregoing is true and correct. Electronic Submission #488068 verified by the BLM Well Information System For SHACKELFORD OIL COMPANY, sent to the Hobbs Committed to AFMSS for processing by DEBORAH MCKINNEY on 10/16/2019 (20DLM0021SE)						
Name (Printed/Typed)	DON SHACKELFORD	Title	PRESIDENT			
Signature	(Electronic Submission)	Date	10/15/2019			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By	ames a. amo _	Title	SALT	7	1D-27-19 Date	
Conditions of approval, if a certify that the applicant ho	ny, are attached. Approval of this notice does not warrant or ids legal or equitable title to those rights in the subject lease licant to conduct operations thereon.	Office	240			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED NM 6CD 11-15-19

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted