	To Appropriate District	51	ate of New Me			Form C-103 Revised July 18, 2013	
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District H – (575) 249 1293					WELL API NO.	30-025-11488	
<u>District II</u> – (57 811 S. First St.,	Artesia, NM 88210 U	BBS OCD	SERVATION	DIVISION	5. Indicate Type of		
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 18 2019 District IV - (505) 476-3460 Santa Fe, NM 87505					STATE] FEE 🗖	
1220 S. St. Fran	05) 476-3460 🛛 🚺 ncis Dr., Santa Fe, NM	6. State Oil & Gas	s Lease No.				
87505	SUNDRY	EGENEDPO	RTS ON WELLS		7. Lease Name or	Unit Agreement Name	
DIFFERENT R	THIS FORM FOR PRO ESERVOIR. USE "AP	POSALS TO DRILL OR	TO DEEPEN OR PLU			•	
PROPOSALS.) 1. Type of V	Well: Oil Well	Gas Well 🛛 O	ther injection		8. Well Number		
2. Name of Operator Fulfer OII And CAttle Co LLC					9. OGRID Number 141402		
3. Address of Operator P.O.Box 1224, 101 E. Panther AVE Jal NM, 88252					10. Pool name or Wildcat Yates, Queens		
4. Well Loc Uni	ation I t Letter7	_:feet fro		FSL Inne and 9	60 feet from	n the <u>FFL</u> line	
Sec	tion /			<u> </u>	NMPM	County LEA	
		IT. Elevation (S	now whether DK,	KKB, KI, GK, elc.	/		
	12 Chec	Image: State of the state					
					•		
PERFORM	REMEDIAL WORK						
						PANDA	
				CASING/CEMEN	FJOB 📙		
CLOSED-LC			_			_	
OTHER: 13 Desc	ribe proposed or co	moleted operations	Clearly state all n	OTHER: ertinent details and	l give pertinent dates	, including estimated date	
of sta		work). SEE RULE					
	•	•	up WSU, on 11/0	6/2019unset the pa	cker and pull the pa	cker, hydro-test the tubing	
the	well and run retriev	vable BP and packer a	it the same time. s	et the BP and test t	he casing and found	holes in the casing at	
						at cement, let the cement se	
				ose rams on non te	si ine casing io suria	נוחות בא הופת #נורב הופג	
			ne BP. POH w/ To	ols. run collars and	bit to bottom and cl		
bot	tom,3353.POH and	lav down Collars. Pie	ne BP. POH w/ To ck up 7"AD1 plas	ols. run collars and tic coated packer a	bit to bottom and cl		
bot		lay down Collars. Pie /IT test.	ne BP. POH w/ To ck up 7"AD1 plas	ols. run collars and tic coated packer a	bit to bottom and cl	ean out well to	
bot	tom,3353.POH and	lay down Collars. Pie /IT test.	ne BP. POH w/ To ck up 7"AD1 plas dition of APP	ols. run collars and tic coated packer a roval: notify	bit to bottom and cl nd run and set at 318	ean out well to	
bot	tom,3353.POH and	lay down Collars. Pie /IT test.	ne BP. POH w/ To ck up 7"AD1 plas dition of APP	ols. run collars and tic coated packer a roval: notify	bit to bottom and cl nd run and set at 318	ean out well to	
bot	tom,3353.POH and	lay down Collars. Pie /IT test.	ne BP. POH w/ To ck up 7"AD1 plas dition of APP	ols. run collars and tic coated packer a roval: notify	bit to bottom and cl nd run and set at 318	ean out well to	
bot	tom,3353.POH and	lay down Collars. Pie /IT test.	ne BP. POH w/ To ck up 7"AD1 plas dition of APP	ols. run collars and tic coated packer a roval: notify ice 24 hours IT Test & Cha	bit to bottom and cl nd run and set at 318	ean out well to	
bot the Spud Date:	tom,3353.POH and OCD to schedule N 3/29/54	lay down Collars. Pie AlT test. Col Q prio	ne BP. POH w/ Te ck up 7"ADI plas adition of App CD Hobbs off r of running N Rig Release Dat	ols. run collars and tic coated packer a roval: notify ice 24 hours IT Test & Cha e: 4/25/54	l bit to bottom and cl nd run and set at 318	ean out well to	
bot the Spud Date:	tom,3353.POH and OCD to schedule N 3/29/54	lay down Collars. Pie /IT test.	ne BP. POH w/ Te ck up 7"ADI plas adition of App CD Hobbs off r of running N Rig Release Dat	ols. run collars and tic coated packer a roval: notify ice 24 hours IT Test & Cha e: 4/25/54	l bit to bottom and cl nd run and set at 318	ean out well to	
bot the Spud Date:	tom,3353.POH and OCD to schedule N 3/29/54	lay down Collars. Pie AlT test. Col Q prio	the BP. POH w/ Teck up 7"ADI plass adition of App CD Hobbs off r of running N Rig Release Data complete to the be	ols. run collars and tic coated packer a roval: notify ice 24 hours IT Test & Cha e: 4/25/54	l bit to bottom and cl nd run and set at 318	ean out well to 6 load the backside and ca	
bot the Spud Date: I hereby certif	tom,3353.POH and OCD to schedule N 3/29/54 y that the informati	lay down Collars. Pie AllT test. Col prio on above is true and c	te BP. POH w/ Te ck up 7"ADI plas adition of App CD Hobbs off r of running N Rig Release Dat complete to the be 	ols. run collars and tic coated packer a roval: notify ice 24 hours IT Test & Cha IT Test & Cha e: 4/25/54 st of my knowledge tions Manager	bit to bottom and cl nd run and set at 318	ean out well to 6 load the backside and ca	
bot the Spud Date: I hereby certif SIGNATURE	tom,3353.POH and OCD to schedule N 3/29/54 y that the informati Mike Denn name	lay down Collars. Pie AllT test. Col prio on above is true and c	te BP. POH w/ Te ck up 7"ADI plas adition of App CD Hobbs off r of running N Rig Release Dat complete to the be 	ols. run collars and tic coated packer a roval: notify ice 24 hours IT Test & Cha e: 4/25/54 st of my knowledge	bit to bottom and cl nd run and set at 318	ean out well to 6 load the backside and ca	
bot the Spud Date: I hereby certif SIGNATURE Type or print r For State Use APPROVED 1	tom,3353.POH and OCD to schedule N 3/29/54 3/29/54 with the information mame Mike Dennion Only	lay down Collars. Pie AllT test. Col prio on above is true and c	te BP. POH w/ Te ck up 7"ADI plas adition of App CD Hobbs off r of running N Rig Release Dat complete to the be 	ols. run collars and tic coated packer a roval: notify ice 24 hours IT Test & Cha IT Test & Cha e: 4/25/54 st of my knowledge tions Manager	bit to bottom and cl nd run and set at 318	ean out well to 6 load the backside and ca 	