| Submit 1 Copy To Appropriate District State of New Mexico Office | Form C-103 Revised July 18, 2013 |
|--|---|
| District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 | WELL API NO. |
| District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION | 30-025-32003 5. Indicate Type of Lease |
| District III - (305) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos R4, Aztre, NM 87410 | STATE FEE |
| District IV - (505) 476-3460 Santa Fe, NM 87505 87505 | 6. State Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WEIGH, (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PEUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (PORM C-101) FOR SUCH | 7. Lease Name or Unit Agreement Name Red Hawk 32 State |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Disposal | 8. Well Number 2 |
| 2. Name of Operator | 9. OGRID Number 246368 |
| Basic Energy Services 3. Address of Operator | 10. Pool name or Wildcat |
| P.O. Box 1375 Artesia, NM 88210 | Delaware |
| 4. Well Location | |
| Unit Letter J: 1980 feet from the South line and | 1980 feet from the <u>East</u> line |
| Section 32 Township 19S Range 11. Elevation (Show whather DR RKB, RT, GR, etc. | 34E NMPM County Lea |
| 11. Lasvanda (anow whether 214 rates, 117, 014 and | 1 |
| 12. Check Appropriate Box to Indicate Nature of Notice, | Report or Other Data |
| NOTICE OF INTENTION TO: SUB | SEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR | |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR | = |
| PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN | TJOB [|
| DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM | |
| OTHER: | |
| | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an | |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co. | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an | |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co. | |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report. | mpletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co- proposed completion or recompletion. | mpletions: Attach wellbore diagram of |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report. | mpletions: Attach wellbore diagram of |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report. | mpletions: Attach wellbore diagram of |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report. Spud Date: Rig Release Date: | mpletions: Attach wellbore diagram of |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report. Spud Date: Rig Release Date: | mpletions: Attach wellbore diagram of |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledged SIGNATURE. TITLE Consultant | mpletions: Attach wellbore diagram of out |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report Rig Release Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledges SIGNATURE TYPE Consultant Type or print name Michael J.Johnson Bernall address: gaider61.johnson | mpletions: Attach wellbore diagram of out |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report in the information above is true and complete to the best of my knowledges of print name Michael Monagon E-mail address: raider61.johnse For State Use Only | mpletions: Attach wellbore diagram of out ort e and belief. DATE 03-09-2020 pm@att.net PHONE: (432)413-8981 |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Please see attached completion report, M.I.T. chart, and braden head report Rig Release Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledges SIGNATURE TYPE Consultant Type or print name Michael J. Johnson Bernall address: gaider61, johnson | mpletions: Attach wellbore diagram of out |

Red Hawk 32 State #2

Completion Report

| While bleeding annulus to frac tank, tubing communication noted. Pump 273 bbls 11 kill mud down tubing. Tubing and annulus pressure @ 200 psi 01-09-20 ND pumping tee. Unseat packer. LD injection string. Hole found in 3 collars of inject string 01-10-20 PU R8P and work packer. Set R8P @ 5619' (Bottom 7" liner 5622'). Set packer @ 50 (Top of liner @ 4989'). Conduct negative pressure test on liner. Liner OK 01-13-20 LD 7" packer. PU 8 5/8" packer. Packer would not go past 668'. Attempt to work 7 7 bit past spot @ 668' – no success 01-14-20 PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on R8P. PU 7 7/8" swage. Swage tagged up @ 35'. Work swage. No success 01-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' 01-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed 01-17-20 Test annular @ 2990', 2020, and 779'. All tests failed 01-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH wash to top of R8P. | 01-02-20 | Flowback 54 bbls PW to frac tank. Grease and work master valve |
|---|----------|---|
| Pump 124 bbls 11.6 ppg kill mud. Tubing on vacuum. Annular psi increased to 500 psi w/ gas noted O1-08-20 While bleeding annulus to frac tank, tubing communication noted. Pump 273 bbls 11 kill mud down tubing. Tubing and annulus pressure @ 200 psi O1-09-20 ND pumping tee. Unseat packer. LD injection string. Hole found in 3 collars of inject string O1-10-20 PU RBP and work packer. Set RBP @ 5619' (Bottom 7" liner 5622'). Set packer @ 50 (Top of liner @ 4989'). Conduct negative pressure test on liner. Liner OK O1-13-20 LD 7" packer. PU 8 5/8" packer. Packer would not go past 668'. Attempt to work 7.7 bit past spot @ 668' – no success O1-14-20 PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on RBP. PU 7.7/8" swage. Swage tagged up @ 35'. Work swage. No success O1-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' O1-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed O1-17-20 Test annular @ 2990', 2020, and 779'. All tests failed O1-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v bit. Wash to top of RBP. O1-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Clas Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RiH open- | 01-03-20 | Flowback 209 bbls PW (avg 35 bph) |
| w/ gas noted O1-08-20 While bleeding annulus to frac tank, tubing communication noted. Pump 273 bbls 11 kill mud down tubing. Tubing and annulus pressure @ 200 psi O1-09-20 ND pumping tee. Unseat packer. LD injection string. Hole found in 3 collars of inject string O1-10-20 PU RBP and work packer. Set RBP @ 5619' (Bottom 7" liner 5622'). Set packer @ 50 (Top of liner @ 4989'). Conduct negative pressure test on liner. Liner OK O1-13-20 LD 7" packer. PU 8 5/8" packer. Packer would not go past 668'. Attempt to work 7 7 bit past spot @ 668' — no success O1-14-20 PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on RBP. PU 7 7/8" swage. Swage tagged up @ 35'. Work swage. No success O1-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' O1-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed O1-17-20 Test annular @ 2990', 2020, and 779'. All tests failed O1-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v bit. Wash to top of RBP. O1-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Clas Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-06-20 | Flowback well. Set surface equipment. Unload kill mud |
| kill mud down tubing. Tubing and annulus pressure @ 200 psi 01-09-20 ND pumping tee. Unseat packer. LD injection string. Hole found in 3 collars of inject string 01-10-20 PU RBP and work packer. Set RBP @ 5619' (Bottom 7" liner 5622'). Set packer @ 50 (Top of liner @ 4989'). Conduct negative pressure test on liner. Liner OK 01-13-20 LD 7" packer. PU 8 5/8" packer. Packer would not go past 668'. Attempt to work 7 7 bit past spot @ 668' – no success 01-14-20 PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on RBP. PU 7 7/8" swage. Swage tagged up @ 35'. Work swage. No success 01-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' 01-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed 01-17-20 Test annular @ 2990', 2020, and 779'. All tests failed 01-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH will bit. Wash to top of RBP. 01-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Clas Neat. Estimated TOC @ 535' 01-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' 01-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. 01-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-07-20 | Pump 124 bbls 11.6 ppg kill mud. Tubing on vacuum. Annular psi increased to 500 psi w/ gas noted |
| O1-10-20 PU RBP and work packer. Set RBP @ 5619' (Bottom 7" liner 5622'). Set packer @ 50 (Top of liner @ 4989'). Conduct negative pressure test on liner. Liner OK O1-13-20 LD 7" packer. PU 8 5/8" packer. Packer would not go past 668'. Attempt to work 7 7 bit past spot @ 668' — no success O1-14-20 PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on RBP. PU 7 7/8" swage. Swage tagged up @ 35'. Work swage. No success O1-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' O1-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed O1-17-20 Test annular @ 2990', 2020, and 779'. All tests failed O1-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v bit. Wash to top of RBP. O1-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Clas Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RiH open- | 01-08-20 | While bleeding annulus to frac tank, tubing communication noted. Pump 273 bbls 11.6 kill mud down tubing. Tubing and annulus pressure @ 200 psi |
| (Top of liner @ 4989'). Conduct negative pressure test on liner. Liner OK 11-13-20 LD 7" packer. PU 8 5/8" packer. Packer would not go past 668'. Attempt to work 7 7 bit past spot @ 668' – no success 11-14-20 PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on RBP. PU 7 7/8" swage. Swage tagged up @ 35'. Work swage. No success 11-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' 11-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed 11-17-20 Test annular @ 2990', 2020, and 779'. All tests failed 11-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH will bit. Wash to top of RBP. 11-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Class Neat. Estimated TOC @ 535' 11-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' 11-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. 11-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-09-20 | ND pumping tee. Unseat packer. LD injection string. Hole found in 3 collars of injection string |
| bit past spot @ 668' – no success 01-14-20 PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on RBP. PU 7 7/8" swage. Swage tagged up @ 35'. Work swage. No success 01-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' 01-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed 01-17-20 Test annular @ 2990', 2020, and 779'. All tests failed 01-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v blt. Wash to top of RBP. 01-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Clas Neat. Estimated TOC @ 535' 01-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' 01-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. 01-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-10-20 | PU RBP and work packer. Set RBP @ 5619' (Bottom 7" liner 5622'). Set packer @ 5023' (Top of liner @ 4989'). Conduct negative pressure test on liner. Liner OK |
| 7/8" swage. Swage tagged up @ 35'. Work swage. No success 01-15-20 Wash thru sand bridge @ 35'. PU swage. Work thru tight spot f/ 668' to 686'. Run swage to TOL @ 4989' 01-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed 01-17-20 Test annular @ 2990', 2020, and 779'. All tests failed 01-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v blt. Wash to top of RBP. 01-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Class Neat. Estimated TOC @ 535' 01-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' 01-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. 01-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-13-20 | LD 7" packer. PU 8 5/8" packer. Packer would not go past 668'. Attempt to work 7 7/8" bit past spot @ 668' – no success |
| swage to TOL @ 4989' O1-16-20 PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed O1-17-20 Test annular @ 2990', 2020, and 779'. All tests failed O1-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v bit. Wash to top of RBP. O1-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Class Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-14-20 | PU 7 7/8" impression block. Marked on sides only. Dump 200 lbs sand on RBP. PU 7 7/8" swage. Swage tagged up @ 35'. Work swage. No success |
| O1-17-20 Test annular @ 2990', 2020, and 779'. All tests failed O1-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v bit. Wash to top of RBP. O1-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Class Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-15-20 | |
| O1-20-20 PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH v bit. Wash to top of RBP. O1-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Class Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-16-20 | PU 8 5/8" packer. Set 4969. Conduct negative pressure test on liner top. Test failed |
| bit. Wash to top of RBP. O1-21-20 Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Class Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-17-20 | Test annular @ 2990', 2020, and 779'. All tests failed |
| Neat. Estimated TOC @ 535' O1-22-20 Tag TOC @ 495'. Drill cement f/ 495 to 681' O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RiH open- | 01-20-20 | PU tension packer. Set @ 579'. Test annulus to 600 psi f/ 30 mins. Held good. RIH w/bit. Wash to top of RBP. |
| O1-23-20 PU 6 1/8" bit and install string mill 30' above bit. Drill cement f/ 681' to 703'. Mill collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RIH open- | 01-21-20 | Retrieve RBP. Wireline set CIBP @ 769'. Hesitate squeeze casing split w/ 350 sx Class C Neat. Estimated TOC @ 535 ' |
| collapsed casing f/ 680' to 684'. O1-24-20 Drill cement f/ 703' to 730 while milling collapsed casing f/ 684' to 686'. RiH open- | 01-22-20 | Tag TOC @ 495'. Drill cement f/ 495 to 681' |
| | 01-23-20 | · · · · · · · · · · · · · · · · · · · |
| | 01-24-20 | • |
| 01-27-20 Stand down due to weather | 01-27-20 | Stand down due to weather |
| 01-28-20 Stand down due to weather | 01-28-20 | Stand down due to weather |

Red Hawk Completion Report (Cont.)

| 01-29-20 | Drill cement f/ 337' to 682'. POOH |
|----------|---|
| 01-30-20 | Drill cement f/ 682' to 712'. POOH. Install string mill 30' above collars |
| 01-31-20 | Mill collapsed casing f/ 678' to 686'. Bit @ 712' |
| 02-03-20 | Mill collapsed casing f/ 686' to 687' (free-point) Drill cement to 738' (15') |
| 02-04-20 | Collapsed casing heaving pea gravel and cobble. Circulate hole clean. LD DC's |
| 02-07-20 | Finish LD tubing. Clean out reverse pit |
| 02-08-20 | RIH w/ CIBP. Set @ 617'. Release rig. Wait on FJ casing |
| 02-18-20 | RU pulling unit. |
| 02-19-20 | Wait on hydraulic BOP. Unpack wellhead. NU BOP |
| 02-20-20 | PU DC's and tubing. Tag CIBP @ 617'. Drill CIBP |
| 02-21-20 | Drill CIBP. Push CIBP to TOC @ 740'. Trip f/ bit |
| 02-24-20 | Drill CIBP, cement and bottom CIBP @ 740'. |
| 02-25-20 | Push/drill CIBP to 777'. Open-hole below. PU tubing to 1850. POOH to 600' |
| 02-26-20 | PU 3 %" tubing to TOL @ 4989'. Spot 270 bbls Brine. Trip to change bit size to 6 1/8" |
| 02-27-20 | RIH to liner top. Tag fill @ 4964' (25' above liner top). Clean off top of liner. RIH w/tubing to 5607' (shoe @ 5604'). POOH. RIH w/7" CBP. Set @ 5600' |
| 02-28-20 | RU & Run 124 jts 5 ½" 17# L-80. Tag fill @ 5492' LD 13 jts casing. Shoe @ 4962' |
| 02-29-20 | PU 13 jts casing. Wash f/ 5488' to 5557'. Circulate casing @ 5557' @ 3 bpm |
| 03-01-20 | Circulate casing @ 5557' @ 3 bpm |
| 03-02-20 | Circulate casing @ 5557' @ 3 bpm. ND BOP. Secure wellhead. Cement 5 ½" casing w/ 900 sx Class C Neat (Yield 1.32 @ 14.8 ppg). Circulate 30 sx cement to surface. WOC. Cut-off casing. Weld on bell nipple. NU BOP |
| 03-03-20 | PU 3 1/8" DC's and tubing. RIH. Tag cement @ 5478'. Drill cement, plug, and shoe track to 5573' |
| 03-04-20 | Stand down due to local flooding |
| 03-05-20 | Drill Redbed and river rock to 5604'. Drill CBP and push to 5607'. PU tubing to 5685'. Tag fill @ 5685'. Clean out open hole to 5715'. Kill well w/ 11.6 kill mud |
| 03-06-20 | Kill well w/ kill mud. LD work string and DC's. PU new production packer and new injection string. |

Red Hawk Completion Report (Cont.)

03-07-20

Finish run injection string. <u>Set packer @ 5553'</u>. Disengage on/off tool. Displace 70 bbls packer fluid down annulus. Reengage on/off tool. Set slips. Packoff wellhead. Install master valve.

03-09-20

Conduct M.I.T. w/ 590 psi; held 30 minutes; Test good.

Michael J. Johnson

Consultant

432-413-8981

Surface Casing: 13 3/8"; 54.5# K-55 @ 535' Intermediate Casing: 8 5/8", 32# K-55 @ 5255' Liner String: 7 ", 26# J-55 SJ-2 FJ f/ 4989' to 5622'

Liner String: 5 1/2" 17# L-80 @ 5557' Injection String: 3 1/2" 9.2# J-55 @ 5553'

Packer: Arrow Set 1-X w/ ON/Off Tool
Tbg Volume to Packer (0.0087) = 48.3 bbl
Ann. Volume to Packer (0.0113) = 63.0 bbl
Open hole Volume beneath packer (0.0609) = 107.5 bbl

Profile: 2.31 "F"

API 30-025-32003 Sec 32 T19S R34E Unit J 1980' FSL & 1980' FEL Lea Co., NM

RKB = 22'

17 1/2" Hole 13 3/8" 54.5# J-55 @ 535' Cmt circ to surface

12 1/2" Hole 8 5/8" 32# K-55 @ 5255' DV @ 3514'; Cmt circ to surface

7 7/8" hole 7" 26# J-55 Liner f/ 4989' to 5622' w/ Top Seal Off packer


5 1/2" 17# L-80 @ 5557" Cmt circ to surface

Open 7 7/8" hole f/ 5622' to 7318'

7 7/8" hole Top of Cut 5 1/2" 17# @ 7486'

Attempt FP & CUT 5 1/2" casing @ 8486' & 7926' Both attempts failed

7 7/8" hole TD @ 13,612'




AS1-X w/ on/off & 2.31 "F" profile @ 5553'

Injection Interval f/ 5610' to 8284'

Plug @ 7476' Tagged TOC @ 7316' Plug @ 7545' Tagged @ 7476'

Plug @ 8012' TOC @ 7709'

Plug @ 8536' TOC @ 8283' Top of Bone Springs @ 8284'



THE GREAT HAR CONTRACTOR

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

| | | Ope | erator Name | DENHE | irəi | LKEL | ĥĸi | | , | API Numbe | <u></u> |
|--|------------|------------|--|---------------------------------------|---------------|--|---------------|---------------|---------------|-------------------|---------------|
| BASIC Energy Property Name | | | | | 30-025-32003 | | | | | | |
| | | | | | | Well No. | | | | | |
| | MUL | }~ | STATE | | a Location | | | | | -7 -2 | |
| UL-Lot Section Township Range Feet from NS Line J 32 185 346 1980 5 | | | | | | ine | Feel Fro | | EAV Line | County | |
| <u> </u> | -1// | <u> </u> | - 100 h | | l Státus | | , , , , , | 7700 | ٠ | <u>u</u> | 1.604 |
| TA'D WELL | | SHU | T.IN | | JECTOR | | <u></u> | PRODUCEI | | | DATE |
| YES | NO | YES | NO | INJ " | | SWD | OIL | | | DATE | |
| | | (A)Sfor- | · · · · · · · · · · · · · · · · · · · | | VED DA | | (A) | | (D)D - 4 | | Lavrein |
| | | (A)Surface | | (B)Interm(1) | | (C) lete | HI/41 | | (D)Prod | - 2 08 | (E)Tubing |
| ressure | | | | _0 | | | | | | 2 | |
| low Characteristi | <u>C\$</u> | | 9 | | <u> </u> | <u> </u> | · | ·/·· | | | C02 |
| Puff | | Y //N | | Y | | | YYN | | L | CN | WTR_ |
| Steady Flow | · | Y 10 | <u></u> | Y / (N | | <u> </u> | YIZ | | | | GAS |
| Surges Down to nothing | | R | | Y (A) | | | Y/ 1 /Y/ 1 | | | NN | Type of Flaid |
| Gas or Oil | | Y 10 | <u> </u> | Y | <u> </u> | | Y/1 | | - | VAR Y | WaterDood If |
| Water | | YV | | YY | <u> </u> | | Y11 | | ļ. — | Y(1 N) = | |
| | | | 7 1 | | | / | | | l | · <u>····</u> | |
| | | | | | | 1 | | | | | |
| DWO | | | | | | | | · | | | |
| | | | | | | | | | | | |
| Signature: | | | ······································ | · · · · · · · · · · · · · · · · · · · | | <u> </u> | | 1 | IL CON | SERVAT | ON DIVISION |
| Signature: Printed name: | | | · · · · · · · · · · · · · · · · · · · | · · · · · · · · · · · · · · · · · · · | | | | 0 | | | ON DIVISION |
| · | | | • | : | | | | 0 | IL CON | | ON DIVISION |
| Printed name: | | | · · · · · · · · · · · · · · · · · · · | | | | | O: Entered | IL CON | | ON DIVISION |
| Printed name: Title: | | Ph | one: | | | | | O: Entered | IL CON | | ON DIVISION |

INSTRUCTIONS ON BACK OF THIS FORM