

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

<p>WELL API NO. 30-025-36355</p>	
<p>5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/></p>	
<p>6. State Oil & Gas Lease No.</p>	
<p>7. Lease Name or Unit Agreement Name Vacuum Grayburg San Andres Unit Well Number: 233</p>	
<p>9. OGRID Number 4323</p>	
<p>10. Pool name or Wildcat Vacuum; Grayburg San Andres</p>	
<p>11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,997' GL, 4,003' KB</p>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/></p>		<p>SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/></p>	
<p>OTHER: <input type="checkbox"/></p>		<p>OTHER: TEMPORARILY ABANDON <input type="checkbox"/></p>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 8-5/8" @ 1,535' TOC Surface, 5-1/2" @ 4,600' TOC Surface via CBL. Perforations: 4,366'-4,448'.

Chevron USA INC respectfully requests to abandon this well as follows:

1. Call and notify NMOCD 24 hrs before operations begin.
2. Pressure test casing t/ 1,000 psi f/ 15 minutes rig-less.
 - a. If tubing fails a pressure test, contact the engineer. This may generate a change in the procedure to lay down the tubing, setting CIBP, and allow CTU to plug the well.
3. MIRU pulling unit.
4. Check well pressures, kill well as necessary, perform bubble test on surface casing annuli, if bubble test fails Chevron intends to Zonite, cut and pull casing, or eliminate SCP with another means after the well is plugged to a certain point agreed upon by the NMOCD and Chevron.
5. N/U BOP and pressure test as per SOP.
 - a. 250 psi low, MASP or 1,000 psi for 5 minutes each (whichever is higher).
6. R/U wireline unit, pressure test lubricator t/ 500 psi for 10 minutes, run gauge ring, cut tubing at 4,255'.
 - a. If gauge ring does not make it to depth, contact engineer to discuss unsetting packer, laying down tubing, setting a CIBP to allow CTU to plug the well.
 - b. After cutting, verify tubing is free.
7. Spot 75 sx CL "C" cement f/ 4,255' t/ 3,515', WOC & tag (Perfs, Grayburg, Queen).
 - a. TOC must be at 3,663' or shallower.
 - b. Discuss pumping Jet Seal if circulation is not observed.
8. Pressure test casing t/ 1,000 psi f/ 15 minutes.
9. Spot MLF, subtracting cement volumes. Do not place MLF until casing pressure tests.
10. Spot 55 sx CL "C" cement f/ 3,197' t/ 2,654' (Yates).
 - a. TOC must be at 2,695' or shallower.
11. Spot 175 sx CL "C" cement f/ 1,710' t/ Surface (Salt, Shoe, FW).

See Attached
Conditions of Approval

12. Cut all casings & anchors & remove 3' below grade. Verify cement to surface & weld on dry hole marker (4" diameter, 4' tall). Clean location.

Note: All cement plugs class "C" (<7,500') or "H" (>7,500') with closed loop system used, and MLF spotted between plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Howie Lucas TITLE P&A Engineer, Attorney in fact DATE 03/12/2020

Type or print name Howie Lucas E-mail address: howie.lucas@chevron.com PHONE: (832)-588-4044

For State Use Only

APPROVED BY: Kenny Fort TITLE CC A DATE 3-13-20

Conditions of Approval (if any):

VGSAU #233 Wellbore Diagram

Created: 04/03/06 By: C. A. Irlie
 Updated: 2.22.2007 By: JDW
 Updated: 06/27/13 By: PTBP
 Lease: Vacuum Grayburg San Andres Unit
 Field: Vacuum Grayburg San Andres
 Surf. Loc.: 2630' FNL & 660' FEL
 Bot. Loc.:
 County: Lea St.: NM
 Status: TA'd Injection Well

Well #: 233 St. Lse:
 API: 30-025-36355
 Unit Ltr.: L Section: 1
 TSHP/Rng: S-18 E-34
 Unit Ltr.: Section:
 TSHP/Rng:
 Directions: Buckeye, NM
 Chevno: HL4987

Surface Casing

Size: 8 5/8"
 Wt., Grd.: 24# J-55
 Depth: 1,535'
 Sxs Cmt: 745
 Circulate: Yes, 80sx
 TOC: Surface
 Hole Size: 12 1/4"


KB: 4003'
 DF:
 GL: 3997'
 Ini. Spud: 08/13/03
 Ini. Comp.: 10/20/03

FORMATION TOPS:	
Rustler	1502
Salt	1660
Tansil	2701
Yates	2795
Seven Rivers	3147
Queen	3728
Grayburg	4056
San Andres	4342

Production Casing

Size: 5 1/2"
 Wt., Grd.: 15.5# J-55
 Depth: 4,600'
 Sxs Cmt: 1,030
 Circulate: Yes*
 TOC: Surface
 Hole Size: 8 3/4"

*Water cmt, well was flowing, CBL showed good bond below 4000'



8/13/03 Drill: Drl well, wtr flow 4500 @ 14 bph, 4600 @ 35 bph, called TD, wtr cmt circ.
10/13/03 Ini Comp: Perf 4 spf 90 ph 3 1/8 in. XPS Exp 4366-85, 4389-4417, 4425-48, RBP 4480, pkr 4324, acid 7000 gls 15% NEFE HCl 1750# RS, pkr 4311.
2/20/06 Frac: Csg pres, pkr not rel, tag 4391, jet cut tbg 4248, WP & shoe tag 4262, ret 3 jts, tag 4262, mill 4291 scale, 4302 pkr top, scale & met, circ clean, bump sub & jars 4260, latch fish, rel pkr no luck, jar fish no luck, shoe & WP 4293, mill metal & lot of cmt, ret piece of tbg, pkr 4199, test csg good, shoe & WP 4298-4309, ret nothing, tag 4309, mill 4315, cmt & met (csg), ret csg, bull nose mill 4315-20, ret duo tbg, shoe mill 4315-18 cmt, continue milling 4446, fill 4400-46, bull nose mill 4315-4446, shoe & WP 4315, no more, cone buster 4315-19, fell thru 4446, CO 4459, push junk 4491, taper mill 4315-51, pkr 4270, test BS good, pkr 4300 TP 6 jts, spot 300 gls acid, acid 700 gls 15% HCl, pkr 4268.
9/08: Tagged at 4349'. Pkr depth 4261'. PB depth 4556'. Perfs 4366-4448'. Fill 207'. Tagged from 4308-4349'.
10-16-08: Tagged 4349'. Fill 207'. Pkr depth 4261'. PBTD 4556'. Tagged from 4308-4349'.
10/09: MIT Failure. Packer corroded in two. Fished out bottom of packer. TIH w/ pkr and inj tbg and tag up at 4273'. TIH w/ bit and cleanout to 4281'. Circ scale, metal and FeS2. Run tbg and packer down to 4270'. Perform MIT test.
3/18/10: TA well with equipment in hole.

2-3/8" 4.7# J-55 tbg
 Pkr @ 4261' w/10' FL sub & SN below

Perfs: 4366'-4448'

Junk 4491'

PBTB: 4491'
 TD: 4600'

VGSAU #233 Wellbore Diagram


Created: 03/12/20 By: H Lucas
 Updated: _____ By: _____
 Updated: _____ By: _____
 Lease: Vacuum Grayburg San Andres Unit
 Field: Vacuum Grayburg San Andres
 Surf. Loc.: 2630' FNL & 660' FEL
 Bot. Loc.: _____
 County: Lea St.: NM
 Status: TA'd Injection Well

Well #: 233 St. Lse: _____
 API: 30-025-36355
 Unit Ltr.: L Section: 1
 TSHP/Rng: S-18 E-34
 Unit Ltr.: _____ Section: _____
 TSHP/Rng: _____
 Directions: Buckeye, NM
 Chevno: HL4987

Surface Casing

Size: 8 5/8"
 Wt., Grd.: 24# J-55
 Depth: 1,535'
 Sxs Cmt: 745
 Circulate: Yes, 80sx
 TOC: Surface
 Hole Size: 12 1/4"

KB: 4003'
 DF: _____
 GL: 3997'
 Ini. Spud: 08/13/03
 Ini. Comp.: 10/20/03



3 Spot cement across Salt t/ surface

2 Spot cement across Yates and 7 Rivers

1 Pressure test casing and tubing
 Cut above packer.
 Spot cement above, WOC & tag,
 pressure test
 2-3/8" 4.7# J-55 tbgr
 Pkr @ 4261' w/10' FL sub & SN below
 Perfs: 4366'-4448'

Junk 4491'

FORMATION TOPS:	
Rustler	1502
Salt	1660
Tansil	2701
Yates	2795
Seven Rivers	3147
Queen	3728
Grayburg	4056
San Andres	4342

Production Casing

Size: 5 1/2"
 Wt., Grd.: 15.5# J-55
 Depth: 4,600'
 Sxs Cmt: 1,030
 Circulate: Yes*
 TOC: Surface
 Hole Size: 8 3/4"

*Water cmt, well was flowing, CBL
 showed good bond below 4000'

PBTD: 4491'
 TD: 4600'

**CONDITIONS OF APPROVAL
FOR PLUGGING AND ABANDONMENT
OCD - Southern District**

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify **NMOCD District Office I (Hobbs) at (575)-263-6633** at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water will not be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least 1/4" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name
2. Lease and Well Number
3. API Number
4. Unit letter
5. Quarter Section (feet from the North, South, East or West)
6. Section, Township and Range
7. Plugging Date
8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION