Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office Energy Minerals and Natural Descurres	Revised July 18, 2013
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	30-025-33593
Bistrict III – (505) 334-6178 100 Biss Chronic Live Science Structure Store	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 7 2020 Santa Fe, NM 87505	STATE X FEE
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM AUG 27 2020 Santa Fe, NM 87505 87505	6. State Oil & Gas Lease No.
87505	312471
SUNDRY NOTICEOR NO EFORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPAGENTO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	SEMGSAU
1. Type of Well: Oil Well Gas Well Other INI	8. Well Number 908
2. Name of Operator	9. OGRID Number
CROSS TIMBERS ENERGY, LLC	298299
3. Address of Operator	10. Pool name or Wildcat
400 W 7TH STREET FORT WOTH, TX 76102	MALJAMAR; GRAYBURG- SAN ANDRES
4. Well Location	
Unit Letter A: 330 feet from the N line and 330 feet from the E line	
Section 32 Township 17-S Range 33-E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
4074 GL	
	· · · - · · ·
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	•
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🖾 PLUG AND ABANDON 🗌 REMEDIAL WOR	_
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	
PULL OR ALTER CASING D MULTIPLE COMPL CASING/CEMEN	ТЈОВ Ц
	-
CLOSED-LOOP SYSTEM	d give pertinent dates including estimated date
CLOSED-LOOP SYSTEM Image: Closed of the completed operation operation of the completed operation operatio	
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completed operations.	
CLOSED-LOOP SYSTEM Image: Closed of the completed operation operation of the completed operation operatio	
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer.	mpletions: Attach wellbore diagram of
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020	mpletions: Attach wellbore diagram of
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer.	mpletions: Attach wellbore diagram of
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine learning and packer.	mpletions: Attach wellbore diagram of k interval communicating to surface
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lear casing.	mpletions: Attach wellbore diagram of k interval communicating to surface
CLOSED-LOOP SYSTEM OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lear casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP.	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'.
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lear casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lear casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive.	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive.	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive.	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive.	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996 I hereby certify that the information above is true and complete to the best of my knowledge	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996 I hereby certify that the information above is true and complete to the best of my knowledge	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996	mpletions: Attach wellbore diagram of k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lear casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996 Rig Release Date: 10/16/1996 SIGNATURE Samantha Avasello TITLE Regulatory Technology Regulatory Technology	Attach wellbore diagram of Ak interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996 I hereby certify that the information above is true and complete to the best of my knowledge	Attach wellbore diagram of Ak interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996 I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE Samanntha Avarello Type or print name Samanntha Avarello	k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996 I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE Samanntha Avarello Type or print name Samanntha Avarello For State Use Only E-mail address: savarello@msg. APPROVED BY: Yeary	Attach wellbore diagram of Ak interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD
CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. MIRU est'd 9/15/2020 1. MIRU. POOH w/ tubing and packer. 2. Set RBP @ 4,195' (above perfs). Use plug & packer to determine lead casing. 3. Squeeze leak with Class C cement – volume pending leak depth, inj 4. Drill out cement, retrieve RBP. 5. RBIH w/ 2-3/8" IPC injection string and packer. Set packer at prev 6. L&T backside. Release from packer, circulate w/ packer fluid, latch and perform MIT per state representative's directive. Spud Date: 10/16/1996 I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE Samanntha Avarello Type or print name Samanntha Avarello	k interval communicating to surface ection rate & pressure into leak. WOC ious setting depth of 4,198'. back on to packer. Notify NMOCD