

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED:	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**Unknown**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Sunray DX Oil Company</b>	8. Farm or Lease Name <b>New Mexico "H" State</b>
3. Address of Operator <b>P. O. Box 1416, Roswell, New Mexico</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>M</b> <b>660</b> FEET FROM THE <b>West</b> LINE AND <b>660</b> FEET FROM THE <b>South</b> LINE, SECTION <b>8</b> TOWNSHIP <b>18S</b> RANGE <b>34E</b> NMPM.	10. Field and Pool, or Wildcat <b>E. K. Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4072 G.L.</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. T.D. 4404'. O.H. Comp. 4379-4404'. 5 1/2", 14#, J-55 csg. set @ 4379' w/150 sx. Top of cmt @ 3640 (temp. survey). 13 3/8" csg. @ 243' w/250 sx. Cmt. circulated to surface.
2. Pull rods, load hole w/mud.
3. Place 25 sx. cmt. plug w/tbg over Queen prod. form. 4404-4324'.
4. Cut off 5 1/2" csg. @ approx. 3600'.
5. Set 25 sx. cmt. plug in and out of 5 1/2" stub 3640-3560'.
6. Set 25 sx. cmt. plug over Yates 3240-3160'.
7. Set 25 sx. cmt. plug over salt section 3040-2960'.
8. Set 25 sx. cmt. plug over Rustler anhydrite 1780-1700'.
9. Place 25 sx. cmt. plug at base of 13 3/8" 243-218'.
10. Place 10 sx plug at surface and install dry hole marker.
11. Remove surface equipment and install dryhole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. F. Brawley B. F. Brawley TITLE District Engineer DATE 10-20-66

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: