



## Certificate of Analysis

Number: 6030-21060103-008A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Chandler Montgomery  
Occidental Petroleum  
1502 W Commerce Dr.  
Carlsbad, NM 88220

June 11, 2021

Field:	Turkey Track	Sampled By:	Javier Lazo
Station Name:	Turkey Track CTB Check A	Sample Of:	Gas Spot
Station Number:	14670A	Sample Date:	06/08/2021 02:15
Station Location:	CTB	Sample Conditions:	96 psia, @ 96 °F Ambient: 98 °F
Sample Point:	Meter	Effective Date:	06/08/2021 02:15
Formation:	Monthly	Method:	GPA-2261M
County:	Eddy	Cylinder No:	1111-001201
Type of Sample:	Spot-Cylinder	Instrument:	70104124 (Inficon GC-MicroFusion)
Heat Trace Used:	N/A	Last Inst. Cal.:	05/24/2021 0:00 AM
Sampling Method:	Fill and Purge	Analyzed:	06/11/2021 08:44:07 by KNF
Sampling Company:	:SPL		

## Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia	
Hydrogen Sulfide	0.000	0.000	0.000		GPM TOTAL C2+
Nitrogen	1.967	2.018	2.511		GPM TOTAL C3+
Methane	72.913	74.814	53.308		GPM TOTAL iC5+
Carbon Dioxide	0.237	0.243	0.475		
Ethane	11.489	11.789	15.745	3.148	
Propane	5.823	5.975	11.702	1.644	
Iso-butane	0.716	0.735	1.897	0.240	
n-Butane	1.838	1.886	4.869	0.594	
Iso-pentane	0.509	0.522	1.673	0.191	
n-Pentane	0.556	0.570	1.827	0.206	
Hexanes Plus	1.411	1.448	5.993	0.631	
	97.459	100.000	100.000	6.654	

Calculated Physical Properties	Total	C6+
Relative Density Real Gas	0.7803	3.2176
Calculated Molecular Weight	22.51	93.19
Compressibility Factor	0.9959	

**GPA 2172 Calculation:****Calculated Gross BTU per ft<sup>3</sup> @ 14.65 psia & 60°F**

Real Gas Dry BTU	1319	5113
Water Sat. Gas Base BTU	1297	5024
Ideal, Gross HV - Dry at 14.65 psia	1313.9	5113.2
Ideal, Gross HV - Wet	1290.9	5023.7
Net BTU Dry Gas - real gas	1199	
Net BTU Wet Gas - real gas	1178	

**Comments:** H2S Field Content 2.5 ppm  
Mcf/day 21793

Report generated by: Eric Ramirez

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

**EVENT SPECIFIC JUSTIFICATIONS FORM****Facility:** Turkey Track CTB**Start Date:** 08/01/2021 @ 08:30 AM**End Date:** 08/01/2021 @ 09:00 AM**Cause:** Compressor Malfunction > Sales Compressor Unit 3 & 4**Duration of event:** 30 minutes**Method of Flared Gas Measurement:** Flare Meter

---

**1. Reason why this event was beyond Operator's control:**

This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided or prevented by good design, operation, and preventative maintenance practices. Internal OXY procedures ensure that upon gas compressor unit and/or multiple unit shutdown, due to malfunction and/or alarms, production techs are promptly notified, and are instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions.

In this case, Oxy production tech determined that the cause of the malfunctions of NGSG gas compressor units #3 and #4 were due to compressor unit detonation based from an ECM malfunction alarm which happened simultaneously to both units. NGSG gas compressor units #3 & # 4 were working as designed and operated normally prior to the sudden and without warning malfunction due to ECM alarm malfunction. Oxy production techs quickly responded to the malfunction alarms of NGSG gas compressor units # 3 & # 4 and reset the alarm panels and restarted the units. Flaring ceased. During the time that NGSG gas compressor units # 3 & # 4 were down, OXY routed all the stranded sales gas to a flare with a 98% combustion efficiency in order to minimize emissions as much as possible. The flare is regularly monitored per the facility's General Construction Permit (GCP) requirements to ensure flame is lit and meeting opacity requirements.

**2. Steps Taken to limit duration and magnitude of venting or flaring:**

It is OXY's policy to route all stranded sales gas to a flare during a sudden, unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare at this facility has a 98% combustion efficiency in order to lessen emissions as much as possible. The flare is regularly monitored to ensure flame is lit and meeting opacity requirements.

In this case, the steps taken to limit duration and magnitude of flaring was for Oxy production techs to quickly respond to the malfunction alarms of NGSG gas compressor units # 3 & # 4 and reset the alarm panels and restart the units. Flaring ceased. During the time that NGSG gas compressor units # 3 & # 4 were down, OXY routed all the stranded sales gas to a flare with a 98% combustion efficiency

in order to minimize emissions as much as possible. The flare is regularly monitored per the facility's General Construction Permit (GCP) requirements to ensure flame is lit and meeting opacity requirements.

All OXY operations and facility equipment were running at maximized optimization prior to the sudden and unexpected compressor malfunctions occurring. This incident was completely out of Oxy's control to prevent from happening. OXY made every effort to control and minimize emissions as much as possible during this event.

### **3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:**

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to the ensure the flame is lit and meeting opacity requirements. Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of compressor malfunctions as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. This incident was completely out of OXY's control to prevent from happening as it was determined the malfunction occurred from an ECM malfunction alarm. Malfunction alarms can occur without warning and be true or false, yet, OXY makes every effort to control and minimize emissions as much as possible during these circumstances. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for these units.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

## State of New Mexico

### Energy, Minerals and Natural Resources

#### Oil Conservation Division

**1220 S. St Francis Dr.**

**Santa Fe, NM 87505**

QUESTIONS

Action 41791

#### QUESTIONS

Operator:  OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID:  16696
	Action Number:  41791
	Action Type:  [C-129] Venting and/or Flaring (C-129)

#### QUESTIONS

##### Determination of Reporting Requirements

*Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.*

Was or is this venting or flaring caused by an emergency or malfunction	Yes
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a notification of a major venting or flaring	Yes, minor venting or flaring of natural gas.
<i>The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 18 CFR 277.1000</i>	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

##### Unregistered Facility Site

*Please provide the facility details, if the venting or flaring occurred or is occuring at a facility that does not have an Facility ID (#) yet.*

Facility or Site Name	Not answered.
Facility Type	Not answered.

##### Equipment Involved

Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare>Compressor Malfunction > Sales Compressor Unit 3 & 4

##### Representative Compositional Analysis of Vented or Flared Natural Gas

*Please provide the mole percent for the percentage questions in this group.*

Methane (CH4) percentage	75
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

##### Date(s) and Time(s)

Date venting or flaring was discovered or commenced	08/01/2021
Time venting or flaring was discovered or commenced	08:30 AM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	08/01/2021
Time venting or flaring was terminated	09:00 AM
Total duration of venting or flaring in hours, if venting or flaring has terminated	0
Longest duration of cumulative hours within any 24-hour period during this event	0

##### Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Other   Other (Specify)   Natural Gas Flared   Spilled: 75 Mcf   Recovered: 0 Mcf   Lost: 75 Mcf ]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Flare Meter
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

##### Venting or Flaring Resulting from Downstream Activity

Was or is this venting or flaring a result of downstream activity	No
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

##### Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	See Justification Form>This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided or prevented by good design, operation, and preventative maintenance practices. Internal OXY procedures ensure that upon gas compressor unit and/or multiple unit shutdown, due to malfunction and/or alarms, production techs are promptly notified, and are instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions.
Steps taken to limit the duration and magnitude of venting or flaring	See Justification Form>It is OXY's policy to route all stranded sales gas to a flare during a sudden, unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare at this facility has a 98% combustion efficiency in order to lessen emissions as much as possible. The flare is regularly monitored to the ensure flame is lit and meeting opacity requirements.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	See Justification Form>Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of compressor malfunctions as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. This incident was completely out of OXY's control to prevent from happening.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**

**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 41791

**CONDITIONS**

Operator:  OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID:  16696
	Action Number:  41791
	Action Type:  [C-129] Venting and/or Flaring (C-129)

**CONDITIONS**

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	8/12/2021