



AKM MEASUREMENT SERVICES,LLC. Natural Gas Analysis Report
GPA 2172-09/API 14.5 Report with GPA 2145-16 Physical Properties

Sample Information	
Sample Name	LOST TANK 18 FACILITY PROD 2
Technician	ANTHONY DOMINGUEZ
Analyzer Make & Model	INFICON MICRO GC
Last Calibration/Validation Date	12-15-2023
Meter Number	16412P
Air temperature	59
Flow Rate (MCF/Day)	19315
Heat Tracing	HEATED HOSE & GASIFIER
Sample description/mtr name	LOST TANK 18 FACILITY PROD 2
Sampling Method	FILL & EMPTY
Operator	OCCIDENTAL PETROLEUM, OXY USA INC
State	NEW MEXICO
Region Name	PERMIAN_RESOURCES
Asset	NEW MEXICO
System	LOST TANK
FLOC	OP-DELNE-BT010
Sample Sub Type	CTB
Sample Name Type	METER
Vendor	AKM MEASUREMENT
Cylinder #	38967
Sampled by	SCOTT
Sample date	12-11-2023
Analyzed date	12-19-2023
Method Name	C9
Injection Date	2023-12-19 17:22:49
Report Date	2023-12-19 17:24:34
EZReporter Configuration File	1-16-2023 OXY GPA C9+ H2S #2.cfgx
Source Data File	c9df624d-557a-4940-b08e-304ec2186c4a
NGA Phys. Property Data Source	GPA Standard 2145-16 (FPS)
Data Source	INFICON Fusion Connector

Component Results

Component Name	Peak Area	Raw Amount	Response Factor	Norm Mole%	Gross HV (Dry) (BTU / Ideal cu.ft.)	Relative Gas Density (Dry)	GPM (Dry) (Gal. / 1000 cu.ft.)
Nitrogen	33914.5	1.9299	0.00005691	1.9234	0.0	0.01860	0.212
Methane	970996.0	70.7503	0.00007286	70.5121	713.8	0.39057	12.003
CO2	27471.0	1.3080	0.00004761	1.3036	0.0	0.01981	0.223
Ethane	291718.9	13.4465	0.00004609	13.4012	237.7	0.13913	3.599
H2S	0.0	0.0000	0.00000000	0.0000	0.0	0.00000	0.000
Propane	234132.9	7.6719	0.00003277	7.6461	192.8	0.11641	2.115
iso-butane	91468.0	1.0116	0.00001106	1.0082	32.9	0.02023	0.331
n-Butane	233710.5	2.5698	0.00001100	2.5611	83.7	0.05140	0.811
iso-pentane	50142.9	0.4900	0.00000977	0.4883	19.6	0.01216	0.179
n-Pentane	56869.7	0.5337	0.00000938	0.5319	21.4	0.01325	0.194
hexanes	36640.0	0.3612	0.00000986	0.3600	17.2	0.01071	0.149
heptanes	31543.0	0.1905	0.00000604	0.1899	10.5	0.00657	0.088
octanes	12956.0	0.0696	0.00000537	0.0694	4.3	0.00274	0.036
nonanes+	1475.0	0.0048	0.00000326	0.0048	0.3	0.00021	0.003
Total:		100.3379		100.0000	1334.2	0.80179	19.943

Results Summary

Result	Dry	Sat.
Total Un-Normalized Mole%	100.3379	
Pressure Base (psia)	14.730	
Temperature Base (Deg. F)	60.00	
Relative Humidity	83.3	

Result	Dry	Sat.
Flowing Pressure (psia)	100.2	
Gross Heating Value (BTU / Ideal cu.ft.)	1334.2	1311.0
Gross Heating Value (BTU / Real cu.ft.)	1340.0	1317.3
Relative Density (G), Real	0.8049	0.8022

Monitored Parameter Report

Parameter	Value	Lower Limit	Upper Limit	Status
Total un-normalized amount	100.3379	97.0000	103.0000	Pass



UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM

Facility Id# fAPP2226965761

Operator: OXY USA, Inc.

Facility: Lost Tank 18 CPF

Flare Date: 06/09/2025

Duration of Event: 1 Hour 9 Minutes

MCF Flared: 376

Start Time: 10:50 PM

End Time: 11:59 PM

Cause: Emergency Flare > Severe Weather Condition > Thunderstorms & Lightning > Lost Tank 5 CGL > Weather Induced Power Outage > Equipment Malfunctions

Method of Flared Gas Measurement: Gas Flare Meter

1. Reason why this event was beyond Operator's control:

This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program. In this case, severe thunderstorms and lightning caused equipment issues at the Lost Tank 5 CGL due to a weather-induced power outage. As a result of the severe weather conditions, the electric compression equipment at Lost Tank 5 CGL automatically shut down when the area, including the facility, lost power, which in turn increased field pressure and triggered a flaring event at the Lost Tank 18 CPF. Once the thunderstorm and lightning subsided, and power was restored to the area and the facility, OXY production technicians conducted an initial inspection of the Lost Tank 5 CGL facility. OXY production technicians discovered that they were unable to restart the electric compression equipment, and it was subsequently determined that some fuses in the Lost Tank 5 CGL RIO cabinet had shorted out due to a small amount of rainwater leaking into the cabinet from a piece of conduit and therefore, communication to the electric compression equipment was not occurring for a restart of the equipment. Upon being notified that the electric compression equipment at the Lost Tank 5 CGL could not be restarted, the production technicians at the Lost Tank 18 CPF immediately began shutting in several high GOR wells. This action was taken to reduce field pressure and ensure it remained below the flare trigger setpoints of the Lost Tank 18 CPF, thereby ceasing flaring activities. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. The occurrence of this event was beyond OXY's control. OXY took all possible measures to manage and reduce emissions to the greatest extent.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. In this case, severe thunderstorms and lightning caused equipment issues at the Lost Tank 5 CGL due to a weather-induced power outage. As a result of the severe weather conditions, the electric compression equipment at Lost Tank 5 CGL automatically shut down when the area, including the facility, lost power, which in turn increased field pressure and triggered a flaring event at the Lost Tank 18 CPF. Once the thunderstorm and lightning subsided, and power was restored to the area and the facility, OXY production technicians conducted an initial inspection of the Lost Tank 5 CGL facility. OXY production technicians discovered that they were unable to restart the electric compression equipment, and it was

subsequently determined that some fuses in the Lost Tank 5 CGL RIO cabinet had shorted out due to a small amount of rainwater leaking into the cabinet from a piece of conduit and therefore, communication to the electric compression equipment was not occurring for a restart of the equipment. Upon being notified that the electric compression equipment at the Lost Tank 5 CGL could not be restarted, the production technicians at the Lost Tank 18 CPF immediately began shutting in several high GOR wells. This action was taken to reduce field pressure and ensure it remained below the flare trigger setpoints of the Lost Tank 18 CPF, thereby ceasing flaring activities. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. This event is out of OXY's control yet OXY made every effort to control and minimize emissions as much as possible.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in its corrective actions to eliminate the cause and recurrence of weather induced power outages during severe and intense weather circumstances as this is out of Oxy's control to avoid or prevent from reoccurring. The only action available to Oxy and its personnel in severe weather circumstances is to be pro-active and take precautionary measures prior to known severe weather conditions by securing equipment, and focusing on overall safety, communication and operational adjustments, if possible, during and after this event. Oxy is committed to maintaining and operating its equipment in accordance with best practices to minimize emissions and reduce the frequency of emission events. By prioritizing efficiency and safety, Oxy aims to promptly address sudden and unexpected flaring situations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 478516

DEFINITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 478516
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 478516

QUESTIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 478516
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites	
<i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	Unavailable.
Incident Facility	[fAPP2226965761] Lost Tank 18 CPF

Determination of Reporting Requirements	
<i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Severe Weather Condition > Thunderstorms & Lightning > Lost Tank 5 CGL > Weather Induced Power Outage > Equipment Malfunctions

Representative Compositional Analysis of Vented or Flared Natural Gas	
<i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	71
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 478516

QUESTIONS (continued)

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 478516
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	06/09/2025
Time vent or flare was discovered or commenced	10:50 PM
Time vent or flare was terminated	11:59 PM
Cumulative hours during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	<i>Not answered.</i>
Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 376 Mcf Recovered: 0 Mcf Lost: 376 Mcf.
Other Released Details	<i>Not answered.</i>
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	<i>Not answered.</i>
Downstream OGRID that should have notified this operator	<i>Not answered.</i>
Date notified of downstream activity requiring this vent or flare	<i>Not answered.</i>
Time notified of downstream activity requiring this vent or flare	<i>Not answered.</i>

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program. In this case, severe thunderstorms and lightning caused equipment issues at the Lost Tank 5 CGL due to a weather-induced power outage. As a result of the severe weather conditions, the electric compression equipment at Lost Tank 5 CGL automatically shut down when the area, including the facility, lost power, which in turn increased field pressure and triggered a flaring event at the Lost Tank 18 CPF. Once the thunderstorm and lightning subsided, and power was restored to the area and the facility, OXY production technicians conducted an initial inspection of the Lost Tank 5 CGL facility. OXY production technicians discovered that they were unable to restart the electric compression equipment, and it was subsequently determined that some fuses in the Lost Tank 5 CGL RIO cabinet had shorted out due to a small amount of rainwater leaking into the cabinet from a piece of conduit and therefore, communication to the electric compression equipment was not occurring for a restart of the equipment. Upon being notified that the electric compression equipment at the Lost Tank 5 CGL could not be restarted, the production technicians at the Lost Tank 18 CPF immediately began shutting in several high GOR wells. This action was taken to reduce field pressure and ensure it remained below the flare trigger setpoints of the Lost Tank 18 CPF, thereby ceasing flaring activities.

<p>Steps taken to limit the duration and magnitude of vent or flare</p>	<p>It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. In this case, severe thunderstorms and lightning caused equipment issues at the Lost Tank 5 CGL due to a weather-induced power outage. As a result of the severe weather conditions, the electric compression equipment at Lost Tank 5 CGL automatically shut down when the area, including the facility, lost power, which in turn increased field pressure and triggered a flaring event at the Lost Tank 18 CPF. Once the thunderstorm and lightning subsided, and power was restored to the area and the facility, OXY production technicians conducted an initial inspection of the Lost Tank 5 CGL facility. OXY production technicians discovered that they were unable to restart the electric compression equipment, and it was subsequently determined that some fuses in the Lost Tank 5 CGL RIO cabinet had shorted out due to a small amount of rainwater leaking into the cabinet from a piece of conduit and therefore, communication to the electric compression equipment was not occurring for a restart of the equipment. Upon being notified that the electric compression equipment at the Lost Tank 5 CGL could not be restarted, the production technicians at the Lost Tank 18 CPF immediately began shutting in several high GOR wells. This action was taken to reduce field pressure and ensure it remained below the flare trigger setpoints of the Lost Tank 18 CPF, thereby ceasing flaring activities. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel.</p>
<p>Corrective actions taken to eliminate the cause and reoccurrence of vent or flare</p>	<p>Oxy is limited in its corrective actions to eliminate the cause and recurrence of weather induced power outages during severe and intense weather circumstances as this is out of Oxy's control to avoid or prevent from reoccurring. The only action available to Oxy and its personnel in severe weather circumstances is to be pro-active and take precautionary measures prior to known severe weather conditions by securing equipment, and focusing on overall safety, communication and operational adjustments, if possible, during and after this event. Oxy is committed to maintaining and operating its equipment in accordance with best practices to minimize emissions and reduce the frequency of emission events. By prioritizing efficiency and safety, Oxy aims to promptly address sudden and unexpected flaring situations.</p>

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 478516

ACKNOWLEDGMENTS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 478516
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
<input checked="" type="checkbox"/>	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 478516

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 478516
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	6/24/2025