Office	1.8:16:30 PM	State of N	New Me	xico		Form	C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM		Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505			WELL API N	Revised July 1	
<u>District II</u> - (575) 748-1283					30-015-24355 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.		
811 S. First St., Artesia, NM 882 <u>District III</u> – (505) 334-6178	.10						
1000 Rio Brazos Rd., Aztec, NM	[87410						
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe. 87505						ź Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Nan	ne or Unit Agreement N	Jame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					New Mexico (O State Com	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other					8. Well Num	ber 1	
2. Name of Operator XTO Energy, Inc.					9. OGRID N 005380	umber	
3. Address of Operator					10. Pool nam	e or Wildcat	
64001 Holiday Hill rd BLDG #5, Midland TX 79707					Palmillo; Bon		
4. Well Location							
Unit Letter G	: 1980	feet from the	-			t from the East	line
Section 12	11 I	Township ¹⁹ Elevation <i>(Show whe</i>		nge _{28E}	NMPM	County _{Eddy}	
	11.1	Sievation (Snow whe	einer DR,	KKB, KI, GR, eld	:.)		
12. (Check Approp	priate Box to Ind	licate N	ature of Notice	, Report or Ot	her Data	
NOTICE		TION TO:		SUE	BSEQUENT	REPORT OF:	
PERFORM REMEDIAL W		G AND ABANDON	ĸ	REMEDIAL WO			IG 🗌
TEMPORARILY ABANDO		NGE PLANS		COMMENCE DF	RILLING OPNS.[x
PULL OR ALTER CASING	G 🗌 MUL	TIPLE COMPL		CASING/CEMEN	лт јов 🛛 🗌]	
DOWNHOLE COMMINGL					Notify OCD	24 hrs. prior to any work	
CLOSED-LOOP SYSTEM			_		done		
OTHER: 13. Describe proposed	an accordiate d a	nonstions (Closely		OTHER:	nd airean antinant	datas includina astima	
	posed work). S	EE RULE 19.15.7.1				ich wellbore diagram of	
XTOEnergy, Inc. Respectfully su	1		11				
		for plugging.					
1) MIRU plugging company. Se		1 00 0					
2) ND WH and NU 5K manual l	BOP. Function test	BOP.					
 ND WH and NU 5K manual I MIRU WL, RIH 2-3/8" WS a 	BOP. Function test	BOP. 50'.					
2) ND WH and NU 5K manual l	BOP. Function test and tag PBTD at 7,7 25 sxs Class C cmt	BOP. 50'. t. (T/Bone Spring)					
 ND WH and NU 5K manual 1 MIRU WL, RIH 2-3/8" WS a PUH w/tbg to 5,649' and spot PUH w/tbg to 3,387' and spot POOH w/ tbg. RIH WL. Perf 	BOP. Function test and tag PBTD at 7,7 : 25 sxs Class C cmt : 25 sxs Class C cmt f 5-1/2" csg at 3,050	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware)	ass C				
 ND WH and NU 5K manual 1 MIRU WL, RIH 2-3/8" WS a PUH w/tbg to 5,649' and spot PUH w/tbg to 3,387' and spot 	BOP. Function test and tag PBTD at 7,7 25 sxs Class C cmt 25 sxs Class C cmt f 5-1/2" csg at 3,050 . (8-5/8" csg shoe)	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla		until TOC at Surface.	(Surface Plug)		
 ND WH and NU 5K manual 1 MIRU WL, RIH 2-3/8" WS a PUH w/tbg to 5,649' and spot PUH w/tbg to 3,387' and spot POOH w/ tbg. RIH WL. Perf cmt. WOC & Tag at least 2,900'. 	BOP. Function test and tag PBTD at 7,7 25 sxs Class C cmt 25 sxs Class C cmt f 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla sg at 415' and squeeze C		until TOC at Surface.	(Surface Plug)		
 2) ND WH and NU 5K manual 1 3) MIRU WL, RIH 2-3/8" WS a 4) PUH w/tbg to 5,649' and spot 5) PUH w/tbg to 3,387' and spot 6) POOH w/ tbg. RIH WL. Perf cmt. WOC & Tag at least 2,900'. 7) POOH w/tbg. RU WL, and R 8) ND BOP and cut off wellhead 	BOP. Function test and tag PBTD at 7,7 25 sxs Class C cmt 25 sxs Class C cmt f 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla sg at 415' and squeeze C RDMO Well PA'd	lass C cmt	[(Surface Plug)		
 2) ND WH and NU 5K manual 1 3) MIRU WL, RIH 2-3/8" WS a 4) PUH w/tbg to 5,649' and spot 5) PUH w/tbg to 3,387' and spot 6) POOH w/ tbg. RIH WL. Perf cmt. WOC & Tag at least 2,900'. 7) POOH w/tbg. RU WL, and R 8) ND BOP and cut off wellhead 	BOP. Function test and tag PBTD at 7,7 25 sxs Class C cmt 25 sxs Class C cmt f 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla sg at 415' and squeeze C RDMO Well PA'd		[(Surface Plug)		
 ND WH and NU 5K manual 1 MIRU WL, RIH 2-3/8" WS a PUH w/tbg to 5,649' and spot PUH w/tbg to 3,387' and spot POOH w/ tbg. RIH WL. Perf Cmt. WOC & Tag at least 2,900'. POOH w/tbg. RU WL, and R ND BOP and cut off wellhead 	BOP. Function test and tag PBTD at 7,7 : 25 sxs Class C cmt : 25 sxs Class C cmt f 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs d 5' below surface. I	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla sg at 415' and squeeze C RDMO Well PA'd Rig Ro	lass C cmt	te:	(Surface Plug) gged by 10/28	/2022	
 2) ND WH and NU 5K manual 1 3) MIRU WL, RIH 2-3/8" WS a 4) PUH w/tbg to 5,649' and spot 5) PUH w/tbg to 3,387' and spot 6) POOH w/ tbg. RIH WL. Perf cmt. WOC & Tag at least 2,900'. 7) POOH w/tbg. RU WL, and R 8) ND BOP and cut off wellhead Spud Date: 	BOP. Function test and tag PBTD at 7,7 : 25 sxs Class C cmt : 25 sxs Class C cmt f 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs d 5' below surface. I CHED COA's*	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware) ' and squeeze 40 sxs Cla sg at 415' and squeeze C RDMO Well PA'd Rig Ro ****	lass C cmt elease Da	te: <mark>(Must be plu</mark>	gged by 10/28	/2022	
 2) ND WH and NU 5K manual 1 3) MIRU WL, RIH 2-3/8" WS a 4) PUH w/tbg to 5,649' and spot 5) PUH w/tbg to 3,387' and spot 6) POOH w/ tbg. RIH WL. Perf cmt. WOC & Tag at least 2,900'. 7) POOH w/tbg. RU WL, and R 8) ND BOP and cut off wellhead Spud Date: ****SEE ATTAC I hereby certify that the information of the second sec	BOP. Function test 1 and tag PBTD at 7,7 25 sxs Class C cmt 25 sxs Class C cmt 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs 1 5' below surface. 1 CHED COA's* ormation above 1	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla sg at 415' and squeeze C RDMO Well PA'd Rig Ro **** is true and complete	elease Da e to the be	te: <mark>(Must be plu</mark>	gged by 10/28		
 2) ND WH and NU 5K manual 1 3) MIRU WL, RIH 2-3/8" WS a 4) PUH w/tbg to 5,649' and spot 5) PUH w/tbg to 3,387' and spot 6) POOH w/ tbg. RIH WL. Perf cmt. WOC & Tag at least 2,900'. 7) POOH w/tbg. RU WL, and R 8) ND BOP and cut off wellhead Spud Date: (****SEE ATTAC I hereby certify that the info SIGNATURE	BOP. Function test and tag PBTD at 7,7 25 sxs Class C cmt 25 sxs Class C cmt f 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs d 5' below surface. I CHED COA's* prmation above :	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla sg at 415' and squeeze C RDMO Well PA'd Rig Ro **** is true and complete 	lass C cmt elease Da e to the be <u>E Re</u> g	te: (Must be plu est of my knowled gulatory Analyst	gged by 10/28 ge and belief.	_DATE10/11/2021	
 2) ND WH and NU 5K manual I 3) MIRU WL, RIH 2-3/8" WS a 4) PUH w/tbg to 5,649' and spot 5) PUH w/tbg to 3,387' and spot 6) POOH w/ tbg. RIH WL. Perf cmt. WOC & Tag at least 2,900'. 7) POOH w/tbg. RU WL, and R 8) ND BOP and cut off wellhead Spud Date: ****SEE ATTAC I hereby certify that the info SIGNATURE	BOP. Function test 1 and tag PBTD at 7,7 25 sxs Class C cmt 25 sxs Class C cmt 5-1/2" csg at 3,050 . (8-5/8" csg shoe) IH WL. Perf 5.5" cs 1 5' below surface. 1 CHED COA's* ormation above 1	BOP. 50'. t. (T/Bone Spring) t. (T/Delaware))' and squeeze 40 sxs Cla sg at 415' and squeeze C RDMO Well PA'd Rig Ro **** is true and complete 	elease Da e to the be	te: (Must be plu est of my knowled gulatory Analyst	gged by 10/28		571

•

Released	to	Imaging:	10/29/2021 7:	58:59 AM
			TOURS LEADER LAND	COTOS TATIA

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K)Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name2. Lease and Well Number3. API Number4. Unit Letter5. QuarterSection (feet from the North, South, East or West)6. Section, Township and Range7. Plugging Date8. County(SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S – R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S – R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A- F. Sec 27 Unit A,B,C,F,G,H.

T 19S – R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S – R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S – R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S – R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 20 – 29. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S – R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S – R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S – R 30E

Sec 1 – Sec 36

T 21S – R 31E

Sec 1 – Sec 36

T 22S – R 28E

Sec 36 Unit A,H,I,P.

T 22S – R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S – R 30E

Sec 1 – Sec 36

T 22S – R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,B,C,D,G,H. Sec 27 – Sec 34.

T 23S – R 28E

Sec 1 Unit A

T 23S – R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S – R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S – R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S – R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.


T 24S – R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S – R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

New Mexico O State Com 001 - Current and Proposed WBD's



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
XTO PERMIAN OPERATING LLC.	373075
6401 HOLIDAY HILL ROAD	Action Number:
MIDLAND, TX 79707	58040
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	10/28/2021

CONDITIONS

Page 7 of 7

.

Action 58040