<i>Cerved by UCD: 2/27/2022 7:02:15 AM</i> J.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Report 04/27/2022
Well Name: PRONGHORN SWD	Well Location: T19S / R32E / SEC 24 / NWNE /	County or Parish/State: LEA / NM
Well Number: 1	Type of Well: OTHER	Allottee or Tribe Name:
Lease Number: NMNM86144	Unit or CA Name:	Unit or CA Number:
US Well Number: 3002532735	Well Status: Water Disposal Well	Operator: SPUR ENERGY PARTNERS LLC

Notice of Intent

Sundry ID: 2668406 Type of Submission: Notice of Intent Date Sundry Submitted: 04/25/2022 Date proposed operation will begin: 04/30/2022

Type of Action: Workover Operations Time Sundry Submitted: 10:27 0

Procedure Description: Please find procedure and WBDs attached for your use.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Pronghorn_SWD_1__Current__Proposed_WBD__Wellview_History_20220425102639.pdf

Pronghorn_SWD___HIT_Packer_Leak_Procedure_20220425102639.pdf

Accepted for Record Only



7

NMOCD 4/28/22

Received by OCD: 4/27/2022 7:02:15 AM Well Name: PRONGHORN SWD	Well Location: T19S / R32E / SEC 24 / NWNE /	County or Parish/State: LEA/
Well Number: 1	Type of Well: OTHER	Allottee or Tribe Name:
Lease Number: NMNM86144	Unit or CA Name:	Unit or CA Number:
US Well Number: 3002532735	Well Status: Water Disposal Well	Operator: SPUR ENERGY PARTNERS LLC

Conditions of Approval

Specialist Review

Workover_or_Vertical_Deepen_COA_20220426154851.pdf

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: SARAH CHAPMAN Name: SPUR ENERGY PARTNERS LLC

Title: Regulatory Directory

Street Address: 9655 KATY FREEWAY, SUITE 500

City: Houston

Phone: (832) 930-8613

Email address: SCHAPMAN@SPUREPLLC.COM

Field Representative

Representative Name: Street Address:

City:

Phone:

Email address:

State:

State: TX

Zip:

Signed on: APR 25, 2022 10:26 AM

BLM Point of Contact

BLM POC Name: Jonathon W Shepard BLM POC Phone: 5752345972 Disposition: Approved Signature: Jonathon Shepard

BLM POC Title: Petroleum Engineer BLM POC Email Address: jshepard@blm.gov

Disposition Date: 04/26/2022

Pronghorn SWD #1 Lea County, NM API# 30-025-32735

Hole in Tubing / Packer Leak

Objective

This well has a suspected hole in tubing or packer leak due to pressure on the casing. It is proposed to pull and hydrotest tubing and replace any leaking joints. It is also proposed to run a new packer. The well was last pulled in 2018 for a hole in tubing; the top 8 joints were found to have 4 holes and were replaced.


Procedure

- 1. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Lea County, call 575-393-3612.
- 2. Move in rig up pulling unit, laydown machine, and casing crew.
- 3. Nipple up BOP.
- 4. Pull 4-1/2" BTC Glassbore Tubing and lay down on pipe racks.

Tubing Detail (10/25/2018)


10' KB 77 jts 4½'' BTC glassbore tbg (3179') On/off tool w/ 2.25" F Profile 7" x 3½" Nickel Plated as1-x packer @ +/- 3,200'?

- 5. Pick up bit and scraper and 2-7/8" workstring. Run in hole to 3,300' and pull out of hole.
- 6. Run in hole with test packer and set at +/- 3,200'. Load and test casing to 500 psi for 15 mins.
- 7. Pull out of hole laying down workstring.
- 8. Rig up casing crew. Run in hole with new 7" x 3-1/2" Nickel-plated AS1-X Packer with On/Off Tool with 2.25" F profile and pump-out plug, and 77 joints 4-1/2" BTC Glassbore Tubing.
 - a. Hydrotest tubing to 3,000 psi below the slips
 - b. Install new seals
 - c. Replace bad tubing as necessary with new 4-1/2" BTC Glassbore tubing.
- 9. Set packer at +/- 3,200' (same depth as before).
- 10. Load and test casing to 500 psi for 15 mins.
- 11. Get off on/off tool. Circulate packer fluid. Engage on/off tool.
- 12. Load and test casing to 500 psi for 30 mins.
- 13. Nipple up wellhead. Pressure up on tubing and pump out plug.
- 14. Rig down pulling unit.
- 15. Notify BLM & NMOCD to witness MIT.



CREATED ON 6/28/2021 UPDATED ON 4/25/2022

SPUD DATE: 3/5/1995 ELEV: 3620' GL, 3630' KB



PROPOSED WBD

CREATED ON 6/28/2021 UPDATED ON 4/25/2022

Received by OCD: 4/27/2022 7:02:15 AM Daily Operations

5, drill 14 7/8" surface hole to 1080ft., run 26 joints (1083') 10 3/4" 40.5# & 45.5#, Jottross 1080', cement with 600 sx Pacesetter Lite & 200 sx Class C, Circulated 200 sx. to surface, bump C NUBOP. Test casing and BOP to 1000PSI for 30 min. held OK. th 9 7/8" bit, to 3300'. Run 107 jts. (3304') 7" 23# & 26# K-55 ST&C csg. FS @ 3300', Cement with) sx Class C, circulated 160 sx. to surface. WOC Test casing and BOP to 1000PSI for 30 min. Drill 6 g 10:00AM 3-15-95. Tubing @ 3226' with Baker Model AD-1 Packer @ 3226 (Nickel Plated) packer fluid on backside and % NEFE. lown 3 1/2" tubing 1000 gals. 15% HCL Pentol 100 with 2 gals CI-22, 6 gal FE 270, 2 gal FE Pentofax 2, went on a vaccum and chase with 10 bbls. of fresh water. ed filters and hot watered pot to clean any paraffin in tubes, hook back up, only would take 2000bbls. ice and pump down 3 1/2" tubing 2500 gals. 15% HCL Pentol 100 with 5 gals. CI-22, 14 gal. FE 270, nd 60 gal. Pentofac 2, went on vaccuum and chase with 10 bbls. fresh water, let set 1 hour, turn i Acid down tubing, hook up pump to well displace water, running 110# and pumping at rate of 4500 mackside, pumping in at 110# at 4500 BPD, 160 gals. per min. leaking out backside of about 1 1/2 well goes back on vaccuum and backside goes back down, turn pump on well on backside flows. POH w/22 & f 3/4 jts. Shut down. th. RU reverse unit & clean out down to tbg. Fish & POH w/2 jts & 10'. RIH w/3 1/2" grapple. RIH w/3 1 to tbg. 8 jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. 1% NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. 26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 1 30 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. ed off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) 1, found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @	End Date	Start Date
 ax Class C. circulated 160 sx. to surface. WOC Test casing and BOP to 1000PSI for 30 min. Drill 6 g 10:00AM 3-15-95. Tubing @ 3226' with Baker Model AD-1 Packer @ 3226 (Nickel Plated) packer fluid on backside and % NEFE. lown 3 1/2" tubing 1000 gals. 15% HCL Pentol 100 with 2 gals Cl-22, 6 gal FE 270, 2 gal FE 2entofax 2, went on a vaccum and chase with 10 bbls. of fresh water. ad filters and hot watered pot to clean any paraffin in tubes, hook back up, only would take 2000bbls. ice and pump down 3 1/2" tubing 2500 gals. 15% HCL Pentol 100 with 5 gals. Cl-22, 14 gal. FE 270, nd 60 gal. Pentofac 2, went on vaccuum and chase with 10 bbls. fresh water, let set 1 hour, turn and 60 gal. Pentofac 2, went on vaccuum and chase with 10 bbls. fresh water, let set 1 hour, turn Acid down tubing, hook up pump to well displace water, running 110# and pumping at rate of 4500 rackside, pumping in at 110# at 4500 BPD, 160 gals. per min. leaking out backside of about 1 1/2 well goes back on vaccuum and backside goes back down, turn pump on well on backside flows. POH w/22 &f 3/4 jts. Shut down. the reverse unit & clean out down to tbg. Fish & POH w/2 jts & 10'. RIH w/3 1/2" grapple & POH w/15' piece. RIH & POH w/1 jt. RIH & latch on to tbg. PU 30,000 & broke 4 1/2" grapple. RIH w/3 to tbg. & jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. WeFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 130 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. Ied off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) H. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back	3/5/1995	3/4/1995
 % NEFE. lown 3 1/2" tubing 1000 gals. 15% HCL Pentol 100 with 2 gals CI-22, 6 gal FE 270, 2 gal FE Pentofax 2, went on a vaccum and chase with 10 bbls. of fresh water. ed filters and hot watered pot to clean any paraffin in tubes, hook back up, only would take 2000bbls. ice and pump down 3 1/2" tubing 2500 gals. 15% HCL Pentol 100 with 5 gals. CI-22, 14 gal. FE 270 nd 60 gal. Pentofac 2, went on vaccuum and chase with 10 bbls. fresh water, let set 1 hour, turn E Acid down tubing, hook up pump to well displace water, running 110# and pumping at rate of 4500 trackside, pumping in at 110# at 4500 BPD, 160 gals. per min. leaking out backside of about 1 1/2 well goes back on vaccuum and backside goes back down, turn pump on well on backside flows. POH w/22 &f 3/4 jts. Shut down. the RU reverse unit & clean out down to tbg. Fish & POH w/2 jts & 10'. RIH w/3 1/2" grapple & POH w/15' piece. RIH & POH w/1 jt. RIH & latch on to tbg. PU 30,000 & broke 4 1/2" grapple. RIH w/3 to tbg. § jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. % NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 1 130 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. led off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) 4. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 its. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax e casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today in Cost: \$11,725 	3/8/1995	3/7/1995
Pentofax 2, went on a vaccum and chase with 10 bbls. of fresh water. ad filters and hot watered pot to clean any paraffin in tubes, hook back up, only would take 2000bbls. Ice and pump down 3 1/2" tubing 2500 gals. 15% HCL Pentol 100 with 5 gals. CI-22, 14 gal. FE 270 ind 60 gal. Pentofac 2, went on vaccuum and chase with 10 bbls. fresh water, let set 1 hour, turn Acid down tubing, hook up pump to well displace water, running 110# and pumping at rate of 4500 wackside, pumping in at 110# at 4500 BPD, 160 gals. per min. leaking out backside of about 1 1/2 well goes back on vaccuum and backside goes back down, turn pump on well on backside flows. POH w/22 &f 3/4 jts. Shut down. th. RU reverse unit & clean out down to tbg. Fish & POH w/2 jts & 10'. RIH w/3 1/2" grapple & POH w/15' piece. RIH & POH w/1 jt. RIH & latch on to tbg. PU 30,000 & broke 4 1/2" grapple. RIH w/3 to tbg. & jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. % NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 130 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. ed off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) 4. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax e coasing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today 1 Cost: \$11,725	3/20/1995	3/19/1995
ice and pump down 3 1/2" tubing 2500 gals. 15% HCL Pentol 100 with 5 gals. CI-22, 14 gal. FE 270 ind 60 gal. Pentofac 2, went on vaccuum and chase with 10 bbls. fresh water, let set 1 hour, turn Acid down tubing, hook up pump to well displace water, running 110# and pumping at rate of 4500 mackside, pumping in at 110# at 4500 BPD, 160 gals. per min. leaking out backside of about 1 1/2 well goes back on vaccuum and backside goes back down, turn pump on well on backside flows. POH w/22 &f 3/4 jts. Shut down. the RU reverse unit & clean out down to tbg. Fish & POH w/2 jts & 10'. RIH w/3 1/2" grapple & POH w/15' piece. RIH & POH w/1 jt. RIH & latch on to tbg. PU 30,000 & broke 4 1/2" grapple. RIH w/3 n to tbg. & jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. % NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 1 130 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. led off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) -1. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. llhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax e casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today 1 Cost: \$11,725	12/2/1997	12/1/1997
 POH w/22 &f 3/4 jts. Shut down. physical problem is the structure of the	8/14/1998	8/13/1998
 well goes back on vaccuum and backside goes back down, turn pump on well on backside flows. POH w/22 &f 3/4 jts. Shut down. th. RU reverse unit & clean out down to tbg. Fish & POH w/2 jts & 10'. RIH w/3 1/2" grapple & POH w/15' piece. RIH & POH w/1 jt. RIH & latch on to tbg. PU 30,000 & broke 4 1/2" grapple. RIH w/3 to tbg. & jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. % NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 1 30 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. led off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) f. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax e casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today to Cost: \$11,725 	2/28/1999	2/27/1999
 gh. RU reverse unit & clean out down to tbg. Fish & POH w/2 jts & 10'. RIH w/3 1/2" grapple & POH w/15' piece. RIH & POH w/1 jt. RIH & latch on to tbg. PU 30,000 & broke 4 1/2" grapple. RIH w/3 n to tbg. & jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. % NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 1 30 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. led off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) H. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax a casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today a Cost: \$11,725 	3/1/1999	2/28/1999
 w/15' piece. RIH & POH w/1 jt. RIH & latch on to tbg. PU 30,000 & broke 4 1/2" grapple. RIH w/3 in to tbg. & jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. % NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear at 130 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. Ied off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) 4. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax a casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today a Cost: \$11,725 	2/14/2000	2/13/2000
 h to tbg. & jar loose. POH & lay down 3 1/2" tbg. & 7" AD-1 pkr. ^{5%} NEFE acid down csg. & flush w/130 bbls FW. RIH w/106 jts new 2 7/8" Plastic Coated tbg. & 7" set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 130 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. Ied off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) H. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax a casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today a Cost: \$11,725 	2/15/2000	2/14/2000
set. Pkr. @ 3202'. -26#. Landed @ 3202' w/32,000# tension pulled on pkr. 40,000# tension pkr. probably will shear 130 bbls packer fluid & set pkr. Let air in packer fluid settle out overnight. led off 20# in 30 min. Hobbs OCD has chart. NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) H. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax a casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today n Cost: \$11,725	2/16/2000	2/15/2000
NEFE Acid with Pentrol 100 down tubing. (NOTE TUBING OR PACKER LEAKING) H. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax a casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today a Cost: \$11,725	2/17/2000	2/16/2000
H. found 2 holes in middle of collars lay down tbg. PU new plastic coated 7" 20-26# AD-1 left hand stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax e casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today o Cost: \$11,725	2/18/2000	2/17/2000
stic coated tbg. Landed @ 3185' w/102 jts. Pump 105 bbls packer fluid down back side & set Pkr. Ilhead off & test csg. 500#. wouldn't test. Leave csg. open all night let air work out. in 30 min. w/ Pentafax e casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today o Cost: \$11,725	10/5/2001	10/4/2001
w/ Pentafax e casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today n Cost: \$11,725	1/22/2002	1/21/2002
e casing into flowback tank. Unload and rack 110 JTS 2 7/8 workstring. RU DDP. Leave well elivered today n Cost: \$11,725	1/23/2002	1/22/2002
elivered today ı Cost: \$11,725	2/24/2004	2/23/2004
H LD 2 7/8 plastic coated tbg. Parted 80 JTS from surface, collar part, TOF @ 2494' KB, TIH with 5	5/20/2008	5/19/2008
grapple, Xover, bumper sub and 83 JTS TBG. Tag fish @ 2714' KB, work fish free, TOOH , LD 22 KR, TIH with 6 1/8 bit, bit sub, 6 - 3 1/2 drill collars, x- over and 86 JTS 2 7/8 workstring, bit @ 3012' n in A.M., secure well. SDON n Cost: \$25,575	5/21/2008	5/20/2008
TIH off pipe racks. Tag fill @ 3341' KB. RU power swivel, wash fill to 3496' KB. Clean out to 3508' swivel and foam unit. TOOH. LD drill collars. TIH with 7 JTS. 2 7/8 workstring, csg scraper, 98 JTS Pull up to first collar. RU Rising Sta. Acidize well with 10,000 gals. 15% HCL, 8BPM 580 PSI, flush instant vacuum. TOOH LD 2 7/8 workstring and csg scraper. Secure well, SDO. Prep to run P.C. A. to Cost: \$59,400	5/22/2008	5/21/2008
7" pkr. and 101 JTS. new 2 7/8" plastic coated tbg. Set pkr @ 3261' KB, load csg with 16 BBLS fresh I for 10 minutes, held good, Release pkr and pump 100 bbls pkr fluid. ND BOP. Reset pkr. Load Irre up to 600 psi. Record on chart recorder for 45 minutes, start disposal. RDMO DDPU, SDOW In Cost: \$75,075	5/23/2008	5/22/2008
to 450 in 30 minutes, repressure csg to 600 psi, unable to get chart, change out chart recorder, Il to 300 psi in 45 min, wait for orders n Cost: \$75,075	5/27/2008	5/26/2008
	11/8/2011	
	11/9/2011	
	11/10/2011	
	11/11/2011	
AID DOWN TBG AND STARTED IN WITH WORK STRING. ND TBG,ACIDIZE WELL,POOH LAYING DOWN WORK STRING SHUT DOWN FOR THE DAY	3/26/2014 3/27/2014	3/25/2014 3/26/2014
4.5" GLASS BORE INJECTION TBG,SET PKR,CIRC PKR FLUID AND SHUT DOWN FOR THE	3/28/2014	3/27/2014
	2/20/2044	2/20/2044
ED CSG W/PKR FLUID,TESTED OKAY UP TO 735#	3/29/2014	3/28/2014 5/12/2014
I for 10 minutes, held good, Release pkr and pump 100 bbls pkr fluid. Ire up to 600 psi. Record on chart recorder for 45 minutes, start dispose a Cost: \$75,075 to 450 in 30 minutes, repressure csg to 600 psi, unable to get chart, cha Il to 300 psi in 45 min, wait for orders a Cost: \$75,075 TED,SHUT DOWN _AID DOWN TBG AND STARTED IN WITH WORK STRING.	5/27/2008 11/8/2011 11/9/2011 11/10/2011 11/11/2011 11/12/2011 3/25/2014 3/26/2014	5/26/2008 11/7/2011 11/8/2011 11/9/2011 11/10/2011 11/11/2011 3/24/2014 3/25/2014

Start Date	End Date	Summary
10/16/2018	10/17/2018	Totem 10 Road Rig to location. Spot rig and rig up. Very carefully (someone put a 1000BBL tank in a bad spot on location for Pulling unit ops) move in BOP, pipe racks, laydown machine and other rental equipment . Nipple up BOP. Line up casing crew for tomorrow am to pull 4-1/2 TBG. SWI. SDFN
10/17/2018	10/18/2018	Totem 10 Unset packer. Rig up Bird casing crew. Pooh laying down 76 joints of 4-1/2 Glass-bore TBG. Then first 8 joints had bad pitting and 4 large holes. The rest of the TBG looked really good. Move out the 76 joints of 4-1/2. Unload and tally the 2-7/8 PH-6 work string. Pick up Bit, scrapper and 102 joints of work-string. Started raining harder so we shut down. SWI. SDFN
10/18/2018	10/19/2018	Totem 10 Pooh with TBG, scrapper and bit. Pick up 7" x 2-7/8 32-A tension packer Run in hole with TBG 3190' set packer and load Backside with 19 BBLS test to 1000 psi. Hold for one hour. Release PSI. Pooh laying down 2-7/8 work-string and packer. Set up casing crew and CLS tech for tomorrow am. Move out work string and move in new 4-1/2 Glass-bore TBG. Prep to pick up for tomorrow am. SWI.SDFN
10/19/2018	10/20/2018	Totem 10 Rig up Byrd casing crew. Pick up New 7" x 3.5" nickel plated AS1-X packer with 2.25 F profile and pump out Plug. Pick up 76 Joints of 4-1/2 Buttress Glass-bore TBG to 3,179'. While CLS tech installed seals and drifted tubing. Rig down casing crew. Shut well in. Shut down for week end.
10/22/2018	10/23/2018	Totem 10 Set packer at 3,179'. Load TBG. Get off on/off tool. Circulate 120 BBLS of Packer fluid. Try to latch back onto Pack but could not. Send trucks to get more water. Pump 150 BBLS down TBG while trying to latch back onto packer. Ran out of water and might have knocked out pump out plug while Pumping. Decide to make plans to pull out with 4-1/2 TBG and inspect on/off tool. Order casing crew, pipe racks and laydown machine. SWI. SDFN
10/23/2018	10/24/2018	Totem 10 Move in pipe racks and laydown machine. Rig up casing crew. Pooh laying down 76 joints of 4-1/2 TBG. All TBG seemed to unscrew ok. Found that the BTM su on the AS1-X packer had backed off. Leaving the BTM slips, rubber element housing and seal section down hole. BTM slips are engaged so fish did not fall down hole. Move 4-1/2 TBG out and 2-7/8 work string in. SWI. SDFN
10/24/2018	10/25/2018	Totem 10 Measure packer that mesquite oil tools brought to make sure we are Running the right grapple on spear. Pick up spear, bumper sub jars and 100 joints of 2-7/8 PH-6 work string. Spear went into packer assy easily. Pull up 40' set back down and packer was on spear. Pooh with tbg. Laydown jars, bumper sub and spear with packer assy on it. Send to mesquites shop to disassemble packer and spear. Run in hole with work string then POOH laying down work string. Move out work string and move back in 4-1/2 TBG. Have Glass-bore tech inspect TBG threads. Prep to pick up new packer and TBG in am. SWI. SDFN

Daily Ope			
Start Date	End Date	Summary	
0/25/2018	10/26/2018	Totem 10 Rig up Byrd casing crew. Pick up New 7" x 3.5" nickel plated AS1-X packer with 2.25 F profile and pump out Plug. Pick up 77 Joints of 4-1/2 Buttress Glass-bore TBG to 3,179'. While CLS tech installed seals and drifted tubing. Rig down casing crew. Set packer. Load TBG. Get off On/off tool. Circulate 110BBLS of packer fluid. Latch back onto packer. Nipple down BOP and flange up well head. Pressure test casing to 500 PSI. get good test for 30 mins. Nipple up 4-1/2 TBG valve. Tie onto TBG and start pressuring up to pump out plug. Get to 800 psi and notice that valve is leaking where stainless casing nipple goes into valve. Unscrew valve and find that stainless casing nipple is almost corroded through. Try to find a 4-1/2 Buttress to 8 v thread x 16' stainless nipple with no luck. Mesquite oil tools has a machine shop and will make one. Will have it on location Monday. SWI. SDFN	
0/26/2018	10/27/2018	Totem 10 Backside PSI still at 500. Crew cleaned and greased 4-1/2" valve. Then did some maintenance on rig. Waiting on a 4-1/2 Buttress to 8 v thread x 16' stainless nipple . Mesquite oil tools has a machine shop and will make one. Will have it on location Monday. SWI. SDFN	
0/29/2018	10/30/2018	Totem 10 Backside PSI at 400. Crew 4-1/2 Buttress to 8 v thread x 16' stainless nipple and Master valve Tie onto TBG pressure up to 1200 PSI and pump out pump out plug. Pump 20 more BBLS to make sure TBG is clear. Pressure up to 525 and chart lost 40 PSI in one hour then leveled off. Contact BLM and OCD set up to do MIT Wednesday at 9am. Rig down WSU and clean location.	

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Workover/Deepening of a Well

- <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-689-5981
- <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. Cement: Notify BLM if cement fails to circulate.
- Subsequent Reporting: Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. Show date work was completed. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1st through June 15th annually, activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	101746
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Like approval from BLM Run MIT post workover test	4/28/2022

Action 101746