

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Released to Mining: 9/22/2022 11:03:48 AM

Revised July 18, 2013

WELL API NO. 30-025-31739	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. LG 485	
7. Lease Name or Unit Agreement Name State -2-, 8016 JV-P Com	
8. Well Number 2	
9. OGRID Number 260297	
10. Pool name or Wildcat Antelope Ridge, Atoka (Gas)	
4. Well Location Unit Letter L : 1980 feet from the South line and 990 feet from the West line Section 2 Township 23S Range 34E NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3382' GR	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator BTA Oil Producers, LLC	
3. Address of Operator 104 S Pecos, Midland, TX 79701	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ **PLUG AND ABANDON** ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Proposed plan to P&A the subject well as follows:

MIRU Plugging Rig and Equipment. NDWH. NUBOP. Release packer. POOH and LD production tubing.
MIRU Wireline Unit. Make run with gauge ring for 5" 18# Liner to 12,100'. RIH and set 5" CIBP @ 12,075'. RD WL.
RIH with workstring to tag CIBP. PU and circulate hole with 9.5 PPG MLF.
Pump 90 sx Class H cmt on top of CIBP @ 12,075' - 11,290'. WOC & Tag. (CIBP & T/Wolfcamp). Pressure test casing to 500 PSI.
Pump 80 sx Class H cmt @ 10,423' - 9941'. WOC and Tag. (7" Csg shoe & 5" Liner top)
Pump 40 sx Class H cmt @ 8474' - 8374'. (T/Bone Spring). Pump 40 sx Class C cmt @ 6560' - 6460'. WOC & Tag. (DV Tool)
Pump 40 sx Class C cmt @ 5424' - 5324'. (T/Delaware). Pump 80 sx Class C cmt @ 4200' - 3994'. WOC & Tag. (9-5/8" Csg shoe & B/Salt)
Pump 40 sx Class C cmt @ 3029' - 2929'. WOC & Tag. (T/Salt). Pump 40 sx Class C cmt @ 2050' - 1950'. WOC & Tag. (13-3/8" Csg shoe)
Perforate and squeeze 65 sx Class C cmt @ 100'. Circulate cmt to surface. NDBOP. Dig out and cut off wellhead to 3' below grade.
Confirm cement to surface in all casings. Install cap and well marker. (Proposed Plan for editing and WBDs are attached.)

4" diameter 4' tall Above Ground Marker

Spud Date:

Rig Release Date:

SEE ATTACHED CONDITIONS OF APPROVAL

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bob Hall

TITLE **Environmental Manager**

DATE **9/7/2022**

Type or print name **Bob Hall**

E-mail address: **bhall@btaoil.com**

PHONE: **(432) 682-3753**

For State Use Only

APPROVED BY:

Kerry Fortner

TITLE **Compliance Officer A**

DATE **9/22/22**

Conditions of Approval (if any)

State 2 #2
30-025-31739

Proposed plan to P&A the subject well as follows:

MIRU Plugging Rig and Equipment. Blowdown well. NDWH. NUBOP.

Release packer. POOH and LD production tubing.

MIRU Wireline Unit. Make run with gauge ring for 5" 18# Liner to 12,100'.

RIH and set 5" CIBP @ 12,075'. RD WL.

RIH with workstring to tag CIBP.

PU and circulate hole with 9.5 PPG MLF.

Pump 90 sx Class H cmt on top of CIBP @ 12,075' – 11,290'. WOC & Tag. (CIBP & T/Wolfcamp)

Pressure test casing to 500 PSI.

Pump 80 sx Class H cmt @ 10,423' – 9941'. WOC and Tag. (7" Csg shoe & 5" Liner top)

Pump 40 sx Class H cmt @ 8474' – 8374'. (T/Bone Spring)

Pump 40 sx Class C cmt @ 6560' – 6460'. WOC & Tag. (DV Tool)

Pump 40 sx Class C cmt @ 5424' – 5324'. (T/Delaware)

Pump 80 sx Class C cmt @ 4200' – 3994'. WOC & Tag. (9-5/8" Csg shoe & B/Salt)

Pump 40 sx Class C cmt @ 3029' – 2929'. WOC & Tag. (T/Salt)

Pump 40 sx Class C cmt @ 2050' – 1950'. WOC & Tag. (13-3/8" Csg shoe)

Perforate and squeeze 65 sx Class C cmt @ 100'. Circulate cmt to surface.

NDBOP. Dig out and cut off wellhead to 3' below grade. Confirm cement to surface in all casings.

Install cap and well marker.

Tubing Detail

KB = 25X-Mas Tree Top Conn.
2 7/8" 10K

?? jts 2-7/8" 6.5# N-80 AB mod
1 - 7" x 2-7/8" Otis permalatch pkr @ 9,731'
?? jts 2-7/8" 6.5# CS hydril
EOT @ 12,033'

@ 2000' - 13-3/8" 68# K-55 Surf. Csg.
cmt'd w/ 2300 sx, circulated to surface

Tops	Formation
2708	Rustler
2979 *	Top Salt
4044 *	Base Salt
5374 *	Delaware
6247	Cherry Canyon
7098	Brushy Canyon
8424 *	Bone Spring Lime
11340 *	Wolfcamp
12112	Atoka
12666 *	Morrow

@ 4150' - 9-5/8" 40# K-55&S-95 Interm Csg.
cmt'd w/ 2000 Sx Cmt, circulated to surface

DV Tool @ 6510'

Permalatch pkr @ 9,731'

Top of 5" liner @ 9991'

@ 10,373' - 7" 29# P-110 (S-95 collapse) Prod Csg
cmt'd w/ 2000 sx + 600 sx top job

EOT @ 12,033'
No report of SN
(1/22/1994)

CIBP @ 12,835'
Cap w/ 35' cmt
(1/21/1994)

CIBP @ 13,000'
Cap w/ 35' cmt
(10/8/1993)

Atoka 12,122 - 1 24'; 12127 - 130'; 12133 - 139'; 12158 - 161';
12176 - 180'; 12201 - 210'; 12255 - 260'

Morrow 'EO' Zone Perfs 12,866 - 69'

Morrow 'A' Zones Perfs 13,116 - 119'; 13,122 - 126'; 13,136 - 143'

Morrow 'C' Zones Perfs 13,302 - 13,322'

@ 9,991 -13,459' - 5" 18# N-80 Liner
cmt'd w/ 350 Sx

Revised

BHall7/27/2022

API # 30-025-31739 GPS: 32.3318 -103.4462

LEASE: 8016 State 2 # 2

FIELD: Antelope Ridge

LOCATION: 1980' FSL 990' FWL Sec. 2 T23S R34E

COUNTY: Lea STATE: New Mexico

PRODUCING FORMATION: Atoka

BTA

BTA Oil Producers

Drawn TJW

5/20/2010

Approved

Date

[illegible]

**CONDITIONS OF APPROVAL
FOR PLUGGING AND ABANDONMENT
OCD - Southern District**

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water will not be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash---(In the R-111-P Area (Potash Mine Area),
A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name
2. Lease and Well Number
3. API Number
4. Unit letter
5. Quarter Section (feet from the North, South, East or West)
6. Section, Township and Range
7. Plugging Date
8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

COMMENTS

Action 141255

COMMENTS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 141255
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	9/22/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 141255

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 141255
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached COA	9/22/2022