Sundry Print Repor

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Name: ROSS DRAW 25

FEDERAL COM

Well Number: 1

Well Location: T26S / R29E / SEC 25 /

NWNW /

County or Parish/State: EDDY /

Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM41646

Unit or CA Name: 1 ROSS DRAW 25 FED COM

Unit or CA Number:

NMNM106835

US Well Number: 3001531575

Well Status: Producing Gas Well

Operator: XTO ENERGY

INCORPORATED

Accepted for record – NMOCD gc 11/10/2022

LONG VO

Digitally signed by LONG VO

Date: 2022.11.03 09:02:38 -05'00'

Notice of Intent

Sundry ID: 2696442

Type of Submission: Notice of Intent

Date Sundry Submitted: 10/04/2022

Type of Action: Plug and Abandonment

Time Sundry Submitted: 06:42

Date proposed operation will begin: 10/04/2022

Procedure Description: XTO Energy Inc Respectfully requests to submit a NOI to PA sundry for the well above. Attached is the procedure for your review. Also attached is the current and proposed WBD for the well.

Surface Disturbance

Is any additional surface disturbance proposed?: No

Approval Subject to

General Requirements and

Special Stipulations

Attached

NOI Attachments

Procedure Description

Ross_Draw_25_Fed_Com_1_Proposed_WBD_20221004184146.pdf

Ross_Draw_25_Fed_Com_1_DHWP_20221004184058.pdf

Ross_Draw_25_Fed_Com_1_Procedure_20221004184041.pdf

eived by OCD: 11/9/2022 10:52:36 AM Well Name: ROSS DRAW 25

FEDERAL COM

Well Location: T26S / R29E / SEC 25 /

NWNW /

County or Parish/State: EDDY? of

Well Number: 1

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMNM41646

Unit or CA Name: 1 ROSS DRAW 25

FED COM

Unit or CA Number:

NMNM106835

US Well Number: 3001531575

Well Status: Producing Gas Well

Operator: XTO ENERGY

INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Signed on: OCT 04, 2022 06:41 PM **Operator Electronic Signature: CASSIE EVANS**

Name: XTO ENERGY INCORPORATED

Title: Regulatory Analyst

Street Address: 6401 Holiday Hill Road, Bldg 5

City: Midland State: TX

Phone: (432) 218-3671

Email address: CASSIE.EVANS@EXXONMOBIL.COM

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

Page 2 of 2

PLUG AND ABANDON WELLBORE ROSS DRAW 25 FEDERAL COM 001 EDDY COUNTY, NEW MEXICO Class II

MASIP	MAOP	MAWP	Surface Csg Yield
1,000 psi	1,000 psi	3,000 psi	1,730 psi

SUMMARY: Plug and abandon wellbore according to BLM regulations.

- 1) MIRU plugging company. Set open top steel pit for plugging.
- 2) ND WH and NU 3K manual BOP. Function test BOP.
- 3) POOH 2-3/8" tubing string.
- MIRU WLU, RIH GR sized for 5" 18.00# casing to 11350', RIH CIBP and set at 11325'. Notify BLM. Pressure test CIBP to 500 psig for 30 min.
 *Liner top is at 10603', operator cement record shows to surface on all casing and to top of liner.
- 5) RIH WS and spot 99 SKS Class H cement from 11325' to 10446' (T/Perf, 7" CSG shoe,). WOC, tag and notify BLM.
- 6) MIRU WLU, perforate at 9680'.
- 7) Squeeze 41 SKS Class H cement from 9680' to 9475' (T/Wolfcamp). WOC and Tag.
- 8) MIRU WLU, perforate at 7070'.
- 9) Squeeze 122 SKS Class C Cement from 7070' to 6295' (DV Tool, T/Bone Spring, 3000' between plugs). WOC, tag and notify BLM.
- 10) MIRU WLU, perforate at 3300'.
- 11) Squeeze 50 SKS Class C cement from 3300' to 3000' (T/Delaware, 9-58" CSG shoe). WOC, tag and notify BLM.
- 12) Spot cement from 1390' to 1276'. (Base of Salt) WOC and Tag. 25 sxs Class C.
- 13) MIRU WLU, perforate at 983'.
- 14) Squeeze 156 SKS Class C Cement from 983' to surface' (13-3/8" CSG shoe, Top of Salt, Fresh Water, Surface Plug). Verify at surface and notify BLM.

- 18) ND BOP and cut off wellhead 5' below surface. RDMO PU and trucks.
- 19) Set P&A marker.
- 20) Pull fluid from steel tank and haul to disposal. Release steel tank.

Ross Draw 25 Federal Com 001 - Proposed WBD

13-3/8" shoe 933'

T/Delaware 3110'

9-5/8" shoe 3245'

T/Bone Spring 6870'

DV Tool 7018'

T/Wolfcamp 9622'

5" TOC 10603'

7" shoe 11102'

T/Perf 11400'


Approval Subject to

General Requirements and

Special Stipulations

Attached

Bridge Plug - Permanent; 11,325.0-11,326.0



Squeeze ~15 SKS Class C: 100' to surface.

Squeeze 25 SKS Class C: 983' – 833'. WOC and tag.

Squeeze 50 SKS Class C: 3300′ – 3000′. WOC and tag.

Squeeze 25 SKS Class C: 5000' - 4850'.

Squeeze 50 SKS Class C: 7070′ – 6770′. WOC and tag.

Squeeze 30 SKS Class H: 9680' – 9530'.


Spot 32 SKS Class H atop CIBP: 11325' – 11000'. Pressure test CIBP to 500 psig for 30 min. WOC and tag. Received by OCD: 11/9/2022 10:52:36 AM

Page 6 of 17



Downhole Well Profile - with Schematic Well Name: ROSS DRAW 25 FEDERAL COM 001

SAP Cost Center ID Permit Number State/Province County 3001531575 1137511001 813536 **New Mexico** Eddy Surface Location Spud Date Ground Elevation (ft) KB-Ground Distance (ft) Original KB Elevation (ft) Surface Casing Flange Elevation (ft) T26S-R29E-S25 3/12/2001 00:00 2,958.00 2,940.00 18.00




Received by OCD: 11/9/2022 10:52:36 AM



Downhole Well Profile - with Schematic Well Name: ROSS DRAW 25 FEDERAL COM 001

API/UWI 3001531575				County Eddy			
Surface Location T26S-R29E-S25		· ·		()	KB-Ground Distance (ft) 18.00	Surface Casing Flange Elevation (ft)	



Perforations									
Date	Top (ftKB)	Btm (ftKB)	Linked Zone						
8/23/2001	11,496.0	11,500.0	CLEARFORK UPR, Original Hole						
7/8/2001	11,571.0	11,718.0	CLEARFORK LWR, Original Hole						
7/8/2001	11,848.0	11,870.0	CLEARFORK LWR, Original Hole						

	Stimulation Intervals					
	Interval Number	Top (ftKB)	Btm (ftKB)	AIR (bbl/min)	MIR (bbl/min)	Proppant Total (lb)
	99	11,571.0	11,870.0			0.0
ı	99	11,400.0	11,500.0			0.0

Page 2/2 Report Printed: 10/4/2022

XTO Energy

Sundry ID

2696442

	2030442					
Diug Type	Ton	Pottom	Longth	Tag	Sacks	Notes
Plug Type	Тор	Bottom	Length	ı ay	Sacks	Notes
Surface Plug	0.00	983.00	983.00	Tag/Verify		
				If solid		
				base no		
				need to		
				Tag		
				(CIBP		
				present		
				and/or		
				Mechanic al Integrity		
				Test), If		
				Perf &		
				Sqz then		
				Tag, Leak		
				Test all		
				CIBP if no Open		
				Perforatio		
Fresh Water @ 350	296.50	400.00	103.50			
	/-			T 04 :6		
Top of Salt @ 788	730.12	838.00	107.88	Tag/Verify		Spot cement from
						983' to surface.
Shoe Plug	873.67	983.00	109.33	Tag/Verify	156.00	Verify at surface
						Spot cement from
						1390' to 1276'.
Dana of 0alt @ 4040	4070.00	4000.00	440.40	Tog/\/orifi/	25.00	WOC and Tag. Class C
Base of Salt @ 1340	1276.60	1390.00	113.40	Tag/Verify	25.00	Class C
				If solid		
				base no		
				need to		
				Tag		
				(CIBP present		
				and/or		
				Mechanic		
				al Integrity		
				Test), If		
				Perf & Sqz then		
				Tag, Leak		
				Test all		
				CIBP if no		
				Open		
Delevere @ 2446	2020.00	2460.00	404.40	Perforatio		
Delaware @ 3110	3028.90	3160.00	131.10	118		

						Spot cement from 3300' to 3000'.
						WOC and Tag.
Shoe Plug	3162.55	3295.00	122.45	Tag/Verify	50.00	Class C
Silve Flug	3102.55	3293.00	132.43	rag/verily	30.00	Olass O
				If solid		
				base no		
				need to		
				Tag		
				(CIBP		
				present		
				and/or		
				Mechanic		
				al Integrity		
				Test), If		
				Perf &		
				Sqz then		
				Tag, Leak		
				Test all		
				CIBP if no		
				Open		
				Perforatio		
Bonesprings @ 6870	6295.00	6920.00	625.00	ns		O
						Spot cement from 7070' to 6295'.
DV tool plug	6897.82	7068.00	170 10	Tag/Verify	122.00	Class C
DV tool plug	0097.02	7000.00	170.16	rag/verily	122.00	Olass O
				If solid		
				base no		
				need to		
				Tag		
				(CIBP		
				present		
				and/or		
				Mechanic		
				al Integrity		
				Test), If		
				Perf &		
				Sqz then		
				Tag, Leak Test all		
				CIBP if no		
				Open		Spot cement from
				Perforatio		9680' to 9475'.
Wolfcamp @ 9622	9475.78	9672.00	196.22		41.00	Class H
Liner Top @ 10603						
	10446.97	10653.00	206.03	base no		

						1
				If solid		
				base no		
				need to		
				Tag		
				(CIBP		
				present		
				and/or		
				Mechanic		
				al Integrity		
				Test), If		Set CIBP at 11325'.
				Perf &		Spot cement from
				Sqz then		11325' to 10446'.
				Tag, Leak		Class H. Leak Test
				Tag, Leak		CIBP. WOC and
				CIBP if no		Tag. (68 sxs from
				Open		11325' to 10603', 31
				Perforatio		sxs from 10603' to
CIBP Plug		11325.00			99.00	10446')
Perforations Plug (If No CIBP)	11350.00	11920.00		Tag/Verify		
Shoe Plug	12077.50	12300.00	222.50	Tag/Verify		

No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs in cased hole.

Class H >7500'

Class C<7500'

Fluid used to mix the cement in R111P shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.

Medium, Secretary: Top of salt to surface If no salt take the deepest fresh water or Karst Depth

High, Critical: Bottom of Karst to surface or Deepest fresh water, whichever is greater R111P: 50 Feet from Base of Salt to surface.

Class C: 1.32 ft³/sx Class H: 1.06 ft³/sx

Onshore Order 2.III.G Drilling Abandonment Requirements: "All formations bearing usable-quality water, oil, gas, or geothermal resources, and/or a prospectively valuable deposit of minerals shall be protected.

Cave Karst/Potash Cement	High	Bottom of Karst/take deepest fresh water/top of salt whichever is greater to surface					
Shoe @ Shoe @	933.00 3245.00						
Shoe @ Shoe @	11102.00 12250.00	тос @	10603.00				
Perforatons Top @	11400.00	Perforations	11870.00				
DV Tool @	7018.00	CIBP @	11325.00				

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-689-5981.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds). A weep hole shall be left if a metal plate is welded in place.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any/all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip (across the slope and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech/Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Jose Martinez-Colon Environmental Protection Specialist 575-234-5951

Mark Mattozzi Environmental Protection Specialist 575-234-5713

Robert Duenas Environmental Protection Specialist 575-234-2229

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 157338

CONDITIONS

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	157338
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	11/10/2022