
Submit 1 Copy To Appropriate District Office		ew Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals ar	nd Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OH COMERNIA	MINOR DATE MATERIAL	30-025-12411
811 S. First St., Artesia, NM 88210		ATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410		St. Francis Dr.	STATE FEE X
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
87505			
	TICES AND REPORTS ON		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR, USE "APPL			Buffington
PROPOSALS.)	Gas Well Other		8. Well Number 3
Type of Well: Oil Well Name of Operator	Gas Well Other		O. OCRID March an
JR Oil Ltd. Co			256073
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 2975 Hob	bs, NM 88241		LANGLIE MATTIX; 7 RVRS-Q-GRAYBURG
4. Well Location	000	South	C I C II West 1
Unit Letter N	: 660 feet from the	South line and	1650 feet from the West line
Section 19	Township 25		Will Will County
	11. Elevation (Show whe	mer DR, RRB, R1, GR, e	etc.)
12. Check	Appropriate Box to Ind	icate Nature of Notic	ce, Report or Other Data
PERFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON	REMEDIAL W	UBSEQUENT REPORT OF: FORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON			DRILLING OPNS. P AND A
PULL OR ALTER CASING		☐ CASING/CEM	<u> </u>
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM]	OTHER:	
OTHER: 13. Describe proposed or com	pleted operations. (Clearly		, and give pertinent dates, including estimated date
of starting any proposed v	vork). SEE RULE 19.15.7.1	4 NMAC. For Multiple	Completions: Attach wellbore diagram of
proposed completion or re	ecompletion.		
1. MIRU Plugging service			
Lay down all rods & tubing an	d move to edge of location.	0.00001	
 Trip bit & scraper on work stri Set CIBP @ +/- 3240' 	ng to between 3240' & csg st	noe @ 3290°	
RIH work string, tag plug, circulate	ılate well w/ MLF		
Spot 25 sx cement from pluga. All cement plugs shall be C	dass C neat unless approved	by NMOCD	
7. Spot 25 sx cement from 2490'		by Miloob.	
8. Spot 25 sx cement from 880' 9. Perforate 5-1/2" casing @ 303	l' and aguageza EO sy comont		
10. Cut off well head 3' beneath	grade, top out/top off with cer	ment, weld marker plate:	and back fill
11.Remove all underground pipil	ng and surface equipment. R	Remediate surface location	on per NMOCD.
4" diameter 4' tall Above Gr	ound Marker	Ps	SEE ATTACHED CONDITIONS
G 1D (Dia D	elease Date:	OF APPROVAL
Spud Date:	Kig Ki	clease Date.	
I hereby certify that the information	n above is true and complete	to the best of my knowl	ledge and belief.
\cap	F 2	·	
arayyamını A A a ka h /	times man	E Againt	DATE 1/31/2023
SIGNATURE WWW.	TIMUL_TITL	1 101	
Type or print name	Latimer E-ma	il address: mlatime	r@ravenop.comme:575 691 6790
For State Use Only	1 J -		0, 11
APPROVED BY:	toutree more	Compliance Offic	er A DATE 2/1/23
Conditions of Approval (if and	IIILE	575-263-6633	

JR Oil Ltd.

Buffington #3 PROPOSED



Updated: January 26, 2023 by Ian Petersen

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

J R Oil, Ltd. Buffington #3

Plug & Abandon Procedure

01/26/2023

- 1. MIRU plugging service.
- 2. Lay down all rods & tubing and move to edge of location.
 - a. Treat rods with care avoid dropping/banging & excessive bending
- 3. Trip bit & scraper on work string to between 3,240' & csg shoe @ 3,290'
- 4. Set CIBP @ +/- 3,240'
- RIH work string, tag plug, circulate well w/ MLF.
- 6. Spot 25 sx cement from plug
 - a. All cement plugs shall be Class C neat unless approved by NMOCD
- 7. Spot 25 sx cement from 2,490'
- 8. Spot 25 sx cement from 880'
- 9. Perforate 5-1/2" casing @ 303' and squeeze 50 sx cement
- 10. Cut off well head 3' beneath grade, top out/top off with cement, weld marker plate, and back fill.
- 11. Remove all underground piping and surface equipment. Remediate surface location per NMOCD.

Information

<u>Well</u>

Name: Buffington #3

API: 30-025-12411

Location: Unit N, section 19, T 25S, R 38E, 660' FSL, 1,650' FWL

Lat/long: 32.1103477, -103.1028214

Directions: From Jal travel East on Hwy 128 for 4.8 miles.

Turn South (right) onto primary lease road. Bear left at the first Y, then travel 0.9 miles.

Turn East (left) and travel to the well. See attached satellite image.


Contacts

Company Man in charge: Bobby Stearns (575) 760-2482

Engineer: lan Petersen (432) 634-4922

Production Foreman: Josh Latimer (575) 414-9188

Pumper: Charles Cowger (575) 631-7939






JR Oil Ltd.

Buffington #3

	1 1 1													
		WELL NAME: Buffington #3 FORMATION: 7R/Q/GB API NO: 30-025-12411 FIELD: Langlie Ma												
		SPUD DATE: May 29, 1955 COUNTY: Lea CASING					Lea	TD: 3,390 CEMENT & HOLE DATA						
			joints	OD	lb/ft	grade	ID (in)	drift (in)	top	bottom	bit size	depth	sacks	TOC
		Surface Production		8 5/8 5 1/2	28.00 14.00		8.017 5.012	7.892 4.887	0'	253' 3,290'	11 6 3/4		125 300	surf. (calc.)
		(open hole)		3 1/2	14.00		3.012	4.007	· ·	3,230	0 3/4	3,390'	300	
		History:	Soud by W	K Burom en	on hole com	ploted in 7B/	Q/GB , frac 10	k gol	PERFORATI top	ONS bottom	zone	status	ttl shots	date
			IP 240 BOP		en noie com	pieteu iii 710	G/GB, Hac To	k yai,	3,290'	3,390'	7R/Q/GB	active	(open hole)	05/30/55
8-5/8" @ 253'		3/1/1963 1/25/1994		l: tbg draggii	ng out, RIH bi	t, stacked 46	its in, pumped							
						out w/ air 3,36								
222222														
									TUBING (1/2	6/4004\	it longth of	110'		
									TUBING (1/2	OD (in)	ID (in)	joints	length (ft)	depth (ft)
									Tubing SN	2 3/8	1.995	110	3,371.88 1.10	3,372 3,373
									Perf sub				4.00	3,377
									MA			1	30.33	3,407
									RODS (1/26/	1994)				
									Polished rod	OD (in)	grade	rods	length (ft)	depth (ft)
									Ponies	3/4		2	4.0	13
									Sucker rods	3/4 5/8		40 94	1,000.0 2,350.0	1,013 3,363
									Pump	1 1/2	RWTC		10.0	3,373
5-1/2" @ 3,290'		open hole intake @ 3,37	73'											
		ntake @ 3,37 @ 3,407'	. J											
TD @ 3	3,390'													
											Undate	d: January 2	6. 2023 by lar	Potorcon

JR Oil Ltd.

Buffington #3 PROPOSED



Updated: January 26, 2023 by Ian Petersen

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 181296

COMMENTS

Operator:	OGRID:
J R OIL, LTD. CO.	256073
P.O. Box 52647	Action Number:
Tulsa, OK 74152	181296
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartine	z DATA ENTRY PM	2/1/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 181296

CONDITIONS

Operator:	OGRID:
J R OIL, LTD. CO.	256073
P.O. Box 52647	Action Number:
Tulsa, OK 74152	181296
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached COA	2/1/2023