Office	<i>1 PM</i> State of New Mexico Energy, Minerals and Natural Resources	Form C ^P -103 ¹ Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-31702
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE X FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sana Pe, INVI 87505	6. State Oil & Gas Lease No.
SUNDRY NO	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LICATION FOR PERMIT" (FORM C-101) FOR SUCH	VACUUM GLORIETA WEST UNIT
PROPOSALS.)		8. Well Number 052
 Type of Well: Oil Well Name of Operator 	Gas Well Other INJECTION	9. OGRID Number
-	GSTAR OPERATING LLC	330132
3. Address of Operator		10. Pool name or Wildcat
	H ST, FORT WORTH, TX 76102	VACUUM; GLORIETA
4. Well Location		
		feet from theWline NMPM County LEA
Section 25	Township17SRange34E11. Elevation (Show whether DR, RKB, RT, GR,	2
	11. Elevation (Show whether DR, RRD, RT, OR,	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed v proposed completion or re MorningStar Operating has plu	PLUG AND ABANDON REMEDIAL W CHANGE PLANS COMMENCE MULTIPLE COMPL CASING/CEW OTHER: OTHER: npleted operations. (Clearly state all pertinent details work).	DRILLING OPNS. P AND A A IENT JOB
MIRU 01/28/2025. Plug 1: CIBP @ 5844', capped Plug 2: (DV tool) 25 sx plug fro Plug 3: 25 sx plug from 4191' Plug 4: 25 sx plug from 3548' Plug 5: 60 sx plug from 3548' Plug 6: 25 sx plug from 1400' Plug 7: 18 sx from 0' - 150'. RDMO 02/22/2025.	' - 4391'. ' - 3748'. ' - 3748'.	
Plug 1: CIBP @ 5844', capped Plug 2: (DV tool) 25 sx plug fro Plug 3: 25 sx plug from 4191' Plug 4: 25 sx plug from 3548' Plug 5: 60 sx plug from 3548' Plug 6: 25 sx plug from 1400' Plug 7: 18 sx from 0' - 150'. RDMO 02/22/2025.	om 4850' - 5100'. ' - 4391'. ' - 3748'. - 3748'. - 1600'. Rig Release Date:	
Plug 1: CIBP @ 5844', capped Plug 2: (DV tool) 25 sx plug fro Plug 3: 25 sx plug from 4191' Plug 4: 25 sx plug from 3548' Plug 5: 60 sx plug from 3548' Plug 6: 25 sx plug from 1400' Plug 7: 18 sx from 0' - 150'. RDMO 02/22/2025.	om 4850' - 5100'. ' - 4391'. ' - 3748'. ' - 3748'. - 1600'.	ledge and belief.
Plug 1: CIBP @ 5844', capped Plug 2: (DV tool) 25 sx plug fro Plug 3: 25 sx plug from 4191' Plug 4: 25 sx plug from 3548' Plug 5: 60 sx plug from 3548' Plug 6: 25 sx plug from 1400' Plug 7: 18 sx from 0' - 150'. RDMO 02/22/2025.	om 4850' - 5100'. ' - 4391'. ' - 3748'. - 3748'. - 1600'. Rig Release Date:	
Plug 1: CIBP @ 5844', capped Plug 2: (DV tool) 25 sx plug fro Plug 3: 25 sx plug from 4191' Plug 4: 25 sx plug from 3548' Plug 5: 60 sx plug from 3548' Plug 6: 25 sx plug from 1400' Plug 7: 18 sx from 0' - 150'. RDMO 02/22/2025. Spud Date:	om 4850' - 5100'. ' - 4391'. ' - 3748'. - 3748'. - 1600'. Rig Release Date:	DATE03/03/2025
Plug 1: CIBP @ 5844', capped Plug 2: (DV tool) 25 sx plug fro Plug 3: 25 sx plug from 4191' Plug 4: 25 sx plug from 3548' Plug 5: 60 sx plug from 3548' Plug 6: 25 sx plug from 1400' Plug 7: 18 sx from 0' - 150'. RDMO 02/22/2025. Spud Date:	om 4850' - 5100'. ' - 4391'. ' - 3748'. ' - 3748'. - 1600'. Rig Release Date: on above is true and complete to the best of my knowl laylock TITLE_Regulatory Analyst lock E-mail address: _cblaylock@:	DATE03/03/2025 txoenergy.comPHONE:817-334-7882

•

ACTIVE WELL: VACUUM GLORIETA WEST #52 (LEA COUNTY, NM)

01/28/25: RUPU. NDWH, NUBOP. SWN & SDON.

01/29/25: Unloaded and racked 180 jts 2-7/8 workstring. PU on/off tool and 143 jts. Latched onto RBP at 4520', Unset RBP, POOH with tbg and RBP. SWN & SDON.

01/30/25: PU overshot, bumper sub, Jars and 6- drill collars. RIH with tbg, tagged at 4714', Worked down to 4730', RU swivel to circulate well. Worked tbg down from 4731 to 5269', Pumped down tbg to unplug tbg before engaging fish. Worked tbg down to fish, tagged fish and latched onto fish. Pulled 4 pts into fish and slipped off. Worked over fish again with same results, On third attempt tagged 3' higher and decided to pull overshot to check. POOH with tbg and overshot. Had 6' piece of tbg in overshot, SWN & SDON.

01/31/25: RIH with overshot assembly and tbg to 5306'. Worked overshot over fish, latched onto fish, jarred on fish for an hour, Unable to jar free, Tried to unset packer, while working tbg jumped free, POOH with tbg and overshot. Had a 8' piece of tbg in overshot, SWN & SDOWE.

02/03/25: PU 4-5/8 shoe, 10 jts 4-3/8 wash pipe, and jars. RIH with tbg to 5345', RU swivel, Broke circulation, washed over fish from 5345' to 5628', Circulated clean, RD swivel, LD 10 jts and stood back 20 jts. SWN & SDON.

02/04/25: POOH with rest of tbg and washpipe. PU overshot, 1- jt washpipe, jars, Drill collars and accelerator sub. RIH with tbg tagged fish at 5342', Latched onto fish, jarred on fish and tried to unset packer. Tbg spinning free, continued jarring on fish, was able move fish up hole 9', Stopped making hole, worked tbg and continued jarring, Tbg jumped free, Tbg parted or overshot released. POOH with 100 jts tbg, SWN & SDON.

02/05/25: POOH with rest of tbg and overshot. Recovered 60' of 2-3/8 IPC tbg, waited on 6 jts washpipe, RIH with 4-5/8 shoe, 15 jts washpipe, Jars 6- drill collars and tbg. Tagged top of fish at 5366', RIH and tagged fill at 5693'. POOH with 14 jts to get above fish, SWN & SDON.

02/06/25: RIH tagged top of fish, worked shoe over fish and run down to fill, RU swivel, Broke circulation, washed over fish from 5693' to 5809', top of packer. Circulated well clean, RD swivel, POOH with tbg and wash pipe. PU overshot, 1 jt wash pipe, bumper sub, jars, accelerator sub, RIH with drill collars and 160 jts tbg. SWN & SDON.

02/07/25: RIH with rest of tbg to top of fish, Worked overshot over fish and latched onto fish. Picked up on fish and came free. POOH with tbg and overshot. LD 14 jts 2-3/8 tbg and packer. RIH LD drill collars and wash pipe. RIH with tbg open ended, SWN & SDOWE.

02/10/25: POOH LD workstring, NDBOP, NUWH, RDMOPU.

02/11/25: Road plugging rig to location.

02/12/25: MIRU plugging rig. NDWH, NUBOP, Unloaded and racked workstring. PU 5-1/2 CIBP and 3 jts tbg. Rig tongs broke, LD 3 jts tbg and CIBP, SWN & SDON.

02/13/25: PU 5-1/2 CIBP and 120 jts tbg, SWN & SDOWE.


02/18/25: PU & RIH with rest of tbg, Set CIBP at 5844', Circulated well with Mud and spotted 25 sxs cement plug. POOH with tbg, Loaded csg with fluid, SWN & SDON.

02/19/25: RU wireline trk, Ran CBL log, RD wireline trk, SWN & SDON due to freezing weather.

02/20/25: SDFD due to inclement weather.

02/21/25: RIH with tbg to 5100'. Spotted 25 sxs cement plug, POOH with tbg to 4391', Spotted 25 sxs cement plug, POOH with tbg to 3748', Spotted 25 sxs cement plug, POOH to 3173', Spotted 60 sxs cement plug, POOH to 1600', spotted 25 sxs cement plug. POOH to 150', SWN & SDON

02/22/25: Broke circulation, circulated 18 sxs cement from 150' to surface, POOH LD tbg, NDBOP, Did 30 min bubble test, Tested good. RDPU, Cut off well head, Welded plate and dry hole marker. Well PA'ed.



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
MorningStar Operating LLC	330132
400 W 7th St	Action Number:
Fort Worth, TX 76102	438457
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
gcordero	Clean Location in accordance with 19.15.25.10 NMAC.	3/27/2025
gcordero	Submit C-103Q within one year of plugging.	3/27/2025

Page 5 of 5

Action 438457