.

1 1	((1		
Form 3160-5 (June 2015) DEI BUR	secuto		FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC029415					
Do not use this	NOTICES AND REP(form for proposals Use Form 3160-3 (A	to drill or to	o re-enter an		6. If Indian, Allottee or '			
SUBMIT IN	TRIPLICATE - Other instr	ructions on pag	je 2		7. If Unit of CA/Agreen	nent, Name and/or No.		
I. Type of Well Øil Well Gas V	CARL CONTRACTOR				8. Well Name and No. F	Puckett B #18		
2. Name of Operator Hudson Oil Con	npany of Texas				9. API Well No. 30-015-05408			
^{3a, Address} 616 Texas Street Fort Worth, TX 76102	(817) 336-71	(include area code 09	<i>:)</i>	10. Field and Pool or Ex Maljamar; Grayburg	ploratory Area			
4. Location of Well <i>(Footage, Sec., T. I</i> Sec 25, T17S, R31E 1980'FS)	11. Country or Parish, State Eddy, New Mexico			tate			
12. CHE	CK THE APPROPRIATE B	BOX(ES) TO IN	DICATE NATURE	OF NOT	CE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION			TY	PE OF AC	TION			
Notice of Intent✓ Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	New	pen raulic Fracturing Construction and Abandon	Recl	uction (Start/Resume) amation amplete	Water Shut-Off Well Integrity		
Final Abandonment Notice	Convert to Injection		Back		porarily Abandon or Disposal			
03/05/21 MIRU plugging equip Circulated hole w/ 100 BBLS M 500 PSI. Spotted 35 sx class C WOC. ND BOP, NU well head. moved off. Moved in backhoe a Ground Dry Hole Marker". Bac	Comt @ 2190-1844'.WOC Tagged plug @ 767'. Per and welder, cut off well he	C cmt @ 3725- . 03/10/21 Ta f'd csg @ 90'. ad and Rami A	3083'. WOC. Tag gged plug @ 179 Sqz'd 70 sx class Abdelbadi verified	gged plug 6'. Perfd s C cmt @	@ 3140'. Perf'd csg @ csg @ 1050'. Sqz'd 90) 90' & circulated to su	2140'. Pressured up on perfs to sx class C cmt @ 1050-780'.		
	Realan	natio	n da	=e	9	11-21		
4. I hereby certify that the foregoing is	true and correct. Name (Pri	inted/Typed)	[·····				
E. Randall Hudson III		Title Preside	ent					
Signatur	P		Date 3/23/2	1				
rested for Teco	THE SPACE	FOR FED	ERAL OR ST	ATE OF	ICE USE			
onditions of approval, if any, are attach orditions of approval, if any, are attach ordify that the applicant holds legal or e thich would entitle the applicant to com	quitable title to those rights	does not warran in the subject le	t or ase Office	SPE 1.00	T Da	ne 4-2-25		
Nue 18 U.S.C Section 1001 and Title 43 iny false, fictitious or fraudulent stateme	U.S.C Section 1212, make ents or representations as to	it a crime for ar any matter with	ny person knowing in its jurisdiction.	ly and will	fully to make to any depa	artment or agency of the United Sta		
Instructions on page 2)				J				











ceived by OCD: 5/28/2025	0:14:46 AM	Operator Copy	,	6	i di seconda	Page 6 o	
	DEPARTMENT OF THE INTERIOR				FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018		
	REAU OF LAND MANAGE			5. Lease Serial No. LC-029415			
Do not use this	NOTICES AND REPORTS form for proposals to dr Use Form 3160-3 (APD)	ill or to re-enter an		6. If Indian, Allottee or	Tribe Name		
SUBMIT I	NTRIPLICATE - Other instruction	s on page 2		7. If Unit of CA/Agreer	nent, Name and/or No.		
	Well Other	с с.		8. Well Name and No. F	PUCKETT B 18		
2. Name of Operator HUDSON OIL	COMPANY OF TEXAS			9. API Well No. 35-015-05408			
3a. Address 616 TEXAS STREET		hone No. <i>(include area cod</i>		10. Field and Pool or Exploratory Area			
FORT WORTH, TX 7 4. Location of Well <i>(Footage, Sec., T</i>) 336-7109		MALJAMAR; GRAY	BURG-SAN ANDRES		
Sec 25 – T17S – R31E; 1980'				EDDY, NEW MEXIC			
12. CF	IECK THE APPROPRIATE BOX(ES	S) TO INDICATE NATURI	E ÓF NOTI	L CE, REPORT OR OTHI	ER DATA		
TYPE OF SUBMISSION			PE OF ACT				
✓ Notice of Intent	Acidize [Deepen	Prod	uction (Start/Resume)	Water Shut-Off		
	Alter Casing	Hydraulic Fracturing	Recla	amation	Well Integrity		
Subsequent Report	Casing Repair	New Construction		omplete	Other		
Final Abandonment Notice	Convert to Injection	✓ Plug and Abandon Plug Back	-	oorarily Abandon r Disposal			
2. RIH with tubing and tag C tag cement @3,465. If nece	plugging equipment. Install 7-1/6 3720 IBP Displace well with 9.5 ppg r ssary, pump additional cement to	nud. Spot 65 sx cement bring top to 3,4 65°.	on top of (CIBP. POOH with tub		and	
3. POOH with tbg. Shoot sq	ueeze holes @ 2,140' Squeeze	cement plug from 2,140'	– 1,815'. V	WOC. RIH and tag ce	ment. POOH.		
4. RIH and perforate 5-1/2" of	asing @ 1,050'. Squeeze cemen	it across 8-5/8" shoe fron	n 780' – 1,	050' WOC RIH and	tag cement. POOH with tubi	ng.	
5. RIH and perforate 5-1/2" a	nd 8-5/8" casing @ 90' Squeeze	e 60 sx cement to surface	e. Des	ip shots			
6. Cut off well head and verif	y cement to surface around both	casing strings. Install be	low ground	d dry hole marker			
7. Cut off anchors, Rip and r	emove caliche, contour to surrour	nding topography. and re	seed locat	ion.	\bigcirc		
4. I hereby certify that the foregoing	Segel dry k is true and correct. Name (Printed/T	rola mark	200	reguisred	ENTERED La La La	0	
KAREN ZORNES		SR. REGI Title	JLATORY	CONSULTANT			
Signature arew	Janet	Date		10/30/20:	20		
107	THE SPACE FOR	R FEDERAL OR ST	ATE OF	ICE USE			
Approved by Conditions of approval, if any, are atta ertify that the applicant holds legal of which would entitle the applicant to co	equitable title to those rights in the s	Title contract or subject lease Office	SAE 160	T D	ate 12-17-20		
Title 18 U.S.C. Section 1001 and Title ny false, fictitious or fraudulent states	43 U.S.C Section 1212, make it a cri nents or representations as to any ma	me for any person knowing atter within its jurisdiction.	ly and will	fully to make to any dep	artment or agency of the United	States	
Instructions on page 2)							

.

Hudson Oil of Texas – P&A Procedure – 10/28/2020

Puckett "B" #18

API #: 30-015-05408 AFE#: Field: Maljamar-GB-SA Surf Location: Sec 25 – T17S – R31E 1980' FSL & 660' FWL Latitude: 00.0000[°] N / Longitude: -00.0000[°] W Eddy County, NM Spud Date: 6-29-60

Directions to Location

From Maljamar: West on Hwy 82 for 4 miles. Turn south into location.

Description	Size	Wght	Grade	ID	Drift	Burst	Collapse	Btm MD	TOC
Surface	8-5/8"	24	J-55	8.0"				998'	
Production	5-1/2"	14	J-55	6.456"	6.331"			3,934'	

KB: 3,859' GL: 3.857' PBTD: 3,888' TD: 3,934'

Current Perfs: 3,806'- 3,878'

Objective: P&A Well Bore in compliance with the rules and regulations for the state of New Mexico.

Proposed Perfs: None

Procedure

1. MIRU well service rig and plugging equipment. Install 7-1/6" 3K BOP's.

2. RIH with tubing and tag CIBP. Displace well with 9.5 ppg mud. Spot 65 sx cement on top of CIBP. POOH with tubing and WOC. RIH with tbg and tag cement @3;465⁷. If necessary, pump additional cement to bring top to 3;465⁷. 3370

3. POOH with tbg. Shoot squeeze holes @ 2,140'. Squeeze cement plug from 2,140' – 1,815'. WOC. RIH and tag cement. POOH.

4. RIH and perforate 5-1/2" casing @ 1,050'. Squeeze cement across 8-5/8" shoe from 780' – 1,050'. WOC. RIH and tag cement. POOH with tubing.

5. RIH and perforate 5-1/2" and 8-5/8" casing @ 90'. Squeeze 60 sx cement to surface.

6. Cut off well head and verify cement to surface around both casing strings. Install below ground dry hole marker.

7. Cut off anchors, Rip and remove caliche, contour to surrounding topography. and reseed location.

THIS PROCEDURE HAS BEEN PROPOSED IN CONSIDERATION OF AND WITH RESPECT GIVEN TO THE MANY VARIABLES AND POTENTIAL PROBLEMS THAT MAY BE ENCOUNTERED IN THIS WELL IN THIS GEOGRAPHICAL AREA. THEREFORE, THIS PROCEDURE IS TO SERVE AS A GENERAL GUIDELINE AND WILL BE REVIEWED AND MODIFIED WHEN REQUIRED AS DETERMINED BY ACTUAL WELLBORE CONDITIONS ENCOUNTERED IN THE OPERATIONS. SAFETY AND PRUDENT PRACTICES WILL TAKE PRIORITY AT ALL TIMES.

Prior to rig up of any operations and prior to the actual operations, always hold safety meeting to discuss any potential hazards, accurately record names of all personnel on location, pick meeting place, discuss evacuation plans, designate hospital of choice and have coordinates and phone numbers for care flight operations if necessary. Completely discuss the operation and/or rig-up so that all personnel understand the plan, responsibilities and any potential changes that may take place during the rig up or operation

Prepared By:

Greg Milner Petroleum Engineer Date: 10-28-20



Released to Imaging: 7/3/2025 10:44:24 AM

Received by OCD: 5/28/2025 10:14:46 AM



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses.** Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the **BLM is to be contacted with justification to receive an extension for completing the cut off.** Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:

From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



HUDSON OIL COMPANY OF TEXAS 616 TEXAS ST. FORT WORTH, TX 76102

Puckett B #18 Plugging Report Unit L, 1980' FSL & 660' FWL, SEC. 25, T17S - R31E, Eddy Co., NM

- 3/11/21 CREW TO LOCATION, JSA SAFETY MEETING, FILL OUT HOT WORK PERMIT DIG OUT WH AND ANCHORS, CUT OFF WH AND REMOVE ANCHORS MAKE AND INSTALL UNDERGROUND MARKER BACK FILL CLEAR AND CLEAN LOCATION RAMI ABDELHADI WITH BLM VERIFIED CEMENT TO SURFACE BY PIC OK RD PU PUMP AND EQUIPMENT CLEAN LOCATION
- 3/10/21 CREW TO LOCATION, JSA SAFETY MEETING, OPEN WELL 0 PSI, RIH WITH TUBING TAGGED CMT @ 1796' POOH STOOD BACK 25 STANDS AND LD THE REST PU 5 ½ PKR RIH WITH TUBING TO 523' SET PKR RU WIRELINE AND PERF CHARGES RIH TO 1050' AND PERF, POOH, SQZ 90 SX CLASS "C" NEAT CMT FROM 1050' TO 780' CLOSE IN WELL WOC, OPEN WELL 0 PSI, RELEASE PKR POOH LD ALL TUBING AND PKR, RD TUBING TONGS PU FLOOR NDBOP NUWH, RU WIRELINE AND PERF CHARGES RIH TAG CMT @ 767' PUH TO 90' AND PERF POOH SQZ 70 SX CLASS "C" NEAT CMT FROM 90' TO SURFACE, CLOSE IN WELL, SD, NOTIFIED RAMI ABDELHADI WITH BLM OK
- 3/9/21 CREW TO LOCATION, JSA SAFETY MEETING, OPEN WELL 0 PSI PMP 100 BBLS OF MUD LADEN FLUID FROM 1725' TO SURFACE, CIRC MUD SPOT 65 SX CLASS "C" NEAT CMT FROM 3275' TO 3083' PUH STOOD BACK 30 STANDS CLOSE IN WELL WOC OPEN WELL 0 PSI RIH WITH TUBING OPEN ENDED TAG CMT @ 3140' POOH STOOD BACK 25 STANDS AND LD THE REST PU 5 ½ PKR RIH WITH 2 7/8 TUBING TO 1509' SET PKR RU WIRELINE AND PERF CHARGES RIH TO 2140' AND PERF, POOH, ESTABLISH INJECTION RATE PRESSURE UP TO 500 PSI HELD RELEASE PRESSURE AND RELEASE PKR POOH STOOD BACK ALL TUBING AND LD PKR RIH WITH 2 7/8 TUBING OPEN ENDED TO 2190' SPOT 35 SX CLASS "C" NEAT CMT FROM 2190' TO 1844' PUH STOOD BACK 20 STANDS, SD, NOTIFIED PAMI ABDELHADI WITH BLM OK
- 3/8/21 CREW TO LOCATION, JSA SAFETY MEETING, OPEN WELL 0 PSI RU NDWH, NUBOP, PU FLOOR, RU TUBING TONGS, PU 2 7/8 TUBING TIH OPEN ENDED TAGGED CIBP @ 3725' SD

HUDSON OIL COMPANY OF TEXAS 616 TEXAS ST. FORT WORTH, TX 76102

Puckett B #18 Plugging Report Unit L, 1980' FSL & 660' FWL, SEC. 25, T17S - R31E, Eddy Co., NM

3/5/21 JSA MOVE RIG TO NEW LOCATION SPOT RIG AND EQP DUG OUT CELLAR SD

' s



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
HUDSON OIL COMPANY OF TEXAS	25111
616 Texas Street	Action Number:
Fort Worth, TX 76102	468036
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
gcordero	THIS WELL WAS PLUGGED WITHOUT PRIOR APPROVAL OR NOTIFICATION TO OCD	7/3/2025

CONDITIONS

Page 17 of 17

Action 468036