Form C-103 of 5 Received by OCD; 8/28/2025 6:25:36 AM State of New Mexico Phone: (505) 476-3441 Revised July 18, 2013 Energy, Minerals and Natural Resources General Information WELL API NO. Phone: (505) 629-6116 OIL CONSERVATION DIVISION Online Phone Directory Visit: 5. Indicate Type of Lease https://www.emnrd.nm.gov/ocd/contact-us/ 1220 South St. Francis Dr. STATE FEE \square Santa Fe, NM 87505 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number 3. Address of Operator 10. Pool name or Wildcat 4. Well Location Unit Letter : feet from the line and feet from the line Township Range **NMPM** County Section 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK ALTERING CASING □ CHANGE PLANS COMMENCE DRILLING OPNS. P AND A TEMPORARILY ABANDON PULL OR ALTER CASING MULTIPLE COMPL \Box CASING/CEMENT JOB DOWNHOLE COMMINGLE П **CLOSED-LOOP SYSTEM** OTHER: \Box OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Rig Release Date:

Conditions of Approval (if any):

Spud Date:



HILCORP ENERGY COMPANY NE DRI UN #904 P&A NOI

API #: 3002506754


JOB PROCEDURES

- 1. Contact NMOCD and BLM (where applicable) 24 hours prior to MIRU.
- 2. Hold pre-job safety meeting. Verify cathodic is off. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.
- 3. MIRU service rig and associated equipment; NU and test BOP.
- 4. Well currently has a bridge plug set at 5,010' w/ 20' of sand dump-bailed on top.
- 5. Load the well as needed. Pressure test the casing above the plug to 500 psig for 30 min.
- 6. RU Wireline. Run CBL from 5,010' to surface. Record Top of Cement. All subsequent plugs below are subject to change pending CBL results.
- 7. PU & TIH w/ work string to +/- 5,010'.
- 8. PLUG #1: 54sx of Class C Cement (PPG, 1.22 yield); SA Top @ 3,930' | GB Top @ 3,704':
 Pump a 54 sack balanced cement plug inside the 5-1/2" casing (est. TOC @ +/- 3,604' & est. BOC @ +/- 4,090'). Wait on Cement for 4 hours, tag TOC w/ work string. *Note cement plug lengths & volumes account for excess.
- 9. POOH w/ work string. TIH & perforate squeeze holes @ +/- 3,408'. Establish circulation. TIH w/ work string.
- 10. PLUG #2: 163sx of Class C Cement (PPG, 1.22 yield); QN Top @ 3,358' | Int. Casing Shoe @ 2,905':
 Pump 72sx of cement in the 5-1/2" casing X 7-7/8" open hole annulus (est. TOC @ +/- 2,905' & est. BOC @ +/- 3,408'). Continue pumping 24sx of cement in the 5-1/2" casing X 8-5/8" casing annulus (est. TOC @ +/- 2,755' & est. BOC @ +/- 2,905'). Pump a 67 sack balanced cement plug inside the 5-1/2" casing (est. TOC @ +/- 2,805' & est. BOC @ +/- 3,408'). WOC for 4 hrs, tag TOC w/ work string. *Note cement plug lengths and volumes account for excess.
- 11. POOH w/ work string. TIH & perforate squeeze holes @ +/- 270'. Establish circulation.
- 12. PLUG #3: 73sx of Class C Cement (PPG, 1.22 yield); Surf. Casing Shoe @ 220':
 Pump 43sx of cement in the 5-1/2" casing X 8-5/8" casing annulus (est. TOC @ +/- 0' & est. BOC @ +/- 270'). Pump a 30 sack balanced cement plug inside the 5-1/2" casing (est. TOC @ +/- 0' & est. BOC @ +/- 270'). WOC for 4 hrs, tag TOC w/ work string. *Note cement plug lengths and volumes account for excess.
- 13. ND BOP, cut off Wellhead. Top off cement in surface casing annulus, if needed. Install a P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.

Formation	Depth ('MD)
Queen	3358
Greyberg	3704
San Andres	3930
Glorieta	5082
Blinebry	5716
Tubb	6042
Drinkard	6383




HILCORP ENERGY COMPANY NE DRI UN #904 P&A NOI





HILCORP ENERGY COMPANY NE DRI UN #904 P&A NOI



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 500073

CONDITIONS

Operator:	OGRID:
APACHE CORPORATION	873
303 Veterans Airpark Ln	Action Number:
Midland, TX 79705	500073
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
loren.diede	NMOCD requests that the sand above the RBP set at 5010' be cleaned off and that the RBP be pulled.	9/2/2025
loren.diede	NMOCD requests that the fish, (top of fish at 5135') consisting of 15 + jts tbg, O/O tool and pker) be fished and removed from the well.	9/2/2025
loren.diede	Set CIBP @ +/- 5666' and run CBL from there to surface.	9/2/2025
loren.diede	Place plugs to cover the following formation tops; Blinebry top = 5716', Glorietta top = 5082', San Andres top = 3930', Greyburg top = 3704', Queen top = 3358', Yates top = 2565', Base of Salt top = 2380' and Rustler = 1183'.	9/2/2025
loren.diede	Notify the OCD inspection supervisor via email 24 hours prior to beginning Plug & Abandon (P&A) operations.	9/2/2025
loren.diede	Submit the CBL tif file to NMOCD for upload into the Well Log File.	9/2/2025
loren.diede	NMOCD considers this well to be within the LPCH restricted area and a below-grade marker will be required. Submit the marker photo and GPS coordinates of the marker with the final P&A reports.	9/2/2025