Submit 3 Copies To Appropriate District  Office  State of New Mexico	Form C-103
District 1 Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-019-20135
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Braves Rd. Artes NM 87410	STATE FEE 🗵
District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Hage & Webb Land & Cattle Co.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	raige of Webb Land & Cattle Co.
PROPOSALS.)	8. Well Number Webb 3-23
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator	9. OGRID Number
SWEPI LP	250036
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 576, Houston, TX 77001	Wildcat
4. Well Location	
Unit Letter K: 1654+/- feet from the South line and 1646+/-	feet from the West line
Section 23 Township 11N Range 23E NMPM	County Guadalupe
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance	e from nearest surface water_N/A
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls: Constru	uction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
12. Check Appropriate Box to material value of Notice,	Report of Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WO	
TEMPORARILY ABANDON	RILLING OPNS. P AND A
TEMPORARILY ABANDON	RILLING OPNS. P AND A
TEMPORARILY ABANDON	RILLING OPNS. P AND A
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  d give pertinent dates, including estimated date
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  d give pertinent dates, including estimated date
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  d give pertinent dates, including estimated date
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  d give pertinent dates, including estimated date
TEMPORARILY ABANDON	RILLING OPNS. P AND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p. to ctoc 4600.
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  The properties of the ctoc 4600.
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  The properties of the ctoc 4600 proposed completion of the ctoc 4600.  The properties of the ctoc 4600 proposed completion of the ctoc 4600.  The properties of the ctoc 4600 proposed completion of the ctoc 4600 proposed completion of the ctoc 4600.
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  The properties of the ctoc 4600 proposed completion of the ctoc 4600.  The properties of the ctoc 4600 proposed completion of the ctoc 4600.  The properties of the ctoc 4600 proposed completion of the ctoc 4600 proposed completion of the ctoc 4600.
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  The proposed tach well by the man between the proposed completion of
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  The proposed tach well by the man between the proposed completion of
TEMPORARILY ABANDON	RILLING OPNS. PAND A  OT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  p to ctoc 4600.  when the standard of the standar
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  p to ctoc 4600.  p to ctoc 4600.  p to ctoc 4600.  p to ctoc 4600.  y, rih & perf @ 1200psi, sqz 100  ppsi no leaks & tagged @ 6259.  %, rih & perf @ 5841.  f 5/8 2 bpm @ 500psi circ, sqz 156 sx cmt  10 % leaked 100 lbs after 30 min. Perf
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  p to ctoc 4600.  when the stagged well and the stagged we
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  p to ctoc 4600.  when the stagged well and the stagged we
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p to ctoc 4600.  p to ctoc 4600.  when the stagged well and the stagged we
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion to to ctoc 4600?.  The performance of the
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion to to ctoc 4600?.  The performance of the
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion to to ctoc 4600?.  The performance of the
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DE PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  1/19/12 Set CIBP in 2 3/8" tubing @ 11947'.  1/20/12 Cut 2 3/8" tubing @ 11921', work pipe (not free).  1/21/12 Cut tubing @ 7600', work pipe (not free) Spot 100 sx cmt down tubing & dis 1/22/12 Attempt to pressure test plug, unable load & shut in 4 ½ & get pump rate do Sx cmt & disp to ctoc 6331', wait 4 ½ hrs & pressure test 4 ½ & 2 3/8 @ 1800 1/23/12 Cut tbg @ 6000', still stuck unable to work pipe free, circ down 2 3/8 & up 4 Bpm @ 700psi sqz 92 sx cmt & shut in well. Tagged @ 5297'.  1/24/12 Cut tubing @ 1000', pooh w/pipe perf @ 921'. Get pump rate down 4 ½ & 7 Leaving 400 ft in 7 5/8 & 10 ¼ & 100ft on rtnr tagged in 4 ½ @ 858'.  1/25/12 Spot 15 sx cmt @ 858' to ctoc 668' pressure test all casing strings @ 500psi. @ 450' & sqz cmt from surface till all csg had cmt returns 260 sx total, disp. 1/26/12 Cut off well head & rih w/ 1" in & tag cmt in 4 ½ @ 50', 7 5/8 @ 10', 10 ¼ @ Total.  1 hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion to toc 4600?.  The proposed completion of proposed completion of the pertine of 1 ½ bpm @ 1200psi, sqz 100 opsi no leaks & tagged @ 6259?.  ½, rih & perf @ 5841' get rate of 1 ½  5/8 2 bpm @ 500psi circ, sqz 156 sx cmt  10 ¾ leaked 100 lbs after 30 min. Perf  ¼ brl mud down each string.  22'. Fill all casing to surface w/15 sx  e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan .
TEMPORARILY ABANDON	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion to toc 4600?.  The proposed completion of proposed completion of the pertine of 1 ½ bpm @ 1200psi, sqz 100 opsi no leaks & tagged @ 6259?.  ½, rih & perf @ 5841' get rate of 1 ½  5/8 2 bpm @ 500psi circ, sqz 156 sx cmt  10 ¾ leaked 100 lbs after 30 min. Perf  ¼ brl mud down each string.  22'. Fill all casing to surface w/15 sx  e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan .
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DE PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEME! OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions; At or recompletion.  1/19/12 Set CIBP in 2 3/8" tubing @ 11947'.  1/20/12 Cut 2 3/8" tubing @ 11921', work pipe (not free).  1/21/12 Cut tubing @ 7600', work pipe (not free) Spot 100 sx cmt down tubing & dis 1/22/12 Attempt to pressure test plug, unable load & shut in 4 ½ & get pump rate do Sx cmt & disp to ctoc 6331', wait 4 ½ hrs & pressure test 4 ½ & 2 3/8 @ 180/123/12 Cut tbg @ 6000', still stuck unable to work pipe free, circ down 2 3/8 & up 4 Bpm @ 700psi sqz 92 sx cmt & shut in well. Tagged @ 5297'.  1/24/12 Cut tubing @ 1000', pooh w/pipe perf @ 921'. Get pump rate down 4 ½ & 7 Leaving 400 ft in 7 5/8 & 10 ½ & 100ft on rtnr tagged in 4 ½ @ 858'.  1/25/12 Spot 15 sx cmt @ 858' to ctoc 668' pressure test all casing strings @ 500psi. @ 450' & sqz cmt from surface till all csg had cmt returns 260 sx total, disp: 1/26/12 Cut off well head & rih w/ 1" in & tag cmt in 4 ½ @ 50', 7 5/8 @ 10', 10 ¼ @ Total.  1 hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines ⊠. a general permit ☐ SIGNATURE	RILLING OPNS. PAND A  OT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p. to ctoc 4600.  p. to ctoc 460
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ CASING/CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  1/19/12 Set CIBP in 2 3/8" tubing @ 11947'.  1/20/12 Cut 2 3/8" tubing @ 11921', work pipe (not free).  1/21/12 Cut tubing @ 7600', work pipe (not free) Spot 100 sx cmt down tubing & dis 1/22/12 Attempt to pressure test plug, unable load & shut in 4 ½ & get pump rate down Sx cmt & disp to ctoc 6331', wait 4 ½ hrs & pressure test 4 ½ & 2 3/8 @ 180/123/12 Cut tbg @ 6000', still stuck unable to work pipe free, circ down 2 3/8 & up 4 Bpm @ 700psi sqz 92 sx cmt & shut in well. Tagged @ 5297'.  1/24/12 Cut tubing @ 1000', pooh w/pipe perf @ 921'. Get pump rate down 4 ½ & 7 Leaving 400 ft in 7 5/8 & 10 ½ & 100 ft on rtnr tagged in 4 ½ @ 858'.  1/25/12 Spot 15 sx cmt @ 858' to ctoc 668' pressure test all casing strings @ 500psi. @ 450' & sqz cmt from surface till all csg had cmt returns 260 sx total, disp.  1/26/12 Cut off well head & rih w/ 1" in & tag cmt in 4 ½ @ 50', 7 5/8 @ 10', 10 ¼ @ Total.  1 hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit ☐ SIGNATURE ☐ TITLE P & A Supervisor (Basic Type or print name:	RILLING OPNS. PAND A  NT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion to toc 4600?.  The proposed completion of proposed completion of the pertine of 1 ½ bpm @ 1200psi, sqz 100 opsi no leaks & tagged @ 6259?.  ½, rih & perf @ 5841' get rate of 1 ½  5/8 2 bpm @ 500psi circ, sqz 156 sx cmt  10 ¾ leaked 100 lbs after 30 min. Perf  ¼ brl mud down each string.  22'. Fill all casing to surface w/15 sx  e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan .
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DE PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  1/19/12 Set CIBP in 2 3/8" tubing @ 11947'.  1/20/12 Cut 2 3/8" tubing @ 11921', work pipe (not free).  1/21/12 Cut tubing @ 7600', work pipe (not free) Spot 100 sx cmt down tubing & dis 1/22/12 Attempt to pressure test plug, unable load & shut in 4 ½ & get pump rate do Sx cmt & disp to ctoc 6331', wait 4 ½ hrs & pressure test 4 ½ & 2 3/8 @ 180(1/23/12) Cut tbg @ 6000', still stuck unable to work pipe free, circ down 2 3/8 & up 4 Bpm @ 700psi sqz 92 sx cmt & shut in well. Tagged @ 5297'.  1/24/12 Cut tubing @ 1000', pooh w/pipe perf @ 921'. Get pump rate down 4 ½ & 7 Leaving 400 ft in 7 5/8 & 10 ½ & 100ft on rtnr tagged in 4 ½ @ 858'.  1/25/12 Spot 15 sx cmt @ 858' to ctoc 668' pressure test all easing strings @ 500psi. @ 450' & sqz cmt from surface till all csg had cmt returns 260 sx total, disp.  1/26/12 Cut off well head & rih w/ 1" in & tag cmt in 4 ½ @ 50', 7 5/8 @ 10', 10 ¼ @ Total.  1 hereby certify that the information above is true and complete to the best of my knowledggrade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ SIGNATURE ☐ TITLE P & A Supervisor (Basic Type or print name: E-mail address:	RILLING OPNS. PAND A  OT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  p to ctoc 4600.
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DE PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  1/19/12 Set CIBP in 2 3/8" tubing @ 11947'.  1/20/12 Cut 2 3/8" tubing @ 11921', work pipe (not free).  1/21/12 Cut tubing @ 7600', work pipe (not free) Spot 100 sx cmt down tubing & dis 1/22/12 Attempt to pressure test plug, unable load & shut in 4 ½ & get pump rate do Sx cmt & disp to ctoc 6331', wait 4 ½ hrs & pressure test 4 ½ & 2 3/8 @ 180(1/23/12) Cut tbg @ 6000', still stuck unable to work pipe free, circ down 2 3/8 & up 4 Bpm @ 700psi sqz 92 sx cmt & shut in well. Tagged @ 5297'.  1/24/12 Cut tubing @ 1000', pooh w/pipe perf @ 921'. Get pump rate down 4 ½ & 7 Leaving 400 ft in 7 5/8 & 10 ½ & 100ft on rtnr tagged in 4 ½ @ 858'.  1/25/12 Spot 15 sx cmt @ 858' to ctoc 668' pressure test all easing strings @ 500psi. @ 450' & sqz cmt from surface till all csg had cmt returns 260 sx total, disp.  1/26/12 Cut off well head & rih w/ 1" in & tag cmt in 4 ½ @ 50', 7 5/8 @ 10', 10 ¼ @ Total.  1 hereby certify that the information above is true and complete to the best of my knowledggrade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ SIGNATURE ☐ TITLE P & A Supervisor (Basic Type or print name: E-mail address:	RILLING OPNS. PAND A  OT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  p to ctoc 4600.
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DE PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.  1/19/12 Set CIBP in 2 3/8" tubing @ 11947'.  1/20/12 Cut 2 3/8" tubing @ 11921', work pipe (not free).  1/21/12 Cut tubing @ 7600', work pipe (not free) Spot 100 sx cmt down tubing & dis 1/22/12 Attempt to pressure test plug, unable load & shut in 4 ½ & get pump rate do Sx cmt & disp to ctoc 6331', wait 4 ½ hrs & pressure test 4 ½ & 2 3/8 @ 180(1/23/12) Cut tbg @ 6000', still stuck unable to work pipe free, circ down 2 3/8 & up 4 Bpm @ 700psi sqz 92 sx cmt & shut in well. Tagged @ 5297'.  1/24/12 Cut tubing @ 1000', pooh w/pipe perf @ 921'. Get pump rate down 4 ½ & 7 Leaving 400 ft in 7 5/8 & 10 ½ & 100ft on rtnr tagged in 4 ½ @ 858'.  1/25/12 Spot 15 sx cmt @ 858' to ctoc 668' pressure test all easing strings @ 500psi. @ 450' & sqz cmt from surface till all csg had cmt returns 260 sx total, disp.  1/26/12 Cut off well head & rih w/ 1" in & tag cmt in 4 ½ @ 50', 7 5/8 @ 10', 10 ¼ @ Total.  1 hereby certify that the information above is true and complete to the best of my knowledggrade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ SIGNATURE ☐ TITLE P & A Supervisor (Basic Type or print name: E-mail address:	RILLING OPNS. PAND A  OT JOB  d give pertinent dates, including estimated date tach wellbore diagram of proposed completion p. to ctoc 4600.  p. to ctoc 460

Post Completion Webb 3-23

Surface: 1654' FSL, 1646' FWL, Sec 23, T11N, R23E Surface Elevation: 4554' KB: 22' to GL API#: 30-019-20135

Pinedale Anticline Field

ped Plug, Floats Held 14.75 971 10 3/4 40.5# K-55 3130 1580 STC R3 9.894 10.05 8.4 636 sx Surface CSG. 9.875 1178 sx ed Plug, Floats Held Full returns Prod 0 13,309 4-1/2" 13.5# P-110 12410 10670 3.795 3.92 0.0149 10.1 935 sx Per CBL: Flag Joints @ 9490', 10,980', 12,459' FC @ 13,281 FC @ 132 Drift Burst Collaps LNDG Profile 1D NO GO IE Туре Bore Upper Tree NIPPLE info. Lower Tree 4-1/16", 10 Date Frac'ed Proppant Infor Perf Top Perf Bot Shots Squeeze perfs @ 450', used 275 10,602 10,604 12 Open 0.641 10,625 10,627 12 by TVD 30/50 sx cement to plug all casing 10,649 12 strings from 450' to surface. Cut tubing @ 100 10,684 12 10,693 10,695 12 Cut off well head 6' below Squeeze perfs @ ground level. Weld plate on 10-**Cement Retainer** 3/4" string with Name, API# Pumped 156sx co 0.639 11.146 11,148 12 400' (16.7 bbl) in 11,165 11,167 12 5/8"x10-3/4" anı 11,187 11,189 12 (10.5 bbl) in 4-1/ 11,197 11,199 12 Squeeze perfs @ annulus, 55' (0.8 .5,841'. pumped 200' below retainer ir cement (42 sx) in 2-0.652 190' (15 sx) abov by TVD 11,588 11,589 3 3/8", 4-1/2", 7-5/8" 11,610 11,609 3 in 4-1/2" csg. csg from 5861'-11,631 11,632 3 5641'. Squeezed 50 11,658 11,659 3 sx cement in 7-5/8" 11.678 11.679 3 casing from perfs to 11,756 11,757 Open 0.652 TOC 6;300' Per CBL 11,776 11,777 shoe, 5841,-6201'. ackside by TVD 20/40 Econoprop 11,799 11,800 3 Tubing TOC= 5297'. FG high due to gas in the wellbe 6 11,818 11,820 11,840 11,842 6 Oct-08 5,160 11,903 11,904 3 Open 11,930 11,932 6 ackside by TVD Econoprop 135000 11,993 11,995 6 60 Quality N2 pumped 12.008 12,010 12,071 12,072 0.688 Oct-08 5.230 12,091 12,092 by TVD 20/40 12,000 12,114 12,115 100,000 Versaprop 12,126 12,127 3 12,142 12,143 3 12,150 12,151 3 60 Quality N2 pu 12,162 12,163 12,223 12,224 5,345 Oct-08 12,247 12,248 3 12,276 12,277 3 12.346 12.347 3 FG high due to gas ? 12,379 12,380 3 60 Quality N2 pumped Shot perfs from 12,440-12,442'. 12,405 12,406 3 12,426 12,428 12,480 12,481 0.601 Baker pkr @ 12,016' 12,490 12,491 3 by TVD 86200 CIBP set in 2 3/8" @ 12,501 12,502 3 Carboorop 56.800 11.971'. Cut tubing @ 12,522 12,523 12,545 11.921' and @ 8150'. 12,544 Pump 200 sx cement. 12,565 12,566 FG high due to gas ? 60 Quality N2 pumped 22 bbls in annulus, tubing TOC 6259'. 12,625 12,626 3 28-Oct-08 0.597 0 Oct-08 5.500 12,652 12,654 6 by TVD 20/40 CP 20/40 105000 12,692 12,693 3 12,705 12,706 60 Quality N2 pumped 12,767 12.869 12,871 6 0.709 Oct-08 5 590 12,910 12,911 by TVD 20/40 CP 20/40 52,000 PBTD: 13,200' CTM 12,931 FC per Tally: 13,305' 12,950 12,951 12,972 12,973 FC per CBL 13,2811 12,998 13,000 4-1/2" @ 13;309' 13,039 TD @ TMD: 13,327' 13,052 13,057 15 13.068 13.078

BHT: 218 @ 13,327



## **Shell Exploration & Production**

State of New Mexico Energy, Minerals and Natural Resources Dept. Oil Conservation Division-District 4 1220 South St. Francis Drive Sante Fe, New Mexico 87505 Attn.: Ed Martin, District Supervisor

Shell Exploration & Production Co.

Regulatory Affairs-EP Americas 4582 S. Ulster Street Parkway Suite 1400 Denver, Colorado 80237

January 7, 2013

Subject:

Subsequent Notice of Plugging and Abandonment

Shell Exploration & Production Co., Webb 3-23 (API No. 30-019-20135)

Guadalupe County, New Mexico

Dear Mr. Martin:

Shell Exploration & Production Company (Shell), as service provider to SWEPI LP in New Mexico, is submitting a Subsequent Notice of Plugging and Abandonment (Form C-103) to detail well plugging and abandonment activities conducted for the subject well, to New Mexico Oil Conservation Division-District 4 (OCD) for your review and approval.

If you have any questions or require any additional information regarding these reports, please contact me at (303) 222-6347, or Steve Compton at (303) 305-4017.

Regards,

Michael L. Bergstrom

Senior Regulatory Advisor

Shell Exploration & Production Company

Attachments: Form C-103

Mechanical Well Sketch