

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr. OGD  
Santa Fe, NM 87505

2013 JUL 29 P 2: 59

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-021-20542
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other X CO2		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> P <input type="checkbox"/>
2. Name of Operator Hess Corporation		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 840 Seminole TX 79360		7. Lease Name or Unit Agreement Name West Bravo Dome Unit
4. Well Location Unit Letter J : 1650 feet from the S line and 1650 feet from the E line Section 32 Township 19N Range 30E NMPM County Harding		8. Well Number 322J
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4400 GR		9. OGRID Number 495
		10. Pool name or Wildcat West Bravo Dome CO2 Gas

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: rePerf prod casing <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1930 322J	MIRU pulling unit, and equipment. Set up and hook tanks. Unset packer and circulate casing with produced water to kill well. (If packer wont unset, run in w/plug and set plug in packer. Pull off from packer & TOH w/fiberglass tbg & LD. PU & TIH w/ workstring & latch onto packer. TOH w/workstring & packer) ND WH & NU BOPs TOOH and standback fiberglass tubing and packer. Ensure casing is loaded w/produced water to keep well dead. CI well.	MIRU TOOH w/tbg & packer
08/12/2013	MIRU wireline services. Tag P6TD to determine fill. Get on depth w/CL and perforate from 1893'-1920' & 1927' - 1940' w/ 6 spf (RAZR charge - 3- 3/8" gun, 25 gm charge, 0.47" entry hole, 46.11 penetration) RDMO wireline services. If fill found, TIH w/ hit and clean out. TOH w/tbg and LD. Keep well SI	Perforation job
	Kill well (trickle water down the casing). Pickup and run new Vweatherford AS packer with workstring with on/off tool on bottom of workstring and set @ 1860 ft, unlatch from packer & TOH & LD workstring. PU & TIH w/fiberglass tbg (check how much tension is needed for fiberglass tubing) Latch back into packer and & space out.	Replace tubing bonnet & TIH w/fiberglass tubing
	ND BOPs NU wellhead Pressure test the casing to 500 psi for 30 mins. Clean well site & RDMO Return well back to production	RDMO & return to production

Spud Date: 04/17/2012

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rita C Smith TITLE Senior Regulatory Analyst DATE 7-24-2013

Type or print name Rita C Smith E-mail address: rsmith@hess.com PHONE: 432-758-6726

For State Use Only

APPROVED BY: Ed Martin TITLE DISTRICT SUPERVISOR DATE 7/30/2013  
Conditions of Approval (if any):

**WBDGU 1930 322J Workover Procedure**

Date: 06/21/2013

Well name:	WBDGU 1930 322J	
API#	3002120542	
KB/GU	4412'/4400'	
Conductor size/weight	14" 104.2# @ 40'	
Surface size/weight	8 5/8", 24# @ 758'	
Prod casing size/weight	5 1/2" @ 2165'	
PBTD		
TD	2169'	
DOD		
Tubing size	2 3/8" fiberglass @ 1920'	
Perfs	1950' - 1970'	
Open Hole		
Engineer:	Madhuran Shah- Cell: 832-491-4519, email: mshah@hess.com	
WO Summary:	Frac did not get to the top and well needs to be perfed in the zone above current perforations	
NOTE's:	Need workstring, jars, bits, elevators/slips Well will be re perfed in the upper zone & lower zone to increase injectivity	
Day	Description	Daily Snap Shot
1	MIRU pulling unit, and equipment. Set up and hook tanks. Unset packer and circulate casing with produced water to kill well. (If packer wont unset, run in w/plug and set plug in packer, pull off from packer & TOH w/fiberglass tbg & LD. PU & TIH w/ workstring & latch onto packer. TOH w/workstring & packer). ND WH & NU BOPs. TOOH and standback fiberglass tubing and packer. Ensure casing is loaded w/produced water to keep well dead. CI well.	MIRU, TOOH w/tbg & packer
2	MIRU wireline services. Tag PBTD to determine fill. Get on depth w/CL and perforate from 1893'-1920' & 1927' - 1940' w/ 6 spf (RAZR charge - 3- 3/8" gun, 25 gm charge, 0.47" entry hole, 46.11 penetration) RDMO wireline services. If fill found, TIH w/ bit and clean out. TOH w/bit and LD. Keep well SI	Perforation job
3	Kill well (trickle water down the casing). Pickup and run new Weatherford AS packer with workstring with on/off tool on bottom of workstring and set @ 1860 ft, unlatch from packer & TOH & LD workstring. PU & TIH w/fiberglass tbg (check how much tension is needed for fiberglass tubing). Latch back into packer and & space out.	Replace tubing bonnet & TIH w/fiberglass tubing
4	ND BOPs NU wellhead. Pressure test the casing to 500 psi for 30 mins. Clean well site & RDMO. Return well back to production	RDMO & return to production