

Atchafalaya Measurement Inc
416 East Main Street, Artesia NM 88210 575-746-3481

Sample Information

	Sample Information
Sample Name	OXY__Burton Flats CTB Production__GC2-73019-12
Station Number	14071P
Lease Name	Burton Flats CTB Production
Analysis For	OXY USA
Producer	OXY USA
Field Name	Burton Flats
County/State	N/A
Frequency/Spot Sample	Spot
Sampling Method	Fill Empty
Sample Deg F	97
Atmos Deg F	79
Flow Rate	153.142
Line PSIG	48
Date Sampled/Time Sampled	7-23-19
Cylinder Number	N/A
Cylinder Clean Date	N/A
Sampled By	Derek Sauder
Analysis By	Pat Silvas
Verified/Calibrated Date	7-29-19
Report Date	2019-07-30 10:46:10

Component Results

Component Name	Ret. Time	Peak Area	Norm%	GPM (Dry) (Gal. / 1000 cu.ft.)
Nitrogen	23.100	30269.9	2.1819	0.000
H2S	0.000	0.0	0.0000	0.000
Methane	23.860	787502.9	75.1296	0.000
Carbon Dioxide	27.900	5825.9	0.3597	0.000
Ethane	36.960	202456.6	11.6915	3.121
Propane	77.160	133263.6	5.8157	1.600
i-Butane	29.820	64807.6	0.7713	0.252
n-Butane	32.080	165504.2	1.9549	0.615
i-Pentane	39.120	49926.9	0.5126	0.187
n-Pentane	41.900	54913.2	0.5487	0.199
C6's	50.750	43911.0	0.3860	0.158
C7's	67.000	54984.0	0.4654	0.214
C8's	84.000	18044.0	0.1628	0.083
C9's	102.000	4888.0	0.0159	0.009
C10 Plus	146.000	1090.0	0.0040	0.002
Total:			100.0000	6.441

Results Summary

Result	Dry	Sat. (Base)
Total Raw Mole% (Dry)	103.9585	
Pressure Base (psia)	14.650	
Temperature Base	60.00	
Gross Heating Value (BTU / Ideal cu.ft.)	1294.9	1272.2
Gross Heating Value (BTU / Real cu.ft.)	1300.1	1277.9
Relative Density (G), Ideal	0.7687	0.7661
Relative Density (G), Real	0.7715	0.7692
Compressibility (Z) Factor	0.9960	0.9956

UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Burton Flats CTB**Date:** 09/11/2021**Duration of event:** 1 Hours 15 Minutes**MCF Flared:** 80**Start Time:** 09:15 AM**End Time:** 10:30 AM**Cause:** Compressor Scheduled Maintenance > OOOOa Leak Repair**Method of Flared Gas Measurement:** Gas Flare Meter**Well API Associated with Facility:** 30-015-43123 Charlie Chocolate 14 15 Federal Com #031H

Comments: This upset event was not caused by any wells associated with the facility. This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control.

1. Reason why this event was beyond Operator's control:

USA Compression, who is the owner of the gas compressor unit, was scheduled to fix an OOOOa emissions leak on the compressor that had been identified during a routine LDAR inspection. The compressor unit was anticipated to be shut down a very minimal amount of time for the scheduled maintenance repair to be completed and it was projected that the field psi would be low enough that flaring should not occur during the down time the compressor unit was offline.

Approximately, around 08:15 AM, USA Compression's mechanic was on-site and had let the facility's Oxy production tech know that the gas compressor would be shut down as planned but would only be down for a very brief period to perform a quick compressor unit leak repair and didn't anticipate a flaring event to occur, given that the unit would not be shut down long. Around 08:30 AM, the compressor unit was shut down, and the Oxy production techs received a compressor shut down alarm. Due to unexpected issues with the repair of the OOOOa emissions leak from the gas compressor unit, the USA compressor mechanic had the gas compressor unit shut down for longer than originally planned and during that time, the field psi began to steadily increase until it reached a psi level which triggered a flaring event around 09:15 AM. Although this was a planned scheduled maintenance repair, it was unanticipated that the leak repair on the gas compressor unit would exceed the original time planned for or that the field psi would steadily increase until a flaring event was stimulated. This event is completely out of Oxy's control to prevent from happening, or avoid as Oxy is not in control of the maintenance repairs for the gas compressor unit or how long a repair will take to perform, and it cannot make repairs or maintenance to the gas compressor unit.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route all stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, as the part of the overall process or steps to take to limit duration and magnitude of flaring. Oxy personnel are in the field 24/7 and can physically see when we are flaring which in turn are communicated to additional Oxy field personnel. Internal OXY procedures ensure that upon gas compressor unit and/or multiple unit shutdown alarms, increased sensor pressure alarms, etc., field production technician personnel are promptly notified, and are instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize

emissions. Oxy production technicians must assess whether the issue or circumstance is due to damage and repair is needed, or whether there are other reasons for its cause.

In this case, USA Compression, who is the owner of the gas compressor unit, was scheduled to fix an OOOOa emissions leak on the compressor that had been identified during a routine LDAR inspection. The compressor unit was anticipated to be shut down a very minimal amount of time for the scheduled maintenance repair to be completed and it was projected that the field psi would be low enough that flaring should not occur during the down time the compressor unit was offline. USA Compression's mechanic was on-site and had let the facility's Oxy production tech know that the gas compressor would be shut down as planned but would only be down for a very brief period to perform a quick compressor unit leak repair and didn't anticipate a flaring event to occur, given that the unit would not be shut down long. Around 08:30 AM, the compressor unit was shut down, and the Oxy production techs received a compressor shut down alarm. Due to unexpected issues with the repair of the OOOOa emissions leak from the gas compressor unit, the USA compressor mechanic had the gas compressor unit shut down for longer than originally planned and during that time, the field psi began to steadily increase until it reached a psi level which triggered a flaring event around 09:15 AM. USA compressor mechanic completed the leak repair and restarted the gas compressor unit. Shortly thereafter, flaring ceased once gas compressor unit was working at normal operating conditions and speed.

Although this was a planned scheduled maintenance repair, it was unanticipated that the leak repair on the gas compressor unit would exceed the original time planned for or that the field psi would steadily increase until a flaring event was stimulated.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as Oxy is not in control of the maintenance repairs for the gas compressor unit or how long a repair will take to perform, and it cannot make repairs or maintenance to the gas compressor unit. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. This incident was completely out of OXY's control to prevent from happening. The only actions that Oxy can take and handle that is within its control, is to continually collaborate with USA Compression, who owns the gas compressor unit, on the unit's scheduled maintenance, so that future maintenance necessitating the shut down of the unit will allow Oxy to determine if additional measures need to be taken to avoid flaring during those maintenance periods, such as shutting in production wells.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 52219

QUESTIONS

Operator: OXY USA WTP LIMITED PARTNERSHIP P.O. Box 4294 Houston, TX 772104294	OGRID: 192463
	Action Number: 52219
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2126552654] BURTON FLATS FED CTB

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Compressor Scheduled Maintenance > OOOOa Leak Repair

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	75
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	09/11/2021
Time venting and/or flaring was discovered or commenced	09:15 AM
Time venting and/or flaring was terminated	10:30 AM
Cumulative hours during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 80 Mcf Recovered: 0 Mcf Lost: 80 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting and/or flaring a result of downstream activity	No
Was notification of downstream activity received by you or your operator	Not answered.
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	<p>USA Compression, who is the owner of the gas compressor unit, was scheduled to fix an OOOOa emissions leak on the compressor that had been identified during a routine LDAR inspection. The compressor unit was anticipated to be shut down a very minimal amount of time for the scheduled maintenance repair to be completed and it was projected that the field psi would be low enough that flaring should not occur during the down time the compressor unit was offline. Approximately, around 08:15 AM, USA Compression's mechanic was on-site and had let the facility's Oxy production tech know that the gas compressor would be shut down as planned but would only be down for a very brief period to perform a quick compressor unit leak repair and didn't anticipate a flaring event to occur, given that the unit would not be shut down long. Around 08:30 AM, the compressor unit was shut down, and the Oxy production techs received a compressor shut down alarm. Due to unexpected issues with the repair of the OOOOa emissions leak from the gas compressor unit, the USA compressor mechanic had the gas compressor unit shut down for longer than originally planned and during that time, the field psi began to steadily increase until it reached a psi level which triggered a flaring event around 09:15 AM. Although this was a planned scheduled maintenance repair, it was unanticipated that the leak repair on the gas compressor unit would exceed the original time planned for or that the field psi would steadily increase until a flaring event was stimulated. This event is completely out of Oxy's control to prevent from happening, or avoid as Oxy is not in control of the maintenance repairs for the gas compressor unit or how long a repair will take to perform, and it cannot make repairs or maintenance to the gas compressor unit.</p>
Steps taken to limit the duration and magnitude of venting and/or flaring	<p>In this case, USA Compression, who is the owner of the gas compressor unit, was scheduled to fix an OOOOa emissions leak on the compressor that had been identified during a routine LDAR inspection. The compressor unit was anticipated to be shut down a very minimal amount of time for the scheduled maintenance repair to be completed and it was projected that the field psi would be low enough that flaring should not occur during the down time the compressor unit was offline. USA Compression's mechanic was on-site and had let the facility's Oxy production tech know that the gas compressor would be shut down as planned but would only be down for a very brief period to perform a quick compressor unit leak repair and didn't anticipate a flaring event to occur, given that the unit would not be shut down long. Around 08:30 AM, the compressor unit was shut down, and the Oxy production techs received a compressor shut down alarm. Due to unexpected issues with the repair of the OOOOa emissions leak from the gas compressor unit, the USA compressor mechanic had the gas compressor unit shut down for longer than originally planned and during that time, the field psi began to steadily increase until it reached a psi level which triggered a flaring event around 09:15 AM. USA compressor mechanic completed the leak repair and restarted the gas compressor unit. Shortly thereafter, flaring ceased once gas compressor unit was working at normal operating conditions and speed. Although this was a planned scheduled maintenance repair, it was unanticipated that the leak repair on the gas compressor unit would exceed the original time planned for or that the field psi would steadily increase until a flaring event was stimulated.</p>
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	<p>Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as Oxy is not in control of the maintenance repairs for the gas compressor unit or how long a repair will take to perform, and it cannot make repairs or maintenance to the gas compressor unit. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. This incident was completely out of OXY's control to prevent from happening. The only actions that Oxy can take and handle that is within its control, is to continually collaborate with USA Compression, who owns the gas compressor unit, on the unit's scheduled maintenance, so that future maintenance necessitating the shut down of the unit will allow Oxy to determine if additional measures need to be taken to avoid flaring during those maintenance periods, such as shutting in production wells.</p>

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 52219

CONDITIONS

Operator: OXY USA WTP LIMITED PARTNERSHIP P.O. Box 4294 Houston, TX 772104294	OGRID: 192463
	Action Number: 52219
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	9/27/2021