



Certificate of Analysis

Number: 6030-24091009-001A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

Field: PERMIAN_RESOURCES
Station Name: Precious CTB Train 2 Check (FMP)
Station Number: 17622C
Station Location: OP-DELSE-BT001
Sample Point: Meter
Property ID: FMP/LSE NMNM021640
Formation: NEW_MEXICO
County:
Well Name: CTB
Type of Sample: : Spot-Cylinder
Heat Trace Used: N/A
Sampling Method: : Fill and Purge
Sampling Company: : OXY

Report Date: 10/01/2024
Sampled By: JE
Sample Of: Gas Spot
Sample Date: 09/26/2024 13:20
Sample Conditions: 93 psig, @ 98 °F Ambient: 91 °F
Received Date: 09/27/2024
Login Date: 09/27/2024
Effective Date: 09/26/2024 13:20
Flow Rate: 29099 MSCFD
Method: GPA-2261M
Cylinder No: 1111-006946
Instrument: 70142339 (Inficon GC-MicroFusion)
Last Inst. Cal.: 09/30/2024 0:00 AM
Analyzed: 10/01/2024 07:26:38 by CDW

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia
Hydrogen Sulfide	0.0000	0.0000	0.0000	
Nitrogen	1.7253	1.7041	2.0874	
Carbon Dioxide	1.0578	1.0448	2.0106	
Methane	73.9778	73.0679	51.2561	
Ethane	12.5600	12.4055	16.3110	3.313
Propane	6.5193	6.4391	12.4156	1.771
Iso-Butane	0.9178	0.9065	2.3039	0.296
n-Butane	2.3489	2.3200	5.8963	0.730
Iso-Pentane	0.5471	0.5404	1.7049	0.197
n-Pentane	0.6197	0.6121	1.9311	0.222
Hexanes	0.4167	0.4116	1.5510	0.169
Heptanes	0.3668	0.3623	1.5874	0.167
Octanes	0.1597	0.1577	0.7877	0.081
Nonanes Plus	0.0283	0.0280	0.1570	0.016
	101.2452	100.0000	100.0000	6.962

Calculated Physical Properties

Calculated Molecular Weight	Total	C9+
Compressibility Factor	22.87	128.26
Relative Density Real Gas	0.9958	
	0.7927	4.4283

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.65 psia & 60°F

Real Gas Dry BTU	1323.6	6974.4
Water Sat. Gas Base BTU	1301.0	6852.4
Ideal, Gross HV - Dry at 14.65 psia	1318.0	6944.9
Ideal, Gross HV - Wet	1295.0	6820.4

Comments: H2S Field Content: 0 ppm

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated. The test results apply to the sample as received.

**UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM****Facility Id#** fAPP2317679662**Facility:** Precious NC 31 CTB**Duration of Event:** 20 Minutes**Start Time:** 12:00 AM**Operator:** OXY USA, Inc.**Flare Date:** 08/12/2025**MCF Flared:** 51**End Time:** 12:20 AM**Cause:** Emergency Flare > Third Party Downstream Activity > Enterprise > Orla Plant > Continuing Operational Issues**Method of Flared Gas Measurement:** Gas Flare Meter

1. Reason why this event was beyond Operator's control:

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction or complete shut-in of a gas pipeline by a third-party pipeline compressor station operator, which impacted OXY's ability to send gas to them. This interruption, restriction or complete shut-in of the gas pipeline by a third-party pipeline compression station operator is downstream of OXY's custody transfer point and out of OXY's control to foresee, avoid or prevent from happening and did not stem from any of OXY's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. In this case, intermittent flaring persisted after Enterprise's emergency shutdown at their Orla Plant, causing an unplanned halt of sales gas intake from OXY. This emergency shutdown was not communicated in advance to OXY and no updates on ongoing operational issues were provided during this period. This lack of communication significantly hindered OXY's ability and capacity to prevent intermittent flaring from occurring. OXY's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any additional advance warning to the personnel at OXY regarding continual possible interruptions in sales gas flow intake or operational matters that might impact on its facilities. If Enterprise had provided prior notification to OXY personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of gas being sent to the facility and to sales, which in turn would have mitigated the chances of a flaring event occurring. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. The occurrence of this event was beyond OXY's control. The duration and magnitude of this flaring event were attributable to multiple intermittent flares occurring throughout the period.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond OXY's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen emissions as much as possible. In this case, intermittent flaring persisted after Enterprise's emergency shutdown at their Orla Plant, causing an unplanned halt of sales gas intake from OXY. The shutdown was not communicated in advance, and no updates on ongoing operational issues were provided the next morning despite OXY's outreach. This lack of communication significantly hindered OXY's ability and capacity to prevent intermittent flaring from occurring. OXY's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any additional advance warning to the personnel at OXY regarding continual possible interruptions in sales gas flow intake or operational matters that might impact OXY's facilities. OXY's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless,

Enterprise did not provide any advance warning to the personnel at OXY regarding possible interruptions in sales gas flow intake or operational matters which might impact OXY's facilities. If Enterprise had provided prior notification to OXY personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of gas being sent to the facility and to sales, which in turn would have mitigated the chances of a flaring event occurring. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. Once flaring was triggered again, OXY production technicians promptly continued to choke back several additional wells and decreased injection rates in the affected area. These measures were taken to reduce field pressure below the flare activation thresholds of the facility to cease flaring. The occurrence of this event was beyond OXY's control. OXY took all possible measures to manage and reduce emissions to the greatest extent.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

OXY is not in a position to implement corrective measures to address the root cause and prevent future incidents of a gas flow restriction, shut-in or suspension in the Enterprise offload sales gas pipeline, since this matter is beyond OXY's custody transfer point and outside of OXY's capacity to correct or keep from happening again. When Enterprise and its operations encounter operational or equipment issues or have difficulty managing the sales gas transmission flow volume from OXY inefficiently, Enterprise then restricts OXY's ability to proceed with its sales gas transmission. OXY is committed to minimizing emissions as much as possible and aims to maintain open communication with its downstream and midstream operators, when feasible, to handle such events effectively.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 499937

DEFINITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 499937
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 499937

QUESTIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 499937
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Prerequisites <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i>	
Incident Well	Unavailable.
Incident Facility	[fAPP2317679662] Precious NC 31 CTB

Determination of Reporting Requirements <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.
<i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Third Party Downstream Activity > Enterprise > Orla Plant > Continuing Operational Issues

Representative Compositional Analysis of Vented or Flared Natural Gas <i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	73
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0
<i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i>	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 499937

QUESTIONS (continued)

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 499937
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	08/12/2025
Time vent or flare was discovered or commenced	12:00 AM
Time vent or flare was terminated	12:20 AM
Cumulative hours during this event	0

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 51 Mcf Recovered: 0 Mcf Lost: 51 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	Yes
Was notification of downstream activity received by this operator	No
Downstream OGRID that should have notified this operator	[713731] Enterprise Crude Pipeline LLC
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	In this case, intermittent flaring persisted after Enterprise's emergency shutdown at their Orla Plant, causing an unplanned halt of sales gas intake from OXY. The shutdown was not communicated in advance, and no updates on ongoing operational issues were provided the next morning despite Oxy's outreach. This lack of communication significantly hindered Oxy's ability and capacity to prevent intermittent flaring from occurring. Oxy's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any additional advance warning to the personnel at Oxy regarding continual possible interruptions in sales gas flow intake or operational matters that might impact OXY's facilities. If Enterprise had provided prior notification to Oxy personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of gas being sent to the facility and to sales, which in turn would have mitigated the chances of a flaring event occurring. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. The occurrence of this event was beyond OXY's control. The duration and magnitude of this flaring event were attributable to multiple intermittent flares occurring throughout the period.
	It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. The flare at this facility has a 98% combustion efficiency to lessen

Steps taken to limit the duration and magnitude of vent or flare	emissions as much as possible. In this case, intermittent flaring persisted after Enterprise's emergency shutdown at their Orla Plant, causing an unplanned halt of sales gas intake from OXY. The shutdown was not communicated in advance, and no updates on ongoing operational issues were provided the next morning despite Oxy's outreach. This lack of communication significantly hindered Oxy's ability and capacity to prevent intermittent flaring from occurring. Oxy's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any additional advance warning to the personnel at Oxy regarding continual possible interruptions in sales gas flow intake or operational matters that might impact OXY's facilities. Oxy's field and operations teams diligently oversee the facility to swiftly identify any deviations from standard operational parameters. Nevertheless, Enterprise did not provide any advance warning to the personnel at Oxy regarding possible interruptions in sales gas flow intake or operational matters that might impact OXY's facilities. If Enterprise had provided prior notification to Oxy personnel, field and operation personnel would have adjusted and balanced the wells to reduce the amount of gas being sent to the facility and to sales, which in turn would have mitigated the chances of a flaring event occurring. Although flaring is not OXY's preferred method for handling excess gas, it is necessary to ensure the safety of our operations, equipment, and field personnel. Once flaring was triggered
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	OXY is not in a position to implement corrective measures to address the root cause and prevent future incidents of a gas flow restriction, shut-in or suspension in the Enterprise offload sales gas pipeline, since this matter is beyond OXY's custody transfer point and outside of OXY's capacity to correct or keep from happening again. When Enterprise and its operations encounter operational or equipment issues or have difficulty managing the sales gas transmission flow volume from OXY inefficiently, Enterprise then restricts OXY's ability to proceed with its sales gas transmission. OXY is committed to minimizing emissions as much as possible and aims to maintain open communication with its downstream and midstream operators, when feasible, to handle such events effectively.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 499937

ACKNOWLEDGMENTS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 499937
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

☒	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
☒	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
☒	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 499937

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 499937
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	8/27/2025