

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

MAY 13 2015
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB151344350

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>200737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-106H Flow line, the spill is 2003 ft. East of the well pad. UL "J"	Facility Type: Exploration and Production

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-015-37063
------------------------------------	------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	36	22S	30E					Eddy

Latitude N 32.34644° Longitude W 103.83291°

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 24 bbls	Volume Recovered: 20
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 5/3/15, time unknown	Date and Hour of Discovery: 5/3/15 at approximately 2:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson, company e-mail	
By Whom? Tony Savoie	Date and Hour: 5/3/15 at 6:39 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The flow line developed a leak due to corrosion, a temporary leak clamp was placed on the affected area until the well could be shut down and a joint of pipe replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 1,020 sq.ft. of pasture. All of the free standing fluid was picked up with a vacuum truck. The stained area was left as is pending the final remediation. The spill area will be cleaned up in accordance to the NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>5/14/15</i>	Expiration Date:
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: <i>5/13/15</i> Phone: 432-556-8730	LATER THAN: <i>5/15/2015</i>	

* Attach Additional Sheets If Necessary

2RP-2999

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, B. Biehl, JR Smitherman, SF Johnson, W Hanna
G Fletcher, J Fuqua, C Giese, J Brooks, M Titsworth, A Ruth, A Thompson, B Blevins, K Bright

DATE: May 3, 2015

LOCATION OF SPILL SITE: JRU 106 Flowline 2003 Ft. East of well pad (API 30-015-37063)

UL "J" 36-23S-30E, Eddy Co. N.M.

GPS COORDINATES (Lat & Long): 32.34644 -103.83291

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Follow-up report when numbers are known

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled			BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:	24	20	4	Water:		0		0
Contained in impervious liner -	Oil:			0	Water:				0
	Total:	24	20	4	Water:		0	0	0





DESCRIPTION (What happened?):


EHS was notified of a release that occurred on the JRU 106 flowline. Release was due to external corrosion

SPILL RESPONSE (How was the spill cleaned up?):

Vacuum truck came out to location and recovered 20 bbls of oil. Further remediation will be planned

PICTURE ATTACHMENT:






Data use subject to license.

© DeLorme. Topo North America™ 10.

www.delorme.com



Scale 1 : 12,800



1" = 1,066.7 ft Data Zoom 14-0