

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87501

RECEIVED
State of New Mexico
Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Occidental Permian Limited Partnership	Contact Steven M. Bishop
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (575) 397-8251
Facility Name South Hobbs Unit Test Site #502	Facility Type Production
Flow line for South Hobbs Unit #191	

Surface Owner Mr. Malcolm Coombes	Mineral Owner	Lease No. API 30-025-28983
-----------------------------------	---------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
'M'	5	19-S	38-E					LEA

Latitude N32.68516° Longitude W103.16074°

NATURE OF RELEASE

Type of Release Produced water and oil	Volume of Release 2 bbls oil X 100 bbls water	Volume Recovered 80 bbls water
Source of Release 3" check valve at header	Date and Hour of Occurrence 07/06/2009 5:30 PM	Date and Hour of Discovery 07/06/2009 5.30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Mark Whitaker	
By Whom? Steve M. Bishop	Date and Hour 07/06/2009 06:50 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
gwgzz1

Describe Cause of Problem and Remedial Action Taken.* A check valve at the South Hobbs Unit Test Site 502, on the flow line for South Hobbs Unit #191, broke at the victaulic coupling causing release. Valves on the header and at the well were shut to isolate the line and stop flow. Most fluid was around header and in a caliche lease road. A 6' x 150' stream ran to the south down a lease road, some believed to be rain water due to recent rains in the area. An area about 6' X 50' did enter the pasture to the south of the header. Land owner was informed about water in pasture and will be dealt with on damages.

Describe Area Affected and Cleanup Action Taken.*
Spilled fluid ran around header and approximately 150' to the south down a caliche lease road, some believed to be rain water due to recent rains in the area. A small area of pasture approximately 6' x 50' to the south of the location was also affected. 80 bbls of water was recovered. Land owner was contacted regarding the spill. Area will be remediated to NMOCD spill guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Steven M. Bishop</i>	OIL CONSERVATION DIVISION	
Printed Name: Steven M. Bishop	Approved by ENV ENGINEER <i>Stephany Laking</i>	Approved by District Supervisor
Title: HES Specialist	Approval Date: 07/09/09	Expiration Date: 09/08/09
E-mail Address: Steven_Bishop@oxy.com	Conditions of Approval: DELIVERATE TO CLEAN + 1, SUBMIT FINAL C-141 BY 09/08/09.	Attached <input type="checkbox"/>
Date: 07/07/2009	Phone: (575) 397-8251	IRP-09-7-22-24

* Attach Additional Sheets If Necessary

FGIRL 0922634004



Occidental Permian Limited Partnership

July 07, 2009

New Mexico Oil Conservation Division
District I
1625 N. French Drive
Hobbs, New Mexico 88240

RECEIVED
JUL 08 2009
HOBBSOCD

Attn: Environmental Engineering

RE: Remediation Plan
South Hobbs Unit #191 Flow Line Check at
South Hobbs Unit Test Site #502 Header
UL 'M', Sec. 5, T-19-S, R-38-E
SHU #191 API # 30-025-28983

Leak occurred on 07/06/2009, at approximately 5:30 PM. A check valve at the South Hobbs Unit Test Site 502 header serving the flow line for South Hobbs Unit #191 broke at a Victaulic coupling causing release. Valves were shut at the header and at the well to isolate the line and shut off flow. The area affected by this spill is an area around the header, and water stood south down a caliche lease road approximately 6' wide and 150' long. A small amount of produced water measuring approximately 6' wide and 50' long, ran to the south into the pasture. An estimated 2 barrels of oil and 100 barrels of produced water was originally estimated on the ground, much of which was probably rain water in the road. 80 barrels of water were recovered via vacuum truck. Area was covered with sand to keep cattle from drinking. Mr. Malcolm Coombes is the surface owner and utilizes the area for grazing and storage. Depth to ground water according to State Engineers Office is an average of 48', for all wells in the area, giving this spill site a ranking of 20. Remediation of the spill site will be as follows:

1. Affected area will be excavated and soil will be disposed of at Sundance Services, Parabo Faciltiy near Eunice, NM.
2. Soil samples will be gathered from affected area.
3. NMOCD guidelines will be used to insure entire site is in compliance with guidelines.
4. Any soils removed will be replaced with clean fresh soils, where needed.

Page 2

5. Soil analysis data will be submitted with final closure letter.

If you have any questions, or if I can be of further assistance, please contact me at (575) 397-8251.

A handwritten signature in black ink that reads "STEVEN M. BISHOP". The signature is written in a cursive style with a large, stylized initial 'S'.

Steven M. Bishop
HES Spec/COA-Hobbs Area
Steven_Bishop@oxy.com
(575) 397-8251

Attachments: Initial C-141