

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

**P.O. Box 2088**

**Santa Fe, New Mexico 87504-2088**

**WELL API NO.**

**30-021-20026**

**5. Indicate Type of Lease**

**STATE** ☐ **FEE** ☐

**6. State Oil & Gas Lease No.**

**7. Lease Name or Unit Agreement Name**

**BRAVO DOME CO2 GAS UNIT**

**8. Well No.**

**1932-041D**

**9. Pool name or Wildcat**

**BRAVO DOME CO2 GAS UNIT**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

**1. Type of Well**

**OIL WELL** ☐ **GAS WELL** ☐ **OTHER** **CO2**

**2. Name of Operator**

**AMOCO PRODUCTION COMPANY**

**3. Address of Operator**

**P.O. Box 303, AMISTAD, NEW MEXICO 88410**

**4. Well Location**

Unit Letter **D** : **660** Feet From The **North** Line and **660** Feet From The **West** Line  
Section **4** Township **19N** Range **32E** NMPM **Harding** County

**10. Elevation (Show whether DF, RKB, RT, GR, etc.)**

**4739 GR**

**11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

**PERFORM REMEDIAL WORK**

☐

**PLUG AND ABANDON**

☒

**TEMPORARILY ABANDON**

☐

**CHANGE PLANS**

☐

**PULL OR ALTER CASING**

☐

**OTHER:**

☐

**SUBSEQUENT REPORT OF:**

**REMEDIAL WORK**

☐

**ALTERING CASING**

☐

**COMMENCE DRILLING OPNS.**

☐

**PLUG AND ABANDONMENT**

☐

**CASING TEST AND CEMENT JOB**

☐

**OTHER:**

☐

**12. Describe Proposed or Completed Operations**  
SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

MIRU plugging unit. Kill well as necessary with fresh water. Nipple up BOP. Release Guiberson Uni 6 packer. Lay down production tubing, packer, tailpipe. Run and set with wireline a CIBP @ 2241'. Pressure test casing to 500 psi. Cap CIBP with 50 feet of cement. Run 2-3/8" tubing to just above cement cap on CIBP. Displace casing with 9.5# gelled brine water. Pull tubing to 1869'. Pump 10 sacks cement. Displace cement from tubing with 9.5# gelled brine water. Pull tubing to a depth plus or minus 30 feet. Fill top of casing with cement. Pull final joint of tubing from the well. Check surface casing for pressure. Cut off surface casing head. Weld steel plate on top of casing and install PXA marker. RD plugging unit. Remove well panels. Cut service unit anchors off 1' below ground level. Clean location.

*cement plug from 1870 to 1700'*

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Billy E. Prichard*

TITLE

Operations Specialist

DATE

10/27/97

TYPE OR PRINT NAME

B. E. Prichard

TELEPHONE NO.

(505) 374-3053

(This space for State Use)

APPROVED BY

*Ry E. Johnson*

TITLE

**DISTRICT SUPERVISOR**

DATE

11/4/97

CONDITIONS OF APPROVAL, IF ANY: