

State of New Mexico  
Energy, Minerals, and Natural Resources Department

Form C-103  
Revised 1-1-89

## DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

## DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

## DISTRICT III

000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

## WELL API NO.

30-021-20158

## 5. Indicate Type of Lease

STATE ☐FEE ☐

## 6. State Oil &amp; Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

## Type of Well

OIL  
WELL ☐GAS  
WELL ☐

OTHER

CO2

## Name of Operator

AMOCO PRODUCTION COMPANY

## 8. Well No.

2033-161G

## Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

## 9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

## Well Location

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
Section 16 Township 20N Range 33E NMPM Harding County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
5033 GR

## Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐WELL OR ALTER CASING ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

Describe Proposed or Completed Operations

(Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103.

10/20/99

MIRUSU, kill well with fresh water, NUBOP, release packer, lay down 3 1/2" production tubing and packer, run 2 3/8" workstring to 2,637 feet, spot 55 sacks of Class C cement, pull workstring uphole, WOC 4 hours, run workstring, tag cement at 2300 feet, pressure test casing to 500 psi, ok. Displace casing with fresh water and corrosion inhibited fluid, SDON.

10/21/99

Pull workstring to 2,073 feet, spot 20 sacks of cement from 2075' - 1959', pull workstring to 30 feet and spot 5 sacks of cement from 30' - 3', NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location.

2/8/00  
OK Ref

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

TITLE Field Foreman

DATE 10-25-99

PE OR PRINT NAME

Danny J. Holcomb

TELEPHONE NO. (505) 374-3010

This space for State Use

PROVED BY

TITLE

DISTRICT SUPERVISOR

DATE

2/10/00

CONDITIONS OF APPROVAL, IF ANY