

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Federal <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Bravo West
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Harding

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR. USE NOTIFICATION FOR PLUG BACK TO A DIFFERENT RESERVOIR FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Amerada Hess Corporation
3. Address of Operator Attn: Drilling Services. P. O. Box 2040, Tulsa Oklahoma, 74102
4. Location of Well UNIT LETTER <u>G</u> <u>1784.1</u> FEET FROM THE <u>North</u> LINE AND <u>2364.8'</u> FEET FROM <u>East</u> <u>33</u> <u>19N</u> <u>29E</u> THE <u>LINE</u> , SECTION <u>33</u> TOWNSHIP <u>19N</u> RANGE <u>29E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 5395' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See Attached!

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. R. Wilson J. R. Wilson TITLE Supervisor Drlg Admin Servs. DATE 3-13-84

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

BRAVO WEST #1

Moved in, rigged up CO<sub>2</sub> in Action Rig #16. Spudded 12-1/4" hole 3-26-84 (9:30 p.m.). Drld 0-820, ran 22 jt. 9-5/8" 36# K-55 8RS Smls R-3 "A" casing with guide shoe @819' insert float @783', 7 centralizers from 628' to 811'.

Dowell cemented w/470 sx Class H + 2% CaCl<sub>2</sub> (SW=16.4 ppg, Yield = 1.06 cuft/sx) Bumped plug w/1500 psi @1:45 p.m. 3-28-84, displaced w/56.5 bbls fresh water. Circ 145 sx cement to pits. 8-3/4 hrs WOC, cut off 9-5/8" casing and weld on 9-5/8" x 11" 3000# CIW csg head. NU and test blind rams to 1500 psi. TIH and tagged cmt @779'. Drld insert float @25' cmt test rams to 1500 psi, O.K. Finished drilling cement and shoe, drld to 2990', Circ and cond hole for logs, Schlumberger ran DLL-Micro 2980'-816', CNL-LDT 2980'-816' RD loggers, Circ and cond hole for 7" csg. Ran 77 jt 20# K-55 8RS R-3 "A" casing w/FS @ 2990' and float collar @2952', 6 centralizers 2984-2796. RU Dowell and circ casing. Dowell pumped 10 bbl fresh water followed by 1200 sx Class H + 2% Gel + 5#/sx Kolite + 5% KCL + .4% D-60. Bumped plug w/1000 psi @7:15 am 4-3-84. Displaced w/117 bbl fresh water. Circ 175 sx cmt to surface. Floats held, O.K. Good returns thru out job (SW = 14.5# Yield = 1.45#) set 50,000# wt on 7" csg slips, cut off 7" csg and weld on cap Finished ND BOP. Rig released @10 a.m. 4-3-84, well turned to Production Department.